

6TLOBFKDCF  
20-00904

WISCONSIN MOTOR VEHICLE  
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT  
1300 LANGE COURT  
BARABOO, WI 53913  
(608) 356-4895

6TLOBFKDCF

Document Number Override		Primary Crash Document #		Agency Crash Number <b>20-00904</b>		Investigating Officer/Deputy <b>DEPUTY H. VOLZ</b>		
Crash Date <b>01/24/2020</b>		Crash Time <b>12:20 PM</b>		Date Arrived <b>01/24/2020</b>		Time Arrived <b>12:30 PM</b>		
Date Notified <b>01/24/2020</b>		Time Notified <b>12:30 PM</b>		Total Units <b>01</b>		Total Injured <b>00</b>	Total Killed <b>00</b>	
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure	<input type="checkbox"/> Work Zone		<input type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold		
<input type="checkbox"/> Government Property		<input type="checkbox"/> Active School Zone		School Bus Related <b>NO</b>		Tags		
<input type="checkbox"/> Reportable		Crash Type <b>DT4000 (STANDARD CRASH)</b>				<input type="checkbox"/> Amended		<input type="checkbox"/> Secondary Crash

**Description**

Diagram	Reconstruction By
	Photos By
	Additional Information

Non-Reportable Slide Off  
No Damage  
Pull out by Mike's Towing

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

UNIT 1 WAS TRAVELING NB ON S SHORE ROAD AND ATTEMPTED A Y TURN IN THE ROAD WAY. UNIT 1 BECAME STUCK IN THE SNOW IN THE DITCH ON THE WEST SIDE OF THE ROAD WAY. MIKES TOWING RESPONDED AND PULLED OUT THE VEHICLE. NO DAMAGE.

6TL0BFKDCF  
20-00904

WISCONSIN MOTOR VEHICLE  
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT  
1300 LANGE COURT  
BARABOO, WI 53913  
(608) 356-4895

Location

ON S SHORE RD 421 FT N OF SKIHI RD IN THE TOWN OF BARABOO IN SAUK COUNTY	Latitude <b>43.421054698</b>	Longitude <b>-89.747793702</b>
	X Coordinate <b>277562.40625</b>	Y Coordinate <b>4811241.5</b>
	Structure Type	

Crash Scene

First Harmful Event <b>DITCH</b>	First Harmful Event Location <b>ROADSIDE</b>	
Manner of Collision <b>00 - NO COLLISION W/VEHICLE IN TRANSPORT</b>	Light Condition <b>DAYLIGHT</b>	
Road Surface Condition(s) <b>WET, SNOW, SLUSH, ICE</b>	Roadway Factor(s)  <b>BACKUP DUE TO PRIOR CRASH</b>	
Environment Factor(s) <b>WEATHER CONDITIONS</b>		
Weather Condition(s) <b>CLOUDY, SNOW</b>		
Animal Type	Relation To Trafficway <b>TRAFFICWAY - NOT ON ROAD</b>	
Crash Classification - Location <b>PUBLIC PROPERTY</b>	Crash Classification - Jurisdiction <b>NO SPECIAL JURISDICTION</b>	
Tribal Land	Access Control <b>NO CONTROL</b>	Special Study
Within Interchange Area <b>NO</b>	Junction Location <b>NON-JUNCTION</b>	Intersection Type <b>NOT AN INTERSECTION</b>

Unit Summary

<b>UNIT</b>	Unit Status <b>IN TRANSIT</b>	Vehicle Operating As Classification <b>D CLASS</b>		Unit Type <b>AUTOMOBILE</b>	
	Vehicle Type <b>(SPORT) UTILITY VEHICLE</b>	Operating As Endorsements			
	Total Occs <b>1</b>	Train/Bus # Recorded	Total # Citations Issued <b>0</b>	Total Trailers <b>0</b>	Total HazMat Types <b>0</b>
	Insurance? <b>NOT APPLICABLE</b>	Direction Of Travel <b>SOUTHBOUND</b>	<input type="checkbox"/> <b>Pre CrashTire Mark</b>	Speed Limit <b>45</b>	Total Lanes <b>2</b>
	Most Harmful Event: Collision With <b>DITCH</b>	Special Function <b>NO SPECIAL FUNCTION</b>		Emergency Motor Vehicle Use <b>NOT APPLICABLE</b>	
	Traffic Way <b>TWO-WAY, NOT DIVIDED</b>	Traffic Control <b>NO CONTROL</b>		Traffic Control Inoperative/Missing <b>NO</b>	
	Surface Type <b>BLACKTOP (BITUMINOUS)</b>	Road Curvature <b>STRAIGHT</b>		Road Grade <b>LEVEL</b>	
	Truck Bus or HazMat <b>NO</b>				

<b>UNIT</b>	<b>Vehicle</b>				
	<b>01</b>	License Plate Number <b>930YXX</b>	Plate Type <b>AUT - AUTOMOBILE</b>	St <b>WI</b>	Country of Issuance <b>UNITED STATES</b>
		Vehicle Identification Number <b>JTJHY7AX1E4139650</b>	Make <b>LEXUS</b>	Year <b>2014</b>	Model <b>LX 570</b>
	<b>VEHICLE</b>	Color <b>GRY - GRAY</b>	Body Style <b>UT - SPORT UTILITY VEHICLE</b>		Bus Use
		Initial Contact Point <b>01 - RIGHT FRONT CORNER</b>	Vehicle Damage		
Extent Of Damage <b>NO DAMAGE</b>		<b>00 - NO DAMAGE</b>			

WISCONSIN MOTOR VEHICLE CRASH REPORT

UNIT VEHICLE 01 Towed Due To Damage TOWED BUT NOT DUE TO DISABLING DAMAG Vehicle Removed By MIKES TOWING
UNIT INDIVIDUAL 01 Driver TAMRA WATERMAN Citations Issued 0 Sex FEMALE
Safety Equipment On Duty Crash Safety Equipment SHOULDER & LAP BELT
Injury Injury Severity NO APPARENT INJURY Airbag NON DEPLOYED
Distracted By Distracted By Source NOT APPLICABLE (NOT DISTRACTED)
Non Motorist Striking Unit # Location

WISCONSIN MOTOR VEHICLE  
CRASH REPORT

UNIT	INDIVIDUAL			
	Prior Action			
	Action			
	Action Other			To/From School
	<b>Drug &amp; Alcohol</b>		Suspected Alcohol Use <b>NO</b>	Suspected Drug Use <b>NO</b>
	Alcohol Test Given <b>TEST NOT GIVEN</b>		Alcohol Test Type	Alcohol Test Results
	Drug Test Given <b>TEST NOT GIVEN</b>		Drug Test Type	Drug Test Results
	Drug Type			
	Individual Condition <b>APPEARED NORMAL</b>			
	01	001		