

6TLOBZLVN4

20-00843

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

Location

ON STH60 EB 0.26 MI E OF BADGER RD IN THE TOWN OF TROY IN SAUK COUNTY	Latitude 43.198498899	Longitude -89.928044905
	X Coordinate 262102.921875	Y Coordinate 4787021
	Structure Type NO STRUCTURE	

Crash Scene

First Harmful Event DITCH	First Harmful Event Location ROADSIDE	
Manner of Collision 00 - NO COLLISION W/VEHICLE IN TRANSPORT	Light Condition DAYLIGHT	
Road Surface Condition(s) SNOW	Roadway Factor(s) ROAD SURFACE CONDITION (WET, ICY, SNOW, SLUSH, ETC)	
Environment Factor(s) WEATHER CONDITIONS		
Weather Condition(s) SNOW		
Animal Type	Relation To Trafficway TRAFFICWAY - NOT ON ROAD	
Crash Classification - Location PUBLIC PROPERTY	Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land	Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location NON-JUNCTION	Intersection Type NOT AN INTERSECTION

Unit Summary

UNIT	Unit Status IN TRANSIT	Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE	
	Vehicle Type PASSENGER CAR	Operating As Endorsements			
	Total Occs 01	Train/Bus # Recorded	Total # Citations Issued 00	Total Trailers 0	Total HazMat Types 0
	Insurance? YES	Direction Of Travel EASTBOUND	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit 55	Total Lanes 02
	Most Harmful Event: Collision With DITCH	Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way TWO-WAY, NOT DIVIDED	Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)	Road Curvature CURVE LEFT		Road Grade LEVEL	
	Truck Bus or HazMat NO				

Vehicle

UNIT	VEHICLE	01	License Plate Number AFW6213	Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES	
			Vehicle Identification Number 1G2ZG57B994148326	Make PONTIAC	Year 2009	Model G6	
			Color WHI - WHITE	Body Style 4D - 4DR		Bus Use	
			Initial Contact Point 12 - FRONT	Vehicle Damage			
			Extent Of Damage MINOR DAMAGE	11 - LEFT FRONT CORNER, 12 - FRONT			

6TLOBZLVN4

20-00843

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

UNIT	Towed Due To Damage NOT TOWED		Vehicle Removed By OPERATOR	
	What Driver Was Doing NEGOTIATING CURVE		Vehicle Factors	
	Driver Prior Action Other		NOT APPLICABLE	
	Driver Actions FAILURE TO CONTROL, RAN OFF ROADWAY			
01	Owner Name KODI M KNOBLE		Owner Address 900 W SIDE DR RICHLAND CENTER, WI 53581 , US	
	Sequence Of Events			
01	Event DITCH			
	Event			
	Event			
	Event			
02	Event			
	Event			
	Event			
	Event			
03	Event			
	Event			
	Event			
	Event			
04	Event			
	Event			
	Event			
	Event			
UNIT	Policy Holder			
	Insurance Company UNKNOWN		Name	
	Individual			
	Driver KODI M KNOBLE		Citations Issued 00	Sex MALE
Date of Birth		Race WHITE		
Address 900 W SIDE DR RICHLAND CENTER, WI 53581 , US		Driver License Number STATE: WISCONSIN COUNTRY: UNITED STATES		
UNIT	Safety Equipment		On Duty Crash	
	Row 01 - FRONT ROW		Seat Position 07 - LEFT	Safety Equipment SHOULDER & LAP BELT
	Helmet Use		Helmet Compliance	
	Eye Protection		Tint Compliance	
01	Injury		Injury Severity NO APPARENT INJURY	Airbag NON DEPLOYED
	Ejected NOT EJECTED	Ejection Path NOT EJECTED/NOT APPLICABLE		Trapped/Extricated NOT TRAPPED
	Medical Transport NOT TRANSPORTED		EMS Agency Identifier	EMS Run #
	Hospital		Date of Death	Time of Death
001	Distracted By		Distracted By Source NOT APPLICABLE (NOT DISTRACTED)	
	Distracted By Action NOT DISTRACTED			

6TL0BZLVN4

20-00843

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

UNIT	Non Motorist	Striking Unit #		Location			
		Prior Action					
	INDIVIDUAL	Action					
		Action Other				To/From School	
		Drug & Alcohol		Suspected Alcohol Use NO	Suspected Drug Use NO		
	01	001	Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type		Alcohol Test Results
			Drug Test Given TEST NOT GIVEN		Drug Test Type	Drug Test Results	
			Drug Type				
			Individual Condition APPEARED NORMAL				