6TL09QKRF9

20-00715

WISCONSIN MOTOR VEHICLE CRASH REPORT

	Document Number Override	Primary Crash Doc	ument #	Agency 20-007	Crash Number 15	Investigating DEPUTY S	Officer/Deputy . STACEY	,	
אר	Crash Date 01/18/2020	Crash Time 09:08 PM		Date Arr 01/18/2		Time Arrived	Time Arrived 09:08 PM		
y i	Date Notified	Time Notified		Total Ur	nits	Total Injured	Total Kill	ed	
2	01/18/2020	09:08 PM		01		00	00		
0 I LUYUNAAAA	On Emergency	t and Run	Lane Clos	ure	Work Zone	Trailer	or Towed	Reporting Threshold	
0	Government Property	Active Scho	ol Zone	School I NO	Bus Related	Tags			
	Reportable	Crash Type DT4000 (STAND	ARD CRASH	ł)		Amend	ed	Secondary Crash	
[Description								
	Diagram						Reconstructio	n By	
				The second second			Photos By		
				and and	And the				
				ないよう					
	A	n hall and			and the second second		Additional Info	ormation	
	Ceda					5	NONE		
	Freedom Rd					M G			
			1.1						
			Sale a		And and	5			
	the state of the s	1 ⁶ 60			I Threese				
		freed.	IN Rel	all and					
		and the second		1000	記念に変更にな				
		Line and the second	P		No. of the second se				
		e e	1 min	F	SECON Rd				
		C C		Edia.	d'om p				
	the state of the			橋	ald.				
		D STATE			All and a second				
	STATISTICS IN THE REAL PROPERTY OF	Se las	a de la caracita de l		A Company				
		S.							
		All the		A STA	· · · · · · · · · · · · · · · · · · ·				
				N	OT TO SCALE				
	✓ I, a sworn law enforceme	ent officer, agree t	hat I have no	ot added	any CJIS data in th	is report.			
╞						-			
	ON 01/18/20, I WAS ADVISED OF A				AR FREEDOM ROAD. U				
	AND APPEARED TO ATTEMPT TO	MAKE A RIGHT HAND	D TURN ONTO	SEELEY L	EAR FREEDOM ROAD. L ANE AND SLID INTO TH	E DITCH. THERE	WAS NO DRIVE	ER AROUND. AFTER	
		MAKE A RIGHT HANI D OWNER AND ATTE	D TURN ONTO	SEELEY L ACT WITH	AR FREEDOM ROAD. L ANE AND SLID INTO TH A POSSIBLE DRIVER M	E DITCH. THERE	WAS NO DRIVE	ER AROUND. AFTER	

20-00715

WISCONSIN MOTOR VEHICLE CRASH REPORT

	_00	ation							_	
•		ERSECTION	Latitude			Longitude				
		SEELEY LN			43.441008923			-89.864628953		
		FREEDOM RD 'HE TOWN OF FREED	OM		X Coordinate			Y Coordinate		
						268180.25			4813776.5	
				Structure Type						
						NO STRUCTURE				
(Cra	sh Scene								
1		Harmful Event				First Harm	ful Event Lo	ocation		
	DIT			ON ROA		Joanon				
		ner of Collision			Light Condition					
			HICLE IN TRANSPORT			DARK/UNLIT				
		d Surface Condition(s)					Factor(s)			
		T, SNOW, ICE				Roddwdy	1 40101(3)			
		ronment Factor(s)								
		ATHER CONDITIONS				ROAD S ETC)	URFACE	CONDITION	(WET, ICY, SNOW, SL	USH,
	Wea	ther Condition(s)				,				
		DUDY								
		nal Type					Relation To Trafficway			
					TRAFFICWAY - ON ROAD					
	Cras	h Classification - Location			Crash Classification - Jurisdiction					
	PUE	BLIC PROPERTY					NO SPECIAL JURISDICTION Access Control Special Study			
	Triba	al Land								
						NO CONTROL				
		in Interchange Area	Junction Location		Intersectio					
	NO		INTERSECTION		T-INTER	SECTION				
		t Summary 🛛 💻								
	Unit Status Vehicle Operating As Cl									
	Unit	Status			•	lassification		Unit Type		
	UN	KNOWN		Vehicle Ope D CLASS	•	lassification		AUTOMOE		
1	UNP Vehi	KNOWN cle Type			•	lassification		AUTOMOE	BILE s Endorsements	
01	UNI Vehi (SP	KNOWN cle Type ORT) UTILITY VEHICL		D CLASS				AUTOMOE Operating As	s Endorsements	
01	UNI Vehi (SP	KNOWN cle Type	E Train/Bus # Recorded	D CLASS	•		Total Trail	AUTOMOE Operating As	s Endorsements Total HazMat Types	
01	UNP Vehi (SP) Tota	KNOWN cle Type ORT) UTILITY VEHICL I Occs	Train/Bus # Recorded	D CLASS			Total Trail 0	AUTOMOE Operating As	s Endorsements Total HazMat Types 0	
01	UNP Vehi (SP Tota 1 Insu	KNOWN cle Type ORT) UTILITY VEHICL I Occs rance?	Train/Bus # Recorded Direction Of Travel	D CLASS	tions Issued		Total Trail 0 Speed Lin	AUTOMOE Operating As	s Endorsements Total HazMat Types 0 Total Lanes	
	UNP Vehi (SP Tota 1 Insur YES	KNOWN cle Type ORT) UTILITY VEHICL I Occs rance? S	Train/Bus # Recorded Direction Of Travel SOUTHBOUND	D CLASS	CrashTire Mark		Total Trail 0	AUTOMOE Operating As ers nit	s Endorsements Total HazMat Types 0 Total Lanes 2	
UNIT 01	UNP Vehi (SP Tota 1 Insur YES	KNOWN cle Type ORT) UTILITY VEHICL I Occs rance? S t Harmful Event: Collision N	Train/Bus # Recorded Direction Of Travel SOUTHBOUND	D CLASS	tions Issued CrashTire Mark notion		Total Trail 0 Speed Lin	AUTOMOE Operating As ers nit Emergency	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use	
	UNP Vehi (SP Tota 1 Insur YES Most DIT	KNOWN cle Type ORT) UTILITY VEHICL I Occs rance? S t Harmful Event: Collision N CH	Train/Bus # Recorded Direction Of Travel SOUTHBOUND	D CLASS	tions Issued CrashTire Mark Inction CIAL FUNC		Total Trail 0 Speed Lin	AUTOMOE Operating As ers hit Emergency NOT APPL	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE	
	UNP Vehi (SP Tota 1 Insur YES Most DIT Traff	KNOWN cle Type ORT) UTILITY VEHICL I Occs rance? S t Harmful Event: Collision N CH ic Way	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With	D CLASS	CrashTire Mark Inction CIAL FUNC		Total Trail 0 Speed Lin	AUTOMOE Operating As ers nit Emergency NOT APPL Traffic Contr	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use	
	UNH Vehi (SP) Tota 1 Insur YES Most DIT(Traff	KNOWN cle Type ORT) UTILITY VEHICL I Occs rance? S t Harmful Event: Collision V CH fic Way D-WAY, NOT DIVIDED	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With	D CLASS	CrashTire Mark notion CIAL FUNC trol		Total Trail 0 Speed Lin	AUTOMOE Operating As ers nit Emergency NOT APPL Traffic Contr NO	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE ol Inoperative/Missing	
	UNH Vehi (SP) Tota 1 Insur YES Most DIT(Traff TW(Surfa	KNOWN cle Type ORT) UTILITY VEHICL I Occs rance? S t Harmful Event: Collision N CH iic Way D-WAY, NOT DIVIDED ace Type	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With	D CLASS	tions Issued CrashTire Mark notion CIAL FUNC trol IROL ature		Total Trail 0 Speed Lin	AUTOMOE Operating As ers nit Emergency NOT APPL Traffic Contr NO Road Grade	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE ol Inoperative/Missing	
	UNH Vehi (SP) Tota 1 Insur YES Most DIT Traff TW(Surfa BLA	KNOWN cle Type ORT) UTILITY VEHICL I Occs rance? S t Harmful Event: Collision V CH fic Way D-WAY, NOT DIVIDED	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With	D CLASS	tions Issued CrashTire Mark notion CIAL FUNC trol IROL ature		Total Trail 0 Speed Lin	AUTOMOE Operating As ers nit Emergency NOT APPL Traffic Contr NO	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE ol Inoperative/Missing	
	UNH Vehi (SP) Tota 1 Insur YES Most DIT Traff TW(Surfa BLA	KNOWN cle Type ORT) UTILITY VEHICL I Occs rance? S t Harmful Event: Collision N CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With	D CLASS	tions Issued CrashTire Mark notion CIAL FUNC trol IROL ature		Total Trail 0 Speed Lin	AUTOMOE Operating As ers nit Emergency NOT APPL Traffic Contr NO Road Grade	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE ol Inoperative/Missing	
	UNI Vehi (SPu Tota 1 Insuu YES Most DIT Traff TW(Surfa BLA Truc NO	KNOWN cle Type ORT) UTILITY VEHICL I Occs rance? S t Harmful Event: Collision N CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With	D CLASS	tions Issued CrashTire Mark notion CIAL FUNC trol IROL ature		Total Trail 0 Speed Lin	AUTOMOE Operating As ers nit Emergency NOT APPL Traffic Contr NO Road Grade LEVEL	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE fol Inoperative/Missing	
	UNI Vehi (SPu Tota 1 Insuu YES Most DIT Traff TW(Surfa BLA Truc NO	KNOWN cle Type ORT) UTILITY VEHICL I Occs I Occs t Harmful Event: Collision N CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With	D CLASS	CrashTire Mark notion CIAL FUNC trol TROL ature	TION	Total Trail 0 Speed Lin 45 St	AUTOMOE Operating As ers nit Emergency NOT APPL Traffic Contr NO Road Grade LEVEL	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE Tol Inoperative/Missing	
	UNI Vehi (SPu Tota 1 Insuu YES Most DIT Traff TW(Surfa BLA Truc NO	KNOWN cle Type ORT) UTILITY VEHICL I Occs I Occs t Harmful Event: Collision N CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU: k Bus or HazMat Vehicle License Plate Number 654ZXN	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With S)	D CLASS	CrashTire Mark notion CIAL FUNC trol TROL ature	TION	Total Trail 0 Speed Lin 45 St WI	AUTOMOE Operating As ers nit Emergency I NOT APPL Traffic Contr NO Road Grade LEVEL	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE Tol Inoperative/Missing suance	
INI	UNH Vehi (SPU Tota 1 Insuu YES Most DIT(Traff TW(Surfa BLA Truc NO	KNOWN cle Type ORT) UTILITY VEHICL I Occs I occs t Harmful Event: Collision N CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU: k Bus or HazMat Vehicle License Plate Number 654ZXN Vehicle Identification Nur	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With S) S)	D CLASS	CrashTire Mark notion CIAL FUNC trol TROL ature	TION	Total Trail 0 Speed Lin 45 St WI Year	AUTOMOE Operating As ers nit Emergency I NOT APPL Traffic Contr NO Road Grade LEVEL	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE fol Inoperative/Missing suance TATES	
INI	UNI Vehi (SPu Tota 1 Insuu YES Most DIT Traff TW(Surfa BLA Truc NO	KNOWN cle Type ORT) UTILITY VEHICL I Occs rance? S t Harmful Event: Collision N CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number 654ZXN Vehicle Identification Nur 1FMCU9C70AKC901	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With S) S)	D CLASS	tions Issued CrashTire Mark Inction CIAL FUNC TROL ature IT	TION	Total Trail 0 Speed Lin 45 St WI	AUTOMOE Operating As operating As ers it Emergency I NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss UNITED ST Model ESCAPE X	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE fol Inoperative/Missing suance TATES	
UNIT	UNH Vehi (SPU Tota 1 Insuu YES Most DIT Traff TWC Surfa BLA Truc NO	KNOWN cle Type ORT) UTILITY VEHICL I Occs rance? S t Harmful Event: Collision N CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number 654ZXN Vehicle Identification Nur 1FMCU9C70AKC901 Color	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With S) S)	D CLASS	tions Issued CrashTire Mark Inction CIAL FUNC TROL ature IT	TION	Total Trail 0 Speed Lin 45 St WI Year 2010	AUTOMOE Operating As ers nit Emergency I NOT APPL Traffic Contr NO Road Grade LEVEL	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE fol Inoperative/Missing suance TATES	
	UNH Vehi (SP) Tota 1 Insur YES DITO Traff TWO Surfa BLA Truc NO	KNOWN cle Type ORT) UTILITY VEHICL I Occs rance? S t Harmful Event: Collision N CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number 654ZXN Vehicle Identification Nur 1FMCU9C70AKC901 Color WHI - WHITE	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With S) S)	D CLASS	CrashTire Mark Inction CIAL FUNC TROL ature IT JTOMOBIL	TION	Total Trail 0 Speed Lin 45 St WI Year 2010	AUTOMOE Operating As operating As ers it Emergency I NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss UNITED ST Model ESCAPE X	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE fol Inoperative/Missing suance TATES	
01 UNIT	UNH Vehi (SP Tota 1 Insur YES DITO Traff TWO Surfa BLA Truc NO	KNOWN cle Type ORT) UTILITY VEHICL I Occs rance? Tharmful Event: Collision N CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number 654ZXN Vehicle Identification Nur 1FMCU9C70AKC901 Color WHI - WHITE Initial Contact Point	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With S) Mber 60	D CLASS	CrashTire Mark Inction CIAL FUNC TROL ature IT JTOMOBIL	TION	Total Trail 0 Speed Lin 45 St WI Year 2010	AUTOMOE Operating As operating As ers it Emergency I NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss UNITED ST Model ESCAPE X	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE fol Inoperative/Missing suance TATES	
01 UNIT	UNH Vehi (SP Tota 1 Insur YES DITO Traff TWO Surfa BLA Truc NO	KNOWN cle Type ORT) UTILITY VEHICL I Occs rance? S t Harmful Event: Collision N CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle Mentification Nur 1FMCU9C70AKC901 Color WHI - WHITE Initial Contact Point 00 - NON-COLLISION	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With S) Mber 60	D CLASS	tions Issued CrashTire Mark Inction CIAL FUNC TROL ature IT DTOMOBIL CONTINUES DRT UTILIT amage	TION	Total Trail 0 Speed Lin 45 St WI Year 2010	AUTOMOE Operating As operating As ers it Emergency I NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss UNITED ST Model ESCAPE X	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE fol Inoperative/Missing suance TATES	
	UNH Vehi (SP) Tota 1 Insur YES DITO Traff TWO Surfa BLA Truc NO	KNOWN cle Type ORT) UTILITY VEHICL I Occs rance? Tharmful Event: Collision N CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number 654ZXN Vehicle Identification Nur 1FMCU9C70AKC901 Color WHI - WHITE Initial Contact Point	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With S) Mber 60	D CLASS	CrashTire Mark Inction CIAL FUNC TROL ature IT JTOMOBIL	TION	Total Trail 0 Speed Lin 45 St WI Year 2010	AUTOMOE Operating As operating As ers it Emergency I NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss UNITED ST Model ESCAPE X	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE fol Inoperative/Missing suance TATES	

6TL09QKRF9

20-00715

WISCONSIN MOTOR VEHICLE CRASH REPORT

		Towed Due To Damage		Vo	hicle Removed By					
		NOT TOWED			WNER					
		What Driver Was Doing			hicle Factors					
				ve	TICLE FACIOIS					
					OT APPLICABLE					
		Driver Prior Action Other								
		Driver Actions								
	Щ	UNKNOWN								
UNIT	VEHICLE									
5	E.									
	ž									
		Owner Name			Owner Address					
2	2	RUBEN T CAVAZOS (608) 402-5405			402 6TH STREET BARABOO, WI 53913 ,US					
0	0	(000) 402-3403			BAI(ABOO; WI 33313 , 03					
	;	Sequence Of Events								
	6	Event RIGHT TURN								
	02	Event DITCH								
	•									
	03	Event								
	04	Event								
E	I	Policy Holder								
UNIT		Insurance Company			Individual					
		PROGRESSIVE-CLASSIC-INS-CO			RUBEN CAVAZOS					
	l	Individual								
		Driver			Citations Issued	Sex				
	_				0					
	A				Date of Birth	Race				
E	INDIVIDUAL									
UNIT	Σ	Address			Driver License Number					
	P									
	=	, ,								
	Sat	f ety Equipment	/ Crash		Safety Equipment					
	Sai	ety Equipment								
		Row	Seat Position		RESTRAINT USE UNKNOWN					
		01 - FRONT ROW	07 - LEFT							
		Helmet Use		Helmet Compliance						
		Eye Protection		Tint Compliance						
~	Ξ	Injury Severity			Airbag					
5	001				NON DEPLOYED					
		Ejected	Ejection Path			Trapped/Extricated				
		NOT EJECTED NOT EJECTED/NOT A				NOT TRAPPED				
		Medical Transport			EMS Agency Identifier	EMS Run #				
	NOT TRANSPORTED									
		Hospital			Date of Death	Time of Death				
		Distant	ad Du Cauraa							
		Distracted By	ed By Source							
		Distracted By Action								

6TL09QKRF9 20-00715

WISCONSIN MOTOR VEHICLE CRASH REPORT

		Non Motorist	Striking Unit #	Location				
		Prior Action						
UNIT	INDIVIDUAL	Action						
		Action Other						To/From School
	L	Drug & Alcohol	Suspected Alcohol U NO	Jse	Suspected Drug Use			
		Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type			Alcohol Test Results	
		Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug Test Results	ł	
6	001	Drug Type		1		L		
		Individual Condition						
		NOT OBSERVED						