WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT **BARABOO, WI 53913** (608) 356-4895

	Document Number Override		Primary Crash Document #		Agency Crash Number 20-03190		0 0	Investigating Officer/Deputy DEPUTY L. GJORGJIEV		
4 大	Crash Date 03/28/2020		Crash Time 99:99		Date Arrived 03/29/2020		Time Arrived 04:26 AM			
RB	Date Notified 03/29/2020		Time Notified 04:00 AM		Total Units 01		Total Injured 00	Total Killed 00		
097	On Emergency	Hit	and Run	Lane Closu	ire	☐ Work Zone	Trailer or 1	Towed		Reporting Threshold
eTL	Government Property		Active School Zone		School Bus Related NO		Tags			
	Reportable		Crash Type DT4000 (STANDARD CRASH)		Amended	Amended		Secondary Crash
	Description									

Diagram oak hill rd not to scale E9489 Oak Hill rd

Reconstruction By

Photos By

Additional Information NONE

↓ I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

UNIT 1 WAS TRAVELING WEST ON OAK HILL RD NEAR E9489. UNIT 1 DID A U-TURN USING THE DRIVEWAY OF THE HOUSE AT E9489. THE DRIVER OF UNIT 1 SAID THERE WERE DEER ON THE ROAD WHEN SHE DID THE U-TURN WHICH IS WHY SHE WENT A LITTLE TOO FAR INTO THE DRIVEWAY. UNIT 1 THEN DROVE THROUGH THE GRASS AND GOT STUCK IN THE MUD PRIOR TO REENTERING THE ROADWAY. THERE WAS NO DAMAGE TO THE VEHICLE. THE PROPERTY OWNER SAID HE WAS NOT WORRIED ABOUT THE DAMAGE TO THE GRASS. VEHICLE WAS REMOVED THE FOLLOWING DAY BY THE OWNER.

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 03/28/2020

Crash Time 99:99

	_oc	ation								
F	ON	E9489 OAK HILL RD			Latitude			Longitude		
	0.61	MIW		43.6357	43.635762629		-89.849278982			
		F LAGE RD				X Coordinate		Y Coordinate		
	(HO	HOUSE/BUILDING E9489)				270164.09375		4835364.5		
	INI T	HE TOWN OF DELLC	NIA.							
		SAUK COUNTY	MA		Structure Type HOUSE/BUILDING					
L					1.0002					
(sh Scene								
Ī	First	Harmful Event			nful Event L					
	DIT	СН		SHOUL	DER RIGH	T				
Ī	Man	ner of Collision		Light Con	Light Condition					
	00 -	NO COLLISION W/VE	EHICLE IN TRANSPORT		DARK/L	DARK/UNLIT				
Ī	Road	d Surface Condition(s)			Roadway	Factor(s)				
	WET									
	Envi	ronment Factor(s)								
	ANI	MAL (S) IN ROADWA	Υ		NONE					
ŀ	Wea	ther Condition(s)								
	CLC	DUDY								
-	Anim	nal Type			Relation ⁻	To Trafficwa	y			
	DEE	ER			TRAFFI	CWAY - O	N ROAD			
ľ	Cras	sh Classification - Location	1		Crash Cla	Crash Classification - Jurisdiction				
	PRI	VATE PROPERTY			PRIVATE PROPERTY					
ŀ	Tribal Land				Access C	Access Control Special Study				
						NO CONTROL				
					Intersection Type	•				
	NO		NON-JUNCTION		NOT AN INTERSE	AN INTERSECTION				
Į	Jni	t Summary 🗨								
	Unit	Status		Vehicle Ope	erating As Classification	**				
				AUTOMOBILE						
	IN T	RANSIT		D CLASS			AUTOMOE	BILE		
_	Vehi	cle Type		D CLASS				SILE s Endorsements		
01	Vehi			D CLASS			Operating As	s Endorsements		
LO	Vehi (SP	cle Type	LE Train/Bus # Recorded		tions Issued	Total Trail	Operating As			
10	Vehi (SP	cle Type ORT) UTILITY VEHIC			tions Issued	Total Trail	Operating As	s Endorsements		
01	Vehi (SP) Tota 2	cle Type ORT) UTILITY VEHIC		Total # Cita	tions Issued CrashTire		Operating As	s Endorsements Total HazMat Types		
-	Vehi (SP) Tota 2	cle Type ORT) UTILITY VEHIC	Train/Bus # Recorded	Total # Cita		0	Operating As	s Endorsements Total HazMat Types 0		
-	Vehi (SP) Tota 2 Insui NO	cle Type ORT) UTILITY VEHIC	Train/Bus # Recorded Direction Of Travel WESTBOUND	Total # Cita 0 Pre Special Fun	CrashTire Mark action	0 Speed Lin	Operating Asers	Total HazMat Types O Total Lanes 2 Motor Vehicle Use		
-	Vehi (SP) Tota 2 Insui NO	cle Type ORT) UTILITY VEHIC I Occs rance? t Harmful Event: Collision	Train/Bus # Recorded Direction Of Travel WESTBOUND	Total # Cita 0 Pre Special Fun	CrashTire Mark	0 Speed Lin	Operating Asers ers nit Emergency NOT APPL	Total HazMat Types O Total Lanes 2 Motor Vehicle Use		
-	Vehi (SP) Tota 2 Insui NO Most DIT(cle Type ORT) UTILITY VEHIC! I Occs rance? t Harmful Event: Collision CH	Train/Bus # Recorded Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont	CrashTire Mark action IIAL FUNCTION rol	0 Speed Lin	Operating Asers ers nit Emergency NOT APPL	Total HazMat Types O Total Lanes 2 Motor Vehicle Use		
-	Vehi (SP) Tota 2 Insui NO Most DIT(Traff	cle Type ORT) UTILITY VEHICI I Occs rance? t Harmful Event: Collision CH fic Way D-WAY, NOT DIVIDED	Train/Bus # Recorded Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fun	CrashTire Mark action IIAL FUNCTION rol	0 Speed Lin	Operating Asers ers nit Emergency NOT APPL	Total HazMat Types O Total Lanes 2 Motor Vehicle Use		
-	Vehi (SP) Tota 2 Insui NO Most DIT(Traff	cle Type ORT) UTILITY VEHIC! I Occs rance? t Harmful Event: Collision CH	Train/Bus # Recorded Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont	CrashTire Mark liction IIAL FUNCTION rol	0 Speed Lin	ers iit Emergency NOT APPL Traffic Contr	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing		
-	Vehi (SP) Tota 2 Insui NO Most DIT(Traff TW(Surfa	cle Type ORT) UTILITY VEHICI I Occs rance? t Harmful Event: Collision CH fic Way D-WAY, NOT DIVIDED	Train/Bus # Recorded Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont	CrashTire Mark Introduction IAL FUNCTION INTRODUCTION INTRODUCTION INTRODUCTION	0 Speed Lin	ers iit Emergency NOT APPL Traffic Contr	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing		
-	Vehic	cle Type ORT) UTILITY VEHICI I Occs rance? t Harmful Event: Collision CH iic Way D-WAY, NOT DIVIDED ace Type	Train/Bus # Recorded Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva	CrashTire Mark Introduction IAL FUNCTION INTRODUCTION INTRODUCTION INTRODUCTION	0 Speed Lin	ers Emergency NOT APPL Traffic Contr NO Road Grade	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing		
-	Vehi (SP) Tota 2 Insur NO Most DITC Trafff TWC Surfat BLA Truc NO	cle Type ORT) UTILITY VEHICI I Occs rance? It Harmful Event: Collision CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU	Train/Bus # Recorded Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva	CrashTire Mark Introduction IAL FUNCTION INTRODUCTION INTRODUCTION INTRODUCTION	0 Speed Lin	ers Emergency NOT APPL Traffic Contr NO Road Grade	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing		
-	Vehi (SP) Tota 2 Insur NO Most DITC Trafff TWC Surfat BLA Truc NO	cle Type ORT) UTILITY VEHICI I Occs rance? t Harmful Event: Collision CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU	Train/Bus # Recorded Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH	CrashTire Mark Iction IAL FUNCTION rol ROL ature T	0 Speed Lin	ers iit Emergency NOT APPL Traffic Contr NO Road Grade LEVEL	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing		
-	Vehi (SP) Tota 2 Insur NO Most DITC Trafff TWC Surfat BLA Truc NO	cle Type ORT) UTILITY VEHICI I Occs rance? It Harmful Event: Collision CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU ik Bus or HazMat	Train/Bus # Recorded Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH	CrashTire Mark Iction IAL FUNCTION rol ROL ature T	Speed Lin 35	ers Emergency NOT APPL Traffic Contr NO Road Grade	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing		
	Vehi (SP) Tota 2 Insur NO Most DITC Trafff TWC Surfat BLA Truc NO	cle Type ORT) UTILITY VEHICI I Occs rance? It Harmful Event: Collision CH flic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU Ik Bus or HazMat Vehicle License Plate Number	Train/Bus # Recorded Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH	CrashTire Mark Idal FUNCTION rol ROL atture T	Speed Lin 35	ers Emergency NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing		
	Vehi (SP) Tota 2 Insur NO Most DITC Trafff TWC Surfat BLA Truc NO	cle Type ORT) UTILITY VEHICI I Occs rance? It Harmful Event: Collision CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU Ik Bus or HazMat Vehicle License Plate Number A4514XE Vehicle Identification Nu	Train/Bus # Recorded Direction Of Travel WESTBOUND With Direction Of Travel WESTBOUND	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH	CrashTire Mark Idetion IIAL FUNCTION TOI ROL STUTE T EMPORARY PLAT	Speed Lin 35	ers ers Emergency NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss UNITED ST Model	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing		
	Vehi (SP) Tota 2 Insur NO Most DITC Traff TWC Surfa BLA	cle Type ORT) UTILITY VEHICI I Occs rance? It Harmful Event: Collision CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number A4514XE Vehicle Identification Nu 1GNDT13S94235397	Train/Bus # Recorded Direction Of Travel WESTBOUND With Direction Of Travel WESTBOUND	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type TMP - TE Make CHEVRO	CrashTire Mark loction IIAL FUNCTION rol ROL sture T	Speed Lin 35 St WI Year	ers Emergency NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss UNITED ST Model NO DATA F	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing		
	Vehi (SP) Tota 2 Insur NO Most DITC Traff TWC Surfa BLA	cle Type ORT) UTILITY VEHICI I Occs rance? t Harmful Event: Collision CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number A4514XE Vehicle Identification Nu 1GNDT13S94235397 Color	Train/Bus # Recorded Direction Of Travel WESTBOUND With Direction Of Travel WESTBOUND	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type TMP - TE Make CHEVRO Body Style	CrashTire Mark Idal FUNCTION rol ROL ature T	Speed Lin 35 St WI Year 2004	ers ers Emergency NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss UNITED ST Model	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing		
	Vehi (SP) Tota 2 Insur NO Most DITC Traff TWC Surfa BLA	cle Type ORT) UTILITY VEHICI I Occs rance? It Harmful Event: Collision CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU Ik Bus or HazMat Vehicle License Plate Number A4514XE Vehicle Identification Nu 1GNDT13S94235397 Color GRY - GRAY	Train/Bus # Recorded Direction Of Travel WESTBOUND With Direction Of Travel WESTBOUND	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type TMP - TE Make CHEVRO Body Style	CrashTire Mark Idal FUNCTION ITAL FUNC	Speed Lin 35 St WI Year 2004	ers Emergency NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss UNITED ST Model NO DATA F	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing		
ONI ONI	Vehi (SPA) Tota 2 Insur NO Most DITC Trafff Truc NO	cle Type ORT) UTILITY VEHICI I Occs rance? It Harmful Event: Collision CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU Ik Bus or HazMat Vehicle License Plate Number A4514XE Vehicle Identification Nu 1GNDT13S94235397 Color GRY - GRAY Initial Contact Point	Train/Bus # Recorded Direction Of Travel WESTBOUND With Discourse of the second of	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type TMP - TE Make CHEVRO Body Style UT - SPC	CrashTire Mark Idal FUNCTION ITAL FUNC	Speed Lin 35 St WI Year 2004	ers Emergency NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss UNITED ST Model NO DATA F	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing		
ONI ONI	Vehi (SPA) Tota 2 Insur NO Most DITC Trafff Truc NO	cle Type ORT) UTILITY VEHICI I Occs rance? It Harmful Event: Collision CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU Ik Bus or HazMat Vehicle License Plate Number A4514XE Vehicle Identification Nu 1GNDT13S94235397 Color GRY - GRAY Initial Contact Point 00 - NON-COLLISIO	Train/Bus # Recorded Direction Of Travel WESTBOUND With Discourse of the second of	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type TMP - TE Make CHEVRO Body Style UT - SPC Vehicle Da	CrashTire Mark Idan IIAL FUNCTION ITAL FUNCTION ITAL ITAL ITAL ITAL ITAL ITAL ITAL ITAL	Speed Lin 35 St WI Year 2004	ers Emergency NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss UNITED ST Model NO DATA F	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing		
	Vehi (SP) Tota 2 Insur NO Most DITC Traff TWC Surfa BLA	cle Type ORT) UTILITY VEHICI I Occs rance? It Harmful Event: Collision CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU Ik Bus or HazMat Vehicle License Plate Number A4514XE Vehicle Identification Nu 1GNDT13S94235397 Color GRY - GRAY Initial Contact Point	Train/Bus # Recorded Direction Of Travel WESTBOUND With Discourse of the second of	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type TMP - TE Make CHEVRO Body Style UT - SPC	CrashTire Mark Idan IIAL FUNCTION ITAL FUNCTION ITAL ITAL ITAL ITAL ITAL ITAL ITAL ITAL	Speed Lin 35 St WI Year 2004	ers Emergency NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss UNITED ST Model NO DATA F	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing		

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 03/28/2020

Crash Time 99:99

		Towed Due To Damage			hicle Removed By				
		NOT TOWED			WNER				
		What Driver Was Doing		Ve	hicle Factors				
		U TURN Driver Prior Action Other		NO.	OT APPLICABLE				
		Driver Prior Action Other		""	JI AI I LIOADEL				
		Driver Actions							
	щ	RAN OFF ROADWAY							
LNO	CL								
5	VEHICL								
	>								
		Owner Name			Owner Address				
		MCKAYLA JOY BENNETT			S944 BIRCHWOOD RD				
6	0	(608) 344-1025			WISCONSIN DELLS, WI 53965 , US				
		Sequence Of Events							
	01	Event CROSS CENTERLINE							
	02	Event RUN OFF ROADWAY RIG	нт						
	03	Event DITCH							
		Event							
	04								
		ndividual							
		Driver			Citations Issued	Sex			
	Ļ	MCKAYLA JOY BENNETT (608) 344-1025	•		0	FEMALE			
	INDIVIDUAL	(000) 344-1023			Date of Birth	Race WHITE			
	≥	Address			Driver License Number				
ا ر	ΝD	S944 BIRCHWOOD RD WISCONSIN DELLS, WI 53965 , US			STATE: WISCONSIN COUNTRY: UNITED STATES				
	_				STATE: WISSONSIN SOCIATION SHIPE STATES				
					Safety Equipment				
	Sat	fety Equipment	Olasii		Salety Equipment				
		Row Seat Position			SHOULDER & LAP BELT				
		01 - FRONT ROW	07 - LE	FT					
		Helmet Use			Helmet Compliance				
		Eye Protection			Tint Compliance				
		Lye i lotection			Thit Compliance				
_	Ξ	Injury Se	everity		Airbag				
2	9	Injury NO AP	PARENT I	NJURY	NON DEPLOYED				
		Ejected	Ejection Pa			Trapped/Extricated			
		NOT EJECTED Medical Transport	NOT EJE	CTED/NOT APPLIC		NOT TRAPPED			
		NOT TRANSPORTED			EMS Agency Identifier	EMS Run #			
		Hospital			Date of Death	Time of Death			
		·							
	,	Distracted By UNKNO	ed By Source DWN)		·			
		Distracted By Action UNKNOWN							
		Striking	Unit #	Location					
		Non Motorist							

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

ı										
		Prior Action								
LINO	INDIVIDUAL	Action								
		Action Other						To/From School		
		Sugnes	ad Alashal I	loo						
	L	Drug & Alcohol NO	ted Alcohol l	Jse	Suspected Drug Use NO					
		Alcohol Test Given		Alcohol Test Type)		Alcohol Test Results			
		TEST NOT GIVEN Drug Test Given		Drug Test Type		Drug Test Results				
		TEST NOT GIVEN		9		Drug Foot Roodilo				
5	001	Drug Type		+						
	0									
		Individual Condition								
		NOT OBSERVED								
		Individual	ndividual							
		Passenger AXEL ROY CONRAD (608) 432-3472 Address S944 BIRCHWOOD RD			Citations Issued Sex					
	AL				0 Date of Birth		MALE Race			
⊨							WHITE			
L N N	INDIVIDUAL				Driver License Number					
	Z	WISCONSIN DELLS, WI 5	3965 , US	3	STATE: WISCONSIN	I COUNTRY: UNI	TED STATES			
	On Duty Crash Safety Equipment			Safety Equipment						
		Row Seat Position 01 - FRONT ROW 09 - RIGHT			SHOULDER & LAP	BELT				
		Helmet Use			Helmet Compliance					
		Eye Protection			Tint Compliance					
			a a rit. :		Airbag					
2	005	Injury Severity NO APPARENT INJURY			Airbag NON DEPLOYED					
		Ejected	Ejection Pa	ath			Trapped/Extricated			
		NOT EJECTED NOT EJECTED/NOT APP Medical Transport			LICABLE EMS Agency Identifier		NOT TRAPPED EMS Run #			
		NOT TRANSPORTED			EMS Agency identifier EMS Ruff #		LIVIS IXUIT#			
		Hospital			Date of Death Time of Death					
		Distracted By	ed By Sourc	e						
		Distracted By Action								
				Γ						
		Non Motorist Striking	Unit #	Location						
		Prior Action		1						

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 03/28/2020

Crash Time 99:99

Action Action								
	_							
INDIVIDUAL								
INDIVIDUAL								
UNI DIVIDNI DI CALLO DE LA CALLO DEL CALLO DE LA CALLO DEL CALLO DE LA CALLO D								
Z								
Action Other To/	o/From School							
Action Other	J/FIOIII SCHOOL							
Suspected Alcohol Use Suspected Drug Use								
Drug & Alcohol NO NO								
Alcohol Test Given Alcohol Test Type Alcohol Test Results								
TEST NOT GIVEN								
Drug Test Given Drug Test Type Drug Test Results TEST NOT GIVEN								
Drug Type								
Individual Condition								
NOT OBSERVED								
NOT OBSERVED								
Property Owner								
The state of the s								
5 Individual FRANK L ZITSKE E9489 OAK HILL RD	E9489 OAK HILL RD							
(608) 254-5636 WISCONSIN DELLS, WI 53965 , US								
(608) 254-5636 WISCONSIN DELLS, WI 53965 , US								
Fixed Objects Struck								
	nage Tag Number							
5 01 DITCH								