

6TL09H5JRG
20-04247

WISCONSIN MOTOR VEHICLE
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

6TL09H5JRG

Document Number Override		Primary Crash Document #	Agency Crash Number 20-04247	Investigating Officer/Deputy DEPUTY S. MESSNER	
Crash Date 05/07/2020		Crash Time 02:30 PM	Date Arrived 05/07/2020	Time Arrived 02:55 PM	
Date Notified 05/07/2020		Time Notified 02:40 PM	Total Units 01	Total Injured 00	Total Killed 00
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure	<input type="checkbox"/> Work Zone	<input type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold
<input type="checkbox"/> Government Property	<input type="checkbox"/> Active School Zone	School Bus Related NO		Tags	
<input checked="" type="checkbox"/> Reportable		Crash Type DT4000 (STANDARD CRASH)		<input type="checkbox"/> Amended	<input type="checkbox"/> Secondary Crash

Description

<p>Diagram</p> <p>debris where it came to rest</p> <p>Unit 1 debris in motion</p> <p>Witness debris</p> <p>STH 23/33</p>	Reconstruction By
	Photos By DEP. S. MESSNER
	Additional Information PHOTOS

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

ON MAY 7, 2020, AT APPROXIMATELY 2:30 PM, A RED F550 TRUCK, BEARING WI# EC58480, BEING DRIVEN BY JUSTIN J. STANFORD, M/W DOB: 02/09/1999, WAS EASTBOUND ON STH 23/33, EAST OF AULT ROAD, WHEN THE VEHICLE STRUCK A PIECE OF DEBRIS IN ITS LANE OF TRAFFIC. THE DEBRIS WAS KICKED UP AND STRUCK UNIT 1, A 2016 GRAND CARAVAN BEARING WISCONSIN REGISTRATION PLATE WI#501UTX, AND BEING DRIVEN BY KRISTINA A. GARCIA. THE DEBRIS STRUCK UNIT 1'S FRONT CORNER PANEL, CAUSING DAMAGE. KRISTINA FOLLOWED THE TRUCK UNTIL SHE WAS ABLE TO GET THE REGISTRATION PLATE AND CONTACT SAUK COUNTY DISPATCH CENTER. AFTER REPORTING THE MATTER, LAW ENFORCEMENT WAS TAKEN BACK TO THE SCENE AND THE DEBRIS WAS IDENTIFIED AS A MUFFLER. NO VEHICLE WAS IDENTIFIED OF WHICH THE MUFFLER CAME OFF. PHOTOGRAPHS WERE TAKEN OF UNIT 1 AND THE MUFFLER. KRISTINA WAS ABLE TO REMOVE THE VEHICLE FROM THE SCENE.

WISCONSIN MOTOR VEHICLE
CRASH REPORT

Location

ON STH23 EB 330 FT W OF LAKE VIRGINIA RD IN THE TOWN OF EXCELSIOR IN SAUK COUNTY	Latitude 43.533068659	Longitude -89.936703093
	X Coordinate 262708.34375	Y Coordinate 4824204.5
	Structure Type NO STRUCTURE	

Crash Scene

First Harmful Event OTHER OBJECT - NOT FIXED	First Harmful Event Location ON ROADWAY	
Manner of Collision 00 - NO COLLISION W/VEHICLE IN TRANSPORT	Light Condition DAYLIGHT	
Road Surface Condition(s) DRY	Roadway Factor(s) OTHER DEBRIS	
Environment Factor(s) NONE		
Weather Condition(s) CLEAR		
Animal Type	Relation To Trafficway TRAFFICWAY - ON ROAD	
Crash Classification - Location PUBLIC PROPERTY	Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land	Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location NON-JUNCTION	Intersection Type NOT AN INTERSECTION

Unit Summary

UNIT	Unit Status IN TRANSIT	Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE	
	Vehicle Type PASSENGER CAR	Operating As Endorsements			
	Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types 0
	Insurance? YES	Direction Of Travel EASTBOUND	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit 55	Total Lanes 2
	Most Harmful Event: Collision With OTHER OBJECT - NOT FIXED	Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way TWO-WAY, NOT DIVIDED	Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)	Road Curvature STRAIGHT		Road Grade DOWNHILL	
	Truck Bus or HazMat NO				

UNIT	VEHICLE	Vehicle			
		License Plate Number 501UTX	Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES
		Vehicle Identification Number 2C4RDGCGXGR160853	Make DODGE	Year 2016	Model GRAND CARA
		Color WHI - WHITE	Body Style VN - VAN		Bus Use
		Initial Contact Point 11 - LEFT FRONT CORNER	Vehicle Damage 11 - LEFT FRONT CORNER		
	Extent Of Damage FUNCTIONAL DAMAGE				

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT VEHICLE	Towed Due To Damage NOT TOWED		Vehicle Removed By OPERATOR	
	What Driver Was Doing GOING STRAIGHT		Vehicle Factors	
	Driver Prior Action Other		NOT APPLICABLE	
	Driver Actions NO CONTRIBUTING ACTION			
01	Owner Name BAUTISTA P GARCIA (608) 495-2432		Owner Address 126 S AIRE DR REEDSBURG, WI 53959 , US	
	Sequence Of Events			
01	01	Event OTHER NON-COLLISION		
	02	Event		
	03	Event		
	04	Event		
UNIT	Policy Holder			
	Insurance Company GEICO-GENERAL-INS-CO		Individual KRISTINA GARCIA	
UNIT INDIVIDUAL	Individual			
	Driver KRISTINA ANN GARCIA (608) 495-2432		Citations Issued 0	Sex FEMALE
	Address 126 S AIRE DR REEDSBURG, WI 53959 , US		Date of Birth	Race WHITE
	Driver License Number		STATE: WISCONSIN COUNTRY: UNITED STATES	
01	Safety Equipment		On Duty Crash	
	Row 01 - FRONT ROW		Seat Position 07 - LEFT	
	Safety Equipment		SHOULDER & LAP BELT	
	Helmet Use		Helmet Compliance	
	Eye Protection		Tint Compliance	
	Injury		Injury Severity NO APPARENT INJURY	Airbag NON DEPLOYED
Ejected NOT EJECTED		Ejection Path NOT EJECTED/NOT APPLICABLE		Trapped/Extricated NOT TRAPPED
Medical Transport NOT TRANSPORTED		EMS Agency Identifier		EMS Run #
Hospital		Date of Death		Time of Death
Distracted By		Distracted By Source NOT APPLICABLE (NOT DISTRACTED)		
Distracted By Action NOT DISTRACTED				

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT	Non Motorist	Striking Unit #	Location		
		Prior Action			
	INDIVIDUAL	Action			
		Action Other			To/From School
		Drug & Alcohol	Suspected Alcohol Use NO	Suspected Drug Use NO	
		Alcohol Test Given TEST NOT GIVEN	Alcohol Test Type	Alcohol Test Results	
	Drug Test Given TEST NOT GIVEN	Drug Test Type	Drug Test Results		
	Drug Type				
	Individual Condition APPEARED NORMAL				

Witness

WITN 01 ESS	Individual JUSTIN J STANFORD (608) 963-3466	Address 826 COUNTY ROAD K WISCONSIN DELLS, WI 53965 , US	Date of Birth
----------------	--	--	---------------