WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Document Number Overric	de Primary Crash [Primary Crash Document # Crash Time 09:50 PM Time Notified 09:53 PM		20-07664 Date Arrived		Investigating Officer/Deputy DEPUTY W. NEUBAUER		
Crash Date 08/03/2020						Time Arrived 10:05 PM		
Date Notified 08/03/2020	Time Notified			nits	Total Injured To		Total Killed 00	
On Emergency	Hit and Run	Lane Closu		Work Zone	Trailer	or To	wed	Reporting Threshold
Government Property		hool Zone	School I	Bus Related	Tags			
Reportable	Crash Type DT4000 (STA	NDARD CRASH)		Amend	led		Secondary Crash
oliagram (Control of the Control of						Photo 9140		Зу
						Additi NON	onal Inforn E, PHOT	nation OS
			<u> </u>	_				
NOT T	O SCALE							

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 08/03/2020

Crash Time 09:50 PM

	Loc	ation								
		E8800 BRIAR BLUFF	RD		Latitude)		Longitud	de	
	-	MI E			43.560	43.560827713		-89.882	20788	
	-	SIMPSON RD			X Coordinate 267229.25			Y Coord	inate	
	(HO	USE/BUILDING E8800	J)					482713	33	
		HE TOWN OF DELLO	NA			Structure Type HOUSE/BUILDING				
						_,,				
		sh Scene Harmful Event			First III		1 4'			
		_VERT				armful Event	Location			
		ner of Collision			ROADSIDE Light Condition					
			HICLE IN TRANSPORT		_	Light Condition DARK/UNLIT				
		d Surface Condition(s)				ay Factor(s)				
	DR	4								
	Envi	ronment Factor(s)								
	NOI	NE			NONE					
	Wea	ther Condition(s)								
	CLC	DUDY								
	Anin	nal Type				Relation To Trafficway				
						TRAFFICWAY - ON ROAD				
		sh Classification - Location BLIC PROPERTY				Crash Classification - Jurisdiction				
		al Land				NO SPECIAL JURISDICTION Access Control			Special Study	
						NO CONTROL				
	NO NO	in Interchange Area	Junction Location NON-JUNCTION		Intersection Type	section Type T AN INTERSECTION				
			11011 0011011011		NOT AN INTER	JEO 11011				
		t Summary =	NON CONCINCT		NOT AN INTER	JEO HOIL				
	Uni	t Summary Status		Vehicle Ope	erating As Classificat		Unit Type			
	Uni Unit		NON TONOTION	Vehicle Ope	erating As Classificat		Unit Type AUTOMO	BILE		
	Unit Unit IN T	Status RANSIT cle Type	NON TONO MONEY		erating As Classificat				ments	
10	Unit Unit IN T Vehi	Status RANSIT cle Type SSENGER CAR		D CLASS	erating As Classificat	ion	AUTOMO Operating A	As Endorser		
	Unit Unit IN T Vehi	Status RANSIT cle Type	Train/Bus # Recorded	D CLASS	erating As Classificat		AUTOMO Operating A	As Endorser	ments Mat Types	
	Unit Unit IN T Vehi PAS Tota 1	Status RANSIT cle Type SSENGER CAR		D CLASS Total # Cita 0	erating As Classificat	ion Total Tra	AUTOMO Operating A	As Endorser	Mat Types	
10	Unit Unit IN T Vehi PAS Tota 1	Status RANSIT cle Type SSENGER CAR I Occs rance?	Train/Bus # Recorded	D CLASS Total # Cita 0	erating As Classificat	Total Tra	AUTOMO Operating A	Total Haz	Mat Types	
10	Unit IN T Vehi PAS Tota 1 Insu YES	Status RANSIT cle Type SSENGER CAR I Occs rance? S t Harmful Event: Collision V	Train/Bus # Recorded Direction Of Travel WESTBOUND	Total # Cita 0 Pre Special Fur	tions Issued CrashTire Mark	Total Tra 0 Speed L	AUTOMO Operating A ailers imit Emergency	Total Haz 0 Total Land 2 Motor Vehi	Mat Types es	
	Unit IN T Vehi PAS Tota 1 Insu YES Most	Status RANSIT cle Type SSENGER CAR I Occs rance? S t Harmful Event: Collision V	Train/Bus # Recorded Direction Of Travel WESTBOUND	Total # Cita 0 Pre Special Fur	tions Issued CrashTire Mark action EIAL FUNCTION	Total Tra 0 Speed L	AUTOMO Operating A ailers imit Emergency NOT APP	Total Haz 0 Total Land 2 Motor Vehi	Mat Types es icle Use	
10	Unit Unit IN T Vehi PAS Tota 1 Insu YES Mos: CUI	Status RANSIT cle Type SSENGER CAR I Occs rance? St Harmful Event: Collision V LVERT Tic Way	Train/Bus # Recorded Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC	tions Issued CrashTire Mark action EIAL FUNCTION Errol	Total Tra 0 Speed L	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont	Total Haz 0 Total Land 2 Motor Vehi	Mat Types es icle Use	
10	Unit IN T Vehi PAS Tota 1 Insu YES Moss CUL Traff	Status RANSIT cle Type SSENGER CAR I Occs rance? St Harmful Event: Collision V LVERT fic Way D-WAY, NOT DIVIDED	Train/Bus # Recorded Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont	erating As Classificat tions Issued CrashTire Mark cition CIAL FUNCTION trol CROL	Total Tra 0 Speed L	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont	Total Haz 0 Total Land 2 Motor Vehi LICABLE rol Inoperat	Mat Types es icle Use	
10	Unit Unit IN T Vehi PAS Tota 1 Insu YES Mos: CUI Traff TWC	Status RANSIT cle Type SSENGER CAR I Occs rance? St Harmful Event: Collision V LVERT Tic Way	Train/Bus # Recorded Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC	tions Issued CrashTire Mark CIAL FUNCTION CIAL FUNCTION CITCLE CROL ature	Total Tra 0 Speed L	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont	Total Haz 0 Total Land 2 Motor Vehi LICABLE rol Inoperat	Mat Types es icle Use	
10	Unit Unit IN T Vehi PAS Tota 1 Insu YES Most CUI Traff TWG	Status RANSIT cle Type SSENGER CAR I Occs rance? St Harmful Event: Collision V LVERT fic Way D-WAY, NOT DIVIDED ace Type	Train/Bus # Recorded Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva	tions Issued CrashTire Mark CIAL FUNCTION CIAL FUNCTION CITCLE CROL ature	Total Tra 0 Speed L	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade	Total Haz 0 Total Land 2 Motor Vehi LICABLE rol Inoperat	Mat Types es icle Use	
10	Unit Unit IN T Vehi PAS Tota 1 Insu YES Most CUI Traff TWG	Status RANSIT cle Type SSENGER CAR I Occs rance? St Harmful Event: Collision V LVERT fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS)	Train/Bus # Recorded Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva	tions Issued CrashTire Mark CIAL FUNCTION CIAL FUNCTION CITCLE CROL ature	Total Tra 0 Speed L	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade	Total Haz 0 Total Land 2 Motor Vehi LICABLE rol Inoperat	Mat Types es icle Use	
10	Unit Unit IN T Vehi PAS Tota 1 Insu YES Moss CUL Traff TWO Surfa BLA Truc NO	Status RANSIT cle Type SSENGER CAR I Occs rance? S t Harmful Event: Collision N LVERT fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS) k Bus or HazMat	Train/Bus # Recorded Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva	tions Issued CrashTire Mark CIAL FUNCTION CIAL FUNCTION CITCLE CROL ature	Total Tra 0 Speed L 45	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade LEVEL	Total Haz 0 Total Land 2 Motor Vehi LICABLE rol Inoperat	Mat Types es icle Use	
10	Unit Unit IN T Vehi PAS Tota 1 Insu YES Moss CUL Traff TWO Surfa BLA Truc NO	Status RANSIT cle Type SSENGER CAR I Occs rance? St Harmful Event: Collision V LVERT fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ik Bus or HazMat Vehicle License Plate Number	Train/Bus # Recorded Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH	tions Issued CrashTire Mark Inction EIAL FUNCTION ETGI TROL ature T	Total Tra 0 Speed L 45	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade LEVEL	Total Haz O Total Land 2 Motor Vehi LICABLE rol Inoperation	Mat Types es icle Use	
10	Unit Unit IN T Vehi PAS Tota 1 Insu YES Moss CUL Traff TWO Surfa BLA Truc NO	Status RANSIT cle Type SSENGER CAR I Occs rance? St Harmful Event: Collision V LVERT fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS) k Bus or HazMat Vehicle License Plate Number ACC8807	Train/Bus # Recorded Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH	tions Issued CrashTire Mark Inction EIAL FUNCTION ETGI TROL ature T	Total Tra 0 Speed L 45	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED S	Total Haz O Total Land 2 Motor Vehi LICABLE rol Inoperation	Mat Types es icle Use	
10	Unit Unit IN T Vehi PAS Tota 1 Insu YES Moss CUL Traff TWO Surfa BLA Truc NO	Status RANSIT cle Type SSENGER CAR I Occs rance? St Harmful Event: Collision V LVERT fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ik Bus or HazMat Vehicle License Plate Number	Train/Bus # Recorded Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AU Make MITSUBI	tions Issued CrashTire Mark Cital FUNCTION Crol TROL ature T	Total Tra 0 Speed L 45	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade LEVEL	Total Haz O Total Land 2 Motor Vehi LICABLE rol Inoperation	Mat Types es icle Use	
UNIT 01	Unit Unit Unit Unit Unit Unit Unit Unit	Status RANSIT Cle Type SSENGER CAR I Occs rance? S t Harmful Event: Collision V VERT fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number ACC8807 Vehicle Identification Num ML32A3HJ2KH01141 Color	Train/Bus # Recorded Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AU Make MITSUBI Body Style	tions Issued CrashTire Mark Inction CIAL FUNCTION CIAL FUNCTION CITY TO	Total Tra 0 Speed L 45	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED S	Total Haz O Total Land 2 Motor Vehi LICABLE rol Inoperation	Mat Types es icle Use	
UNIT 01	Unit Unit Unit Unit Unit Unit Unit Unit	Status RANSIT cle Type SSENGER CAR I Occs rance? St Harmful Event: Collision Nation Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS) k Bus or HazMat Vehicle License Plate Number ACC8807 Vehicle Identification Num ML32A3HJ2KH01141 Color WHI - WHITE	Train/Bus # Recorded Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AU Make MITSUBI Body Style HB - HAT	tions Issued CrashTire Mark Inction CIAL FUNCTION CIAL FUNCTION CITY CITY CITY CITY CITY CITY CITY CITY	Total Tra 0 Speed L 45	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED S' Model MIRAGE	Total Haz O Total Land 2 Motor Vehi LICABLE rol Inoperation	Mat Types es icle Use	
10 UNIT 01	Unit Unit IN T Vehi PAS Tota 1 Insu YES Mos: CUI Traff TWO Surfa BLA Truc NO	Status RANSIT Cle Type SSENGER CAR I Occs rance? S t Harmful Event: Collision V VERT fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number ACC8807 Vehicle Identification Num ML32A3HJ2KH01141 Color	Train/Bus # Recorded Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AU Make MITSUBI Body Style HB - HAT Vehicle Da	crating As Classificat tions Issued CrashTire Mark Cital FUNCTION trol TROL ature T JTOMOBILE SHI CHBACK Amage	Total Tra 0 Speed L 45 St WI Year 2019	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED S' Model MIRAGE Bus Use	Total Haz 0 Total Land 2 Motor Vehi LICABLE rol Inoperation	Mat Types es icle Use tive/Missing	
UNIT 01	Unit Unit IN T Vehi PAS Tota 1 Insu YES Most CUI Traff TWO Surfa BLA Truca NO	Status RANSIT cle Type SSENGER CAR I Occs rance? S t Harmful Event: Collision Nation Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number ACC8807 Vehicle Identification Num ML32A3HJ2KH01141 Color WHI - WHITE Initial Contact Point	Train/Bus # Recorded Direction Of Travel WESTBOUND With	D CLASS Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AU Make MITSUBI Body Style HB - HAT Vehicle Da 01 - RIGH	tions Issued CrashTire Mark Inction CIAL FUNCTION CIAL FUNCTION CITY CITY CITY CITY CITY CITY CITY CITY	Total Tra 0 Speed L 45 St WI Year 2019	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED S' Model MIRAGE Bus Use	Total Haz 0 Total Land 2 Motor Vehi LICABLE rol Inoperation	Mat Types es icle Use tive/Missing	

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 08/03/2020

Crash Time 09:50 PM

		Towed Due To Damage TOWED DUE TO DISABLE	NG DAMAGE		hicle Removed By				
		What Driver Was Doing			hicle Factors				
		GOING STRAIGHT			NOT APPLICABLE				
		Driver Prior Action Other		NC	71 APPLICABLE				
LINO	VEHICLE	Driver Actions RAN OFF ROADWAY		1					
		Owner Name TYLER MICHAEL HASKE			Owner Address 213 S PRESTON AVE APT 5				
6	01	(608) 432-3137			REEDSBURG, WI 53959 , US				
		Sequence Of Events Event							
	01	MOTOR VEH IN TRANSPO	ORT						
	02	RUN OFF ROADWAY RIG	нт						
	03	Event CULVERT							
	04	Event							
-	Ì	L Policy Holder							
LIND		Insurance Company PROGRESSIVE-CASUALTY-INS-CO			Individual TYLER HASKE				
	Ì	Individual							
		Driver TYLER MICHAEL HASKE			Citations Issued	Sex			
	AL	(608) 432-3137			Date of Birth	Race			
⊨	IDU				Jan 0. 2	WHITE			
LINO	INDIVIDUAL	Address 213 S PRESTON AVE APT 5 REEDSBURG, WI 53959 , US			Driver License Number STATE: WISCONSIN COUNTRY: UNITED STATES				
	Sat	On Duty fety Equipment	Crash	:	Safety Equipment				
	Jai	Row	Seat Position	Ц,	SHOULDER & LAP BELT				
		01 - FRONT ROW	07 - LEFT						
		Helmet Use		Helmet Compliance					
		Eye Protection			Tint Compliance				
2	001	Injury Severity NO APPARENT INJURY			Airbag DEPLOYED-FRONT				
			Ejection Path			Trapped/Extricated			
		NOT EJECTED NOT EJECTED/NOT API Medical Transport			EMS Agency Identifier	NOT TRAPPED EMS Run #			
		NOT TRANSPORTED			LINO Agency Identifier	Livio Rail #			
		Hospital			Date of Death	Time of Death			
Distracted By Source NOT APPLICABLE (NOT DISTRACTE					ΓED)	I			
		Distracted By Action NOT DISTRACTED	•		•				
		NOT DISTRACTED							

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 08/03/2020

Crash Time 09:50 PM

		Non Motor	Striking Unit #	Location				
		Prior Action		1				
		Action						
	۱۹L							
UNIT	/IDU							
)	INDIVIDUAL							
		Action Other						To/From School
	L	Orug & Alcoh	Suspected Alcohol U	lse	Suspected Drug Use NO			
	Alcohol Test Given Alcohol Test Typ			Alcohol Test Type			Alcohol Test Results	
		Drug Test Given TEST NOT GIV	EN	Drug Test Type		Drug Test Results	<u> </u>	
01	001	Drug Type						
		Individual Condition	on					
		APPEARED NO	DRMAL					
	Pro	perty Owne	r ====					
PROP OWNER 01	(608	ernment JK COUNTY HW 8) 356-3855			Address 620 STH 136 PO BOX 26 BARABOO, WI 53913	, US		
	Fixe	d Objects St						
	5	Striking Unit 01	Struck Object CULVERT					Damage Tag Number 337769