

WISCONSIN MOTOR VEHICLE
CRASH REPORT

6TL0C22XWH

Document Number Override		Primary Crash Document#		Agency Crash Number 21-00890		Investigating Officer/Deputy SERGEANT S. STEINHORST	
Crash Date 01/30/2021		Crash Time 09:43 PM		Date Arrived 01/30/2021		Time Arrived 10:05 PM	
Date Notified 01/30/2021		Time Notified 09:46 PM		Total Units 01		Total Injured 00	Total Killed 00
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure	<input type="checkbox"/> Work Zone		<input type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold	
<input type="checkbox"/> Government Property		<input type="checkbox"/> Active School Zone		School Bus Related NO		Tags	
<input type="checkbox"/> Reportable		Crash Type DT4000 (STANDARD CRASH)				<input type="checkbox"/> Amended	<input type="checkbox"/> Secondary Crash

Description

Diagram	Reconstruction By
	Photos By
	Additional Information NONE

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

UNIT 1 WAS CLIMBING THE HILL ON USH 12 SOUTH OF SKI HI RD TRAVELING WESTBOUND. DUE TO THE POOR ROAD CONDITIONS CAUSED BY THE SNOW THE CAR BECAME STUCK IN THE MEDIAN BETWEEN THE EAST AND WESTBOUND LANES. CRAIGS TOWING REMOVED THE CAR FROM THE MEDIAN, NO DAMAGE.

WISCONSIN MOTOR VEHICLE
CRASH REPORT

Location

ON USH12 WB 0.95 MI S OF USH12 WB IN THE TOWN OF SUMPTER IN SAUK COUNTY	Latitude 43.406438976	Longitude -89.771964605
	X Coordinate 275551.65625	Y Coordinate 4809683
	Structure Type NO STRUCTURE	

Crash Scene

First Harmful Event DITCH	First Harmful Event Location MEDIAN	
Manner of Collision 00 - NO COLLISION W/VEHICLE IN TRANSPORT	Light Condition DARK/UNLIT	
Road Surface Condition(s) SNOW	Roadway Factor(s) ROAD SURFACE CONDITION (WET, ICY, SNOW, SLUSH, ETC)	
Environment Factor(s) WEATHER CONDITIONS		
Weather Condition(s) SNOW		
Animal Type	Relation To Trafficway TRAFFICWAY - NOT ON ROAD	
Crash Classification - Location	Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land	Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location NON-JUNCTION	Intersection Type NOT AN INTERSECTION

Unit Summary

UNIT	Unit Status IN TRANSIT	Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE	
	Vehicle Type PASSENGER CAR	Operating As Endorsements			
	Total Occs 01	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types 0
	Insurance? UNKNOWN	Direction Of Travel WESTBOUND	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit 55	Total Lanes 04
	Most Harmful Event: Collision With DITCH	Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way DIVIDED HWY W/O TRAFFIC BARRIER	Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)	Road Curvature STRAIGHT		Road Grade UPHILL	
	Truck Bus or HazMat				

Vehicle

UNIT	VEHICLE	License Plate Number WJF241	Plate Type AUT - AUTOMOBILE	St NE	Country of Issuance UNITED STATES	
		Vehicle Identification Number 1G1ZD5ST5LF116577	Make CHEVROLET	Year 2020	Model MALIBU	
		Color BLK - BLACK	Body Style SD - SEDAN		Bus Use	
		Initial Contact Point 12 - FRONT	Vehicle Damage			
		Extent Of Damage NO DAMAGE	00 - NO DAMAGE			

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT VEHICLE	Towed Due To Damage TOWED BUT NOT DUE TO DISABLING DAMAG		Vehicle Removed By CRAIGS TOWING		
	What Driver Was Doing GOING STRAIGHT		Vehicle Factors		
	Driver Prior Action Other		NOT APPLICABLE		
	Driver Actions NO CONTRIBUTING ACTION				
	Owner Name EAN HOLDINGS LLC		Owner Address 14002 E 21ST ST		
UNIT 01	Sequence Of Events				
	Event DITCH				
	Event				
	Event				
	Event				
UNIT INDIVIDUAL	Individual				
	Driver KATHERINE MARIE SMALLWOOD		Citations Issued 0	Sex FEMALE	
			Date of Birth [REDACTED]	Race WHITE	
	Address 27516 ORLANDO AVE KENDALL, WI 54638 , US		Driver License Number [REDACTED] STATE: WISCONSIN COUNTRY: UNITED STATES		
	Safety Equipment		On Duty Crash		
		Safety Equipment			
Row 01 - FRONT ROW		Seat Position 07 - LEFT	SHOULDER & LAP BELT		
Helmet Use		Helmet Compliance			
Eye Protection		Tint Compliance			
UNIT 01 001	Injury		Injury Severity NO APPARENT INJURY	Airbag NON DEPLOYED	
	Ejected NOT EJECTED	Ejection Path NOT EJECTED/NOT APPLICABLE		Trapped/Extricated NOT TRAPPED	
	Medical Transport NOT TRANSPORTED		EMS Agency Identifier	EMS Run #	
	Hospital		Date of Death	Time of Death	
	Distracted By		Distracted By Source NOT APPLICABLE (NOT DISTRACTED)		
Distracted By Action NOT DISTRACTED					
Non Motorist		Striking Unit #	Location		

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT	Prior Action			
	Action			
	Action Other		To/From School	
	Drug & Alcohol	Suspected Alcohol Use NO	Suspected Drug Use NO	
	Alcohol Test Given TEST NOT GIVEN	Alcohol Test Type	Alcohol Test Results	
	Drug Test Given TEST NOT GIVEN	Drug Test Type	Drug Test Results	
	Drug Type			
	Individual Condition APPEARED NORMAL			
	INDIVIDUAL			