24-06370

# WISCONSIN MOTOR VEHICLE CRASH REPORT

	Document Number Override	Primary Crash	Primary Crash Document # Crash Time 01:40 PM Time Notified 01:40 PM		Agency Crash Number 24-06370 Date Arrived 06/18/2024 Total Units 02		Investigating Officer/Deputy DEPUTY S. MESSNER			
PR	Crash Date 06/18/2024	-					Time Arrived 01:49 PM			
6TL0D1PTPR	Date Notified 06/18/2024						d Total Kille <b>00</b>	led		
OD,	On Emergency	Hit and Run	Lane Clos	sure	Work Zone	Trailer	or Towed	Reporting Threshold		
ŝΤΓ	Government Property	Active Se	chool Zone	School NO	Bus Related	Tags		-		
	✓ Reportable	Crash Type DT4000 (STA	ANDARD CRASH	H)		Ameno	ded	Secondary Crash		
l	Description Diagram									
					Not to scale	$\Diamond$	Photos By DEP. MESS	NER & WITNESSES		
	Unit 1 backing up parked Unit 2 and scene			-	Parked Unit 1		Additional Info PHOTOS	ormation		
	Lyni	n Street underc	construction							
	✔ I, a sworn law enforcen ON 6/18/2024, UNIT 1, A BLACK 2						ZONE PARTIAI	LY CLOSED ROAD WITH		
	EMERGENCY FLASHERS ON. UI TIRE MARKS WERE LEFT FROM	NIT 2, A WHITE CA	B 2007 MACK 600 H	HEAVY TR	UCK, BEARING WI#NB5	359, WAS BACKIN	IG UP. UNIT 2 S			

24-06370

## WISCONSIN MOTOR VEHICLE CRASH REPORT

ON LINN ST/ STH33 EB 4 FT W	Latitude 43.474810419	Longitude -89.761638744				
OF WILLOW ST IN THE VILLAGE OF WEST BARABOO IN SAUK COUNTY	X Coordinate 276639.65625	Y Coordinate 4817249				
	Structure Type NO STRUCTURE					

	First Harmful Event		First Harmful Event Location								
	MOTOR VEH IN TRANS	PORT				ON ROADWAY					
	Manner of Collision					Light Condition					
	03 - FRONT TO REAR						DAYLIGHT				
	Road Surface Condition(s)						Factor(s)				
	DRY										
	Environment Factor(s)										
	NONE					WORK Z	ONE (COM	ISTRUCTIC	N/MAINT	ENANCE/UTILITY)	)
	Weather Condition(s)										
	CLOUDY										
	Animal Type				Relation T	o Trafficway					
						TRAFFIC	WAY - ON	ROAD			
	Crash Classification - Locati	on					ssification				
	PUBLIC PROPERTY							SDICTION			
	I ribai Land	Tribal Land Within Interchange Area Junction Location YES INTERSECTION				Access Co				Special Study	
	Within Interchange Area						IRUL				
	YES					n Type SECTION					
	Work Zone Crash Location	Work Zone	T-INTERSECTION Work Zone Crash Type								
	ACTIVITY AREA			MOVING WORK							
	Workers Present					ent					
	YES			NO		Normal Posted Speed Limit <b>25</b>					
	Work Zone Speed Limit <b>25</b>		Advisory/Regular		mit						
	Unit Summary										
	Unit Status							Unit Type			
	LEGALLY PARKED			D CLASS				TRUCK			
~	Vehicle Type			Operating As Endorsements			ments				
5	UTILITY TRUCK/PICKUP TRUCK										
	Total Occs	Train/Bus # F	Recorded		tions Issued		Total Trailers		Total HazMat Types		
	0			0			0		0		
	Insurance?	Direction Of UNKNOWN		Pre	CrashTire					es	
	YES Most Harmful Event: Collisic	Special Function			25		3 Emergency Motor Vehicle Use				
5	MOTOR VEH IN TRANS					TION		NOT APPLICABLE			
	Traffic Way					Traffic Control		Traffic Control Inoperative/Missing			
	TWO-WAY, NOT DIVIDE	NO CONT				NO					
	Surface Type	Road Curvature				Road Grade					
	BLACKTOP (BITUMINC	US)		STRAIGH	т			LEVEL			
	Truck Bus or HazMat										
	NO										
	Vehicle										
	License Plate Number			Plate Type			St	Country of Is:			
	TH3793				<b>SHT TRUC</b>	K		UNITED ST	ATES		
_	Vehicle Identification N	lumber		Make			Year	Model			

3GCUYDED6MG387667

2 2

2021

SILVERADO

CHEVROLET

24-06370

## WISCONSIN MOTOR VEHICLE CRASH REPORT

		Color		Body Style		Bus Use					
ļ		BLK - BLACK		PK - PICKUP							
۱.	Щ	Initial Contact Point		Vehicle Damage 7 8 9 10 11							
UNIT	VEHICLE	11 - LEFT FRONT COR	RNER	10 - LEFT SIDE FRONT, 1			6 12				
15	H	Extent Of Damage		12 - FRONT		SNI CONNER,	5 4 3 2 1				
	Ň	FUNCTIONAL DAMAG	E				54321				
İ.	-	Towed Due To Damage		Vehicle Removed By							
		NOT TOWED		OPERATOR							
		What Driver Was Doing		Vehicle Factors							
		LEGALLY PARKED									
		Driver Prior Action Other		NOT APPLICABLE							
		Driver Actions									
		NO CONTRIBUTING ACTION									
╘	VEHICLE										
UNIT	<u>S</u>										
5	H										
	N										
		Owner Name		Owner Address							
-	-	CORRE INC		6510 GRAND TETON							
6	01	(608) 617-5460		MADISON, WI 53719	US						
		Sequence Of Events									
		Sequence Of Events Event									
	01	PARKED MOTOR VEH	ICLE								
		Friend									
	02	Event MOTOR VEH IN TRAN	SPORT								
	0										
	03	Event									
	0										
	04	Event									
	0										
╘		Policy Holder									
UNIT		Insurance Company		Organization/Company							
5		CHARTER-OAK-FIRE-I	INS-C0 -THE	CORRE INC							
I											
		t Summary									
	-	Status		Vehicle Operating As Classificat	ion	Unit Type					
	HIT	AND RUN		D CLASS		AUTOMOBILE					
02	Vehi	cle Type				Operating As Endorsements					
0	PAS	SENGER CAR									
1	Tota	Occs	Train/Bus # Recorded	Total # Citations Issued	Total Trail	ers Tota	l HazMat Types				
	1			0	0	0	0				
	Insu	rance?	Direction Of Travel	Pre CrashTire	Speed Lin	nit Tota	l Lanes				
⊢⊢	YES	5	EASTBOUND	Mark 25		3					
UNIT	Most	t Harmful Event: Collision Wi	ith	Special Function		Emergency Motor Vehicle Use					
		RKED MOTOR VEHICLE		NO SPECIAL FUNCTION		NOT APPLICA					
		ic Way		Traffic Control		Traffic Control Inoperative/Missing					
			VITH A CONTINUOUS LE	NO CONTROL		NO					
		ace Type		Road Curvature		Road Grade					
		ACKTOP (BITUMINOUS)		STRAIGHT		LEVEL					
				STRAIGHT		LEVEL					
		k Bus or HazMat									
	TRU	JCK OR TRUCK COMBI	NATION > 10,000LBS GVW	R/GCWR							
		Vehicle									
		License Plate Number		Plate Type	St	Country of Issuand					
		NB5359		HTK - HEAVY TRUCK	wi	UNITED STATE	S				
		Vehicle Identification Numb	ber	Make	Year	Model					
03	02	1M1K189Y97M033465		MACK	2007	600					
I I				1							

24-06370

## WISCONSIN MOTOR VEHICLE CRASH REPORT

		Color		Body Style		Bus Use				
		WHI - WHITE		TK - TRUCK						
	Щ	Initial Contact Point		Vehicle Damage			7 8 9 10 11			
UNIT	Ę	04 - RIGHT SIDE REAR Extent Of Damage		04 - RIGHT SIDE RE			6			
	VEHICLE	MINOR DAMAGE		04 - KIGHT SIDE KE			5 4 3 2 1			
	-	Towed Due To Damage		Vehicle Removed By						
		NOT TOWED		OPERATOR						
		What Driver Was Doing		Vehicle Factors						
		BACKING		NOT APPLICABLE						
		Driver Prior Action Other		NOT AFFEICABLE						
		Driver Actions								
	щ	LOOKED BUT DID NOT SEE, UNKNOWN								
UNIT	VEHICLE									
5	H									
	>									
		Owner Name		Owner Address						
	2	SCOTT CONSTRUCTION	1	E9827 COUNTY						
02	02	(608) 254-2249		WISCONSIN DELLS, WI 53965 , US						
		Sequence Of Events Event								
	0	PARKED MOTOR VEHIC	LE							
	02	Event Event								
	03	Event								
		Event								
	04									
E		Policy Holder								
UNIT		Insurance Company		Organization/Compared						
-		SENTRY-INS-CO		SCOTT CONSTRU	JCTION					
	l	Individual Driver		Citations Issued	Sex					
		JONATHAN CRAPP		0	MALE					
	DUAL	(608) 425-0067		Date of Birth						
E	ğ			WHITE						
-IN NI	INDINI	Address 1345 CLAY ST		Driver License Number STATE: WISCONSIN COUNTRY: UNITED STATES Safety Equipment						
	Z	DARLINGTON, WI 53530	, US							
	0	On Dut	ty Crash							
	Sai	fety Equipment								
		01 - FRONT ROW Helmet Use	07 - LEFT	Helmet Compliance						
				Helmet Compliance						
		Eye Protection		Tint Compliance						
02	001	Injury S Injury NO A	Severity PPARENT INJURY	Airbag NOT APPLICABL	E					
		Ejected	Ejection Path			Trapped/Extricated				
		NOT APPLICABLE	NOT EJECTED/NOT AP			NOT APPLICABLE				
		Medical Transport <b>NOT TRANSPORTED</b>		EMS Agency Identifie	er	EMS Run #				
		Motor Vohicle Crash	This ron	port does not include any (		Crash D	ate 06/18/2024			

24-06370

## WISCONSIN MOTOR VEHICLE CRASH REPORT

		Hospital				Date o	f Death			Time of Death		
		Distracted By	Distracted	d By Source	9							
		Distracted By Action										
	I	Non Motorist	Striking U	Init #	Location							
		Prior Action										
		Action										
⊢	UAL											
UNIT	INDIVIDUAL											
	INI											
		Action Other									To/From School	
			Suspecto	d Alcohol II	50	Succo	cted Drug Use					
	L	Suspected Alcohol Use					cied Drug Ose					
		Alcohol Test Given Alcohol Test Typ				e				Alcohol Test Results		
		Drug Test Given Drug Te TEST NOT GIVEN			Drug Test Type	t Type Drug Test Result			Results			
02	001	Drug Type										
	-	Individual Condition										
		NOT OBSERVED										
		Carrier										
				•	<u> </u>		Source					
		•	enicle O	wner San	ne as Carrier		VEHICLE-SIC Address	Ε				
02	01	SCOTT CONSTRUCTION USDOT# 221615					E9827 COUN WISCONSIN			, US		
	BUS	GVWR	GVWR Vehicle Configuration						-	argo Body Type		
UNIT	Bl	MORE THAN 26,00 US DOT #	00 LB	SINGLE Carrier Ty	•	,				GRAIN/CHIPS/GRAVEL		
	CK	221615		INTRAST	TATE CARRIER	l				NOT APPLICABLE		
	TRUCK	OS/OW Load	WI Permit	Number			itted Vehicle On Escort Vehicle Required rmitted Route By Permit			ermit	Escort Vehicle Present	
		Measured Height		Measu	red Length		Measured Width	ו		Measured Weight		
		ness		•			• 					
01		PHANIE CHAVEZ					LLOWREET				Date of Birth	
WITN ESS	(608	8) 393-0336				WEST	BARABOO, WI	53913 , US	5			
≶й												

24-06370

# WISCONSIN MOTOR VEHICLE CRASH REPORT

	Witness									
WITN 02 ESS 02	Individual TADD J OWENS (608) 617-5460	Address 206 VICTORIA CT BARNEVELD, WI 53507 , US	Date of Birth 02/29/1968							