

6TL0D2XVS7  
24-09976

WISCONSIN MOTOR VEHICLE  
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT  
1300 LANGE COURT  
BARABOO, WI 53913  
(608) 356-4895

6TL0D2XVS7

Document Number Override		Primary Crash Document #		Agency Crash Number <b>24-09976</b>		Investigating Officer/Deputy <b>DEPUTY B. GOODREAU</b>	
Crash Date <b>09/06/2024</b>		Crash Time <b>07:00 PM</b>		Date Arrived <b>09/06/2024</b>		Time Arrived <b>07:26 PM</b>	
Date Notified <b>09/06/2024</b>		Time Notified <b>07:00 PM</b>		Total Units <b>02</b>		Total Injured <b>00</b>	Total Killed <b>00</b>
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure	<input checked="" type="checkbox"/> Work Zone		<input type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold	
<input type="checkbox"/> Government Property		<input type="checkbox"/> Active School Zone		School Bus Related <b>NO</b>		Tags	
<input checked="" type="checkbox"/> Reportable		Crash Type <b>DT4000 (STANDARD CRASH)</b>		<input type="checkbox"/> Amended		<input type="checkbox"/> Secondary Crash	

Description

<p>Diagram</p> <p>Objects and items not scale. Approx sequence of events. BG9113</p> <p>Hickory Rd</p> <p>Hwy 23</p>	Reconstruction By
	Photos By
	Additional Information <b>NONE</b>

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

UNIT 1 WAS TRAVELING SB ON HWY 23, AND WAS ATTEMPTING TO TURN EB ONTO HICKORY RD. UNIT 1 STATED ROAD WORKERS ALLOWED HER TO PASS BETWEEN THEIR DUMP TRUCK AND ROAD SIGN. UNIT 1 BELIEVED THAT SHE HAD ENOUGH ROOM TO PASS THROUGH, BUT STRUCK THE FRONT BUMPER OF THE DUMP TRUCK. BG9113.

6TL0D2XVS7  
24-09976

WISCONSIN MOTOR VEHICLE  
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT  
1300 LANGE COURT  
BARABOO, WI 53913  
(608) 356-4895

Location

ON HICKORY RD 163 FT E OF STH23 EB IN THE TOWN OF FRANKLIN IN SAUK COUNTY	Latitude <b>43.33294732</b>	Longitude <b>-90.0611218</b>
	X Coordinate <b>251837.390625</b>	Y Coordinate <b>4802340.5</b>
	Structure Type <b>NO STRUCTURE</b>	

Crash Scene

First Harmful Event <b>PARKED MOTOR VEHICLE</b>		First Harmful Event Location <b>ON ROADWAY</b>	
Manner of Collision <b>03 - FRONT TO REAR</b>		Light Condition <b>DUSK</b>	
Road Surface Condition(s) <b>DRY</b>		Roadway Factor(s)  <b>NONE</b>	
Environment Factor(s) <b>NONE</b>			
Weather Condition(s) <b>CLEAR</b>			
Animal Type		Relation To Trafficway <b>TRAFFICWAY - ON ROAD</b>	
Crash Classification - Location <b>PUBLIC PROPERTY</b>		Crash Classification - Jurisdiction <b>NO SPECIAL JURISDICTION</b>	
Tribal Land		Access Control <b>NO CONTROL</b>	Special Study
Within Interchange Area <b>YES</b>	Junction Location <b>INTERSECTION</b>	Intersection Type <b>T-INTERSECTION</b>	
Work Zone Crash Location <b>ACTIVITY AREA</b>		Work Zone Crash Type <b>WORK ON SHOULDER OR MEDIAN</b>	
Workers Present <b>YES</b>		Law Enforcement Present <b>NO</b>	
Work Zone Speed Limit <b>55</b>	Advisory/Regulatory Speed Limit <b>ADVISORY</b>	Normal Posted Speed Limit <b>55</b>	

Unit Summary

UNIT	Unit Status <b>IN TRANSIT</b>		Vehicle Operating As Classification <b>D CLASS</b>		Unit Type <b>TRUCK</b>		
	Vehicle Type <b>UTILITY TRUCK/PICKUP TRUCK</b>				Operating As Endorsements		
	Total Occs <b>1</b>	Train/Bus # Recorded	Total # Citations Issued <b>0</b>	Total Trailers <b>0</b>	Total HazMat Types <b>0</b>		
	Insurance? <b>YES</b>	Direction Of Travel <b>EASTBOUND</b>	<input type="checkbox"/> Pre Crash <input type="checkbox"/> Tire Mark	Speed Limit <b>55</b>	Total Lanes <b>2</b>		
	Most Harmful Event: Collision With <b>PARKED MOTOR VEHICLE</b>		Special Function <b>NO SPECIAL FUNCTION</b>		Emergency Motor Vehicle Use <b>NOT APPLICABLE</b>		
	Traffic Way <b>TWO-WAY, NOT DIVIDED</b>		Traffic Control <b>NO CONTROL</b>		Traffic Control Inoperative/Missing <b>NO</b>		
	Surface Type <b>BLACKTOP (BITUMINOUS)</b>		Road Curvature <b>STRAIGHT</b>		Road Grade <b>LEVEL</b>		
	Truck Bus or HazMat <b>NO</b>						
	<b>Vehicle</b>						
	01	License Plate Number <b>VE9907</b>		Plate Type <b>LTK - LIGHT TRUCK</b>	St <b>WI</b>	Country of Issuance <b>UNITED STATES</b>	
Vehicle Identification Number <b>1GCPTCEK3R1224498</b>		Make <b>CHEVROLET</b>	Year <b>2024</b>	Model <b>COLORADO</b>			

6TL0D2XVS7  
24-09976

WISCONSIN MOTOR VEHICLE  
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT  
1300 LANGE COURT  
BARABOO, WI 53913  
(608) 356-4895

UNIT VEHICLE	Color <b>GRY - GRAY</b>	Body Style <b>PK - PICKUP</b>	Bus Use	
	Initial Contact Point <b>04 - RIGHT SIDE REAR</b>	Vehicle Damage		
	Extent Of Damage <b>FUNCTIONAL DAMAGE</b>	<b>04 - RIGHT SIDE REAR, 05 - RIGHT REAR CORNER</b>		
	Towed Due To Damage <b>NOT TOWED</b>	Vehicle Removed By <b>OWNER</b>		
	What Driver Was Doing <b>GOING STRAIGHT</b>	Vehicle Factors		
UNIT VEHICLE	Driver Prior Action Other	<b>NOT APPLICABLE</b>		
	Driver Actions <b>NO CONTRIBUTING ACTION</b>			
	Owner Name <b>CLAUDIA SCHELL CAYA</b>	Owner Address <b>206 S DACOTAH ST DODGEVILLE, WI 53533 , US</b>		
	<b>Sequence Of Events</b>			
	Event <b>PARKED MOTOR VEHICLE</b>			
Event				
Event				
Event				
UNIT INDIVIDUAL	<b>Policy Holder</b>			
	Insurance Company <b>WISCONSIN-MUTUAL-INS-CO</b>	Individual <b>CLAUDIA SCHELL CAYA</b>		
	<b>Individual</b>			
	Driver <b>CLAUDIA SCHELL CAYA</b>	Citations Issued <b>0</b>	Sex <b>FEMALE</b>	
		Date of Birth	Race <b>WHITE</b>	
Address <b>206 S DACOTAH ST DODGEVILLE, WI 53533 , US</b>	Driver License Number			
UNIT INDIVIDUAL	<b>Safety Equipment</b>			
	On Duty Crash	Safety Equipment <b>SHOULDER &amp; LAP BELT</b>		
	Row <b>01 - FRONT ROW</b>	Seat Position <b>07 - LEFT</b>		
	Helmet Use	Helmet Compliance		
	Eye Protection	Tint Compliance		
UNIT INDIVIDUAL	<b>Injury</b>			
	Injury Severity <b>NO APPARENT INJURY</b>	Airbag <b>NON DEPLOYED</b>		
	Ejected <b>NOT EJECTED</b>	Ejection Path <b>NOT EJECTED/NOT APPLICABLE</b>	Trapped/Extricated <b>NOT TRAPPED</b>	
	Medical Transport <b>NOT TRANSPORTED</b>	EMS Agency Identifier	EMS Run #	



6TL0D2XVS7  
24-09976

WISCONSIN MOTOR VEHICLE  
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT  
1300 LANGE COURT  
BARABOO, WI 53913  
(608) 356-4895

UNIT	VEHICLE	Initial Contact Point <b>11 - LEFT FRONT CORNER</b>	Vehicle Damage <b>11 - LEFT FRONT CORNER</b>	
		Extent Of Damage <b>MINOR DAMAGE</b>		
UNIT	VEHICLE	Towed Due To Damage <b>NOT TOWED</b>	Vehicle Removed By <b>OPERATOR</b>	
		What Driver Was Doing <b>LEGALLY PARKED</b>	Vehicle Factors	
		Driver Prior Action Other	<b>NOT APPLICABLE</b>	
		Driver Actions <b>NO CONTRIBUTING ACTION</b>		
02	02	Owner Name <b>FLEET TRANSPORTATION LLC</b>	Owner Address <b>920 10TH AVE N ONALASKA, WI 54650 , US</b>	
<b>Sequence Of Events</b>				
	01	Event <b>MOTOR VEH IN TRANSPORT</b>		
	02	Event		
	03	Event		
	04	Event		
UNIT	<b>Policy Holder</b>			
	Insurance Company <b>WISCONSIN-MUTUAL-INS-CO</b>	Organization/Company <b>FLEET TRANSPORTATION LLC</b>		