24-10934

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	Document Number Override	Primary Crash Document # Crash Time 08:00 AM		24-10934 DEPUT Date Arrived Time Arriv			Investigating Officer/Deputy DEPUTY D. KROLIKOWSKI Time Arrived 08:15 AM		
87	Crash Date 09/30/2024								
6TL0F1BQ87	Date Notified 09/30/2024	Time Notified 08:04 AM		Total U 02	nits	Total Injured	Total Kill 00	ed	
Ĵ.	On Emergency	it and Run		ure Work Zone		Trailer	or Towed	Reporting Threshold	
6TL	Government Property	Active Schoo	1.7	School NO	Bus Related	Tags		•	
-	✓ Reportable	Crash Type PRIVATE PROPE	RTY/PARKIN	IG LOT	г	Ameno	ed	Secondary Crash	
	Description								
			s t					ROLIKOWSKI	
	↓ I, a sworn law enforceme	Google	at I have not	addec	any CJIS data in t	his report.			
	UNITS 2 WAS DRIVING SOUTH IN 2 AS UNIT 1 WAS TURNING RIGHT	PARKING LOT WHEN	UNIT 1 APPROA	CHED F	ROM THE WEST, DRIV	NG EAST BOUND	WHEN UNIT 1	STRUCK THE SIDE OF UNIT	

24-10934

WISCONSIN MOTOR VEHICLE **CRASH REPORT**

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	Loc	ation								
	-	RKING LOT				Latitude			Longitu	de
	DEC	CORAH RD LOT S284	5			43.54103	85218		•	1089596
	(HO	USE/BUILDING S284	5)			X Coordina	ate		Y Coord	linate
						276928.2			482460	
		THE TOWN OF DELTO	N			Structure ⁻				
	IN S	SAUK COUNTY		HOUSE/	21	2				
				HOUGE	BOILDIN					
	Cra	sh Scene								
	First	: Harmful Event				First Harm	ful Event L	ocation		
	MO	TOR VEH IN TRANSP	ORT			IN PARK	ING LAN	E OR ZONE		
	Man	ner of Collision				Light Cond	dition			
	01 -	ANGLE				DAYLIG	ΗΤ			
	Roa	d Surface Condition(s)				Roadway	Factor(s)			
	DR	Y								
	Envi	ronment Factor(s)								
	NOI	NE				NONE				
	Wea	ther Condition(s)								
	CLE	EAR								
	Anin	nal Type				Relation T	o Trafficwa	ıy		
						NON TR	AFFICWA	Y - PARKIN	G LOT	
	Cras	sh Classification - Location)			Crash Clas	ssification -	Jurisdiction		
		VATE PROPERTY				PRIVATE	E PROPE	RTY		
	Triba	al Land				Access Co				Special Study
						NO CONTROL				
	With NO	in Interchange Area	Junction Location NON-JUNCTION			tion Type N INTERSECTION				
					_					
		t Summary	I				-	-		
	Unit	Status			erating As Cl		-	Unit Type		
	Unit IN T	Status RANSIT		Vehicle Op D CLASS			-	AUTOMO		
	Unit IN T Vehi	Status RANSIT icle Type					-			ments
01	Unit IN T Vehi PAS	Status RANSIT icle Type SSENGER CAR		D CLASS	1	assification	_	AUTOMOE Operating A	s Endorse	
	Unit IN T Vehi PAS	Status RANSIT icle Type	Train/Bus # Recorded	D CLASS		assification	Total Trai	AUTOMOE Operating A	s Endorse Total Haz	ments zMat Types
	Unit IN T Vehi PAS Tota 1	Status TRANSIT icle Type SSENGER CAR Il Occs		D CLASS	1	assification	Total Trai 0	AUTOMOE Operating A lers	s Endorse Total Haz 0	zMat Types
	Unit IN T Vehi PAS Tota 1 Insu	Status FRANSIT icle Type SSENGER CAR Il Occs rance?	Direction Of Travel	D CLASS Total # Cita 0	1	assification	Total Trai 0 Speed Lir	AUTOMOE Operating A lers	s Endorse Total Haz 0 Total Lan	zMat Types
01	Unit IN T Vehi PAS Tota 1	Status FRANSIT icle Type SSENGER CAR Il Occs rance?		D CLASS	ations Issued CrashTire Mark	assification	Total Trai 0	AUTOMOE Operating A lers mit	s Endorse Total Haz 0 Total Lan 1	zMat Types es
01	Unit IN T Vehi PAS Tota 1 Insu YES	Status RANSIT icle Type SSENGER CAR I Occs rance? S t Harmful Event: Collision	Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark notion	assification	Total Trai 0 Speed Lir	AUTOMOE Operating A lers mit Emergency	s Endorse Total Haz 0 Total Lan 1 Motor Veh	zMat Types es icle Use
	Unit IN T Vehi PAS Tota 1 Insu YES Mos MO	Status RANSIT icle Type SSENGER CAR il Occs rance? S t Harmful Event: Collision TOR VEH IN TRANSP	Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark Inction CIAL FUNC	assification	Total Trai 0 Speed Lir	AUTOMOB Operating A lers mit Emergency NOT APPI	s Endorse Total Haz 0 Total Lan 1 Motor Veh LICABLE	Mat Types les icle Use
01	Unit IN T Vehi PAS Tota 1 Insu YES Mos Traff	Status RANSIT icle Type SSENGER CAR il Occs rance? S t Harmful Event: Collision TOR VEH IN TRANSP fic Way	Direction Of Travel EASTBOUND With ORT	D CLASS	tions Issued CrashTire Mark netion CIAL FUNC	assification	Total Trai 0 Speed Lir	AUTOMOB Operating A lers mit Emergency NOT APPL Traffic Contr	s Endorse Total Haz 0 Total Lan 1 Motor Veh LICABLE	Mat Types les icle Use
01	Unit IN T Vehi PAS Tota 1 Insu YES MOS Traff	Status FRANSIT icle Type SSENGER CAR il Occs rance? S t Harmful Event: Collision TOR VEH IN TRANSP fic Way RKING LOT OR PRIVA	Direction Of Travel EASTBOUND With ORT	D CLASS	CrashTire Mark notion CIAL FUNC trol FROL	assification	Total Trai 0 Speed Lir	AUTOMOB Operating A lers mit Emergency NOT APPI Traffic Contr NO	s Endorse Total Haz 0 Total Lan 1 Motor Veh ICABLE ol Inopera	Mat Types les icle Use
01	Unit IN T Vehi PAS Tota 1 Insu YES MOS Traff PAR Surf	Status FRANSIT icle Type SSENGER CAR I Occs rance? S t Harmful Event: Collision TOR VEH IN TRANSP fic Way RKING LOT OR PRIVA ace Type	Direction Of Travel EASTBOUND With ORT TE PROPERTY	D CLASS	ations Issued CrashTire Mark notion CIAL FUNC trol FROL ature	assification	Total Trai 0 Speed Lir	AUTOMOB Operating A lers mit Emergency NOT APPI Traffic Contr NO Road Grade	s Endorse Total Haz 0 Total Lan 1 Motor Veh ICABLE ol Inopera	Mat Types les icle Use
01	Unit IN T Vehi PAS Tota 1 Insu YES MOS Traff PAF Surf: BLA	Status TRANSIT icle Type SSENGER CAR il Occs rance? S t Harmful Event: Collision TOR VEH IN TRANSP fic Way RKING LOT OR PRIVA ace Type ACKTOP (BITUMINOU	Direction Of Travel EASTBOUND With ORT TE PROPERTY	D CLASS	ations Issued CrashTire Mark notion CIAL FUNC trol FROL ature	assification	Total Trai 0 Speed Lir	AUTOMOB Operating A lers mit Emergency NOT APPI Traffic Contr NO	s Endorse Total Haz 0 Total Lan 1 Motor Veh ICABLE ol Inopera	Mat Types les icle Use
01	Unit IN T Vehi PAS Tota 1 Insu YES MOS Traff PAF Surf: BLA	Status TRANSIT icle Type SSENGER CAR il Occs rance? S t Harmful Event: Collision TOR VEH IN TRANSP fic Way RKING LOT OR PRIVA ace Type ACKTOP (BITUMINOU ik Bus or HazMat	Direction Of Travel EASTBOUND With ORT TE PROPERTY	D CLASS	ations Issued CrashTire Mark notion CIAL FUNC trol FROL ature	assification	Total Trai 0 Speed Lir	AUTOMOB Operating A lers mit Emergency NOT APPI Traffic Contr NO Road Grade	s Endorse Total Haz 0 Total Lan 1 Motor Veh ICABLE ol Inopera	Mat Types les icle Use
01	Unit IN T Vehi PAS Tota 1 Insuu YES MOS Traff BLA Truc NO	Status TRANSIT icle Type SSENGER CAR il Occs rance? S t Harmful Event: Collision TOR VEH IN TRANSP fic Way RKING LOT OR PRIVA ace Type ACKTOP (BITUMINOU ik Bus or HazMat	Direction Of Travel EASTBOUND With ORT TE PROPERTY	D CLASS	ations Issued CrashTire Mark notion CIAL FUNC trol FROL ature	assification	Total Trai 0 Speed Lir	AUTOMOB Operating A lers mit Emergency NOT APPI Traffic Contr NO Road Grade	s Endorse Total Haz 0 Total Lan 1 Motor Veh ICABLE ol Inopera	Mat Types les icle Use
01	Unit IN T Vehi PAS Tota 1 Insuu YES MOS Traff BLA Truc NO	Status TRANSIT Icle Type SSENGER CAR I Occs rance? S t Harmful Event: Collision TOR VEH IN TRANSP fic Way RKING LOT OR PRIVA ace Type ACKTOP (BITUMINOU Ik Bus or HazMat	Direction Of Travel EASTBOUND With ORT TE PROPERTY	D CLASS	CrashTire Mark notion CIAL FUNC trol FROL ature	TION	Total Trai 0 Speed Lir N/A	AUTOMOB Operating A lers mit Emergency NOT APPI Traffic Contr NO Road Grade	s Endorse Total Haz 0 Total Lan 1 Motor Veh ICABLE ol Inopera	Mat Types les icle Use
01	Unit IN T Vehi PAS Tota 1 Insuu YES MOS Traff BLA Truc NO	Status TRANSIT icle Type SSENGER CAR il Occs rance? S t Harmful Event: Collision TOR VEH IN TRANSP fic Way RKING LOT OR PRIVA ace Type ACKTOP (BITUMINOU ik Bus or HazMat Vehicle License Plate Number 424TCA	Direction Of Travel EASTBOUND With ORT ITE PROPERTY S)	D CLASS	tions Issued CrashTire Mark nction CIAL FUNC trol TROL ature IT	TION	Total Trai 0 Speed Lir N/A	AUTOMOE Operating A lers mit Emergency NOT APPI Traffic Contr NO Road Grade LEVEL	s Endorse Total Haz 0 Total Lan 1 Motor Veh ICABLE ol Inopera	Mat Types les icle Use
UNIT 01	Unit IN T Vehi PAS Tota 1 Insu YES MOS Traff PAF Suff BL/ Truc NO	Status TRANSIT icle Type SSENGER CAR il Occs rance? S t Harmful Event: Collision TOR VEH IN TRANSP fic Way RKING LOT OR PRIVA ace Type ACKTOP (BITUMINOU ik Bus or HazMat Vehicle License Plate Number 424TCA Vehicle Identification Num	Direction Of Travel EASTBOUND With ORT TE PROPERTY S)	D CLASS	ations Issued CrashTire Mark Inction CIAL FUNC trol TROL ature IT	TION	Total Trai 0 Speed Lir N/A St WI Year	AUTOMOE Operating A lers mit Emergency NOT APPL Traffic Contr NO Road Grade LEVEL	s Endorse Total Haz 0 Total Lan 1 Motor Veh ICABLE ol Inopera	Mat Types les icle Use
01	Unit IN T Vehi PAS Tota 1 Insuu YES MOS Traff BLA Truc NO	Status TRANSIT icle Type SSENGER CAR il Occs rance? S t Harmful Event: Collision TOR VEH IN TRANSP fic Way RKING LOT OR PRIVA ace Type ACKTOP (BITUMINOU Ik Bus or HazMat Vehicle License Plate Number 424TCA Vehicle Identification Nuu 1VWCM7A34CC0121	Direction Of Travel EASTBOUND With ORT TE PROPERTY S)	D CLASS	ations Issued CrashTire Mark Inction CIAL FUNC trol TROL ature IT JTOMOBIL	TION	Total Trai 0 Speed Lir N/A	AUTOMOE Operating A Iers mit Emergency NOT APPI Traffic Contr NO Road Grade LEVEL	s Endorse Total Haz 0 Total Lan 1 Motor Veh ICABLE ol Inopera	Mat Types les icle Use
UNIT 01	Unit IN T Vehi PAS Tota 1 Insu YES MOS Traff PAF Suff BL/ Truc NO	Status Status Status RANSIT Color Status RANSIT Color Status Stat	Direction Of Travel EASTBOUND With ORT TE PROPERTY S)	D CLASS	ations Issued CrashTire Mark Inction CIAL FUNC trol TROL ature IT JTOMOBIL VAGEN 2	TION	Total Trai 0 Speed Lir N/A St WI Year	AUTOMOE Operating A lers mit Emergency NOT APPL Traffic Contr NO Road Grade LEVEL	s Endorse Total Haz 0 Total Lan 1 Motor Veh ICABLE ol Inopera	Mat Types les icle Use
UNIT 01	Unit IN T Vehi PAS Tota 1 Insu YES MOS Traff PAR Surfa Truc NO	Status Status Status RANSIT Color RED - RED Status	Direction Of Travel EASTBOUND With ORT TE PROPERTY S)	D CLASS	Ations Issued CrashTire Mark Inction CIAL FUNC Trol FROL ature IT JTOMOBIL S VAGEN	TION	Total Trai 0 Speed Lir N/A St WI Year	AUTOMOE Operating A Iers mit Emergency NOT APPI Traffic Contr NO Road Grade LEVEL	s Endorse Total Haz 0 Total Lan 1 Motor Veh ICABLE ol Inopera	Mat Types les icle Use
01 UNIT 01	Unit IN T Vehi PAS Tota 1 Insu MOS Traff PAF Surfa BL/ Trucc	Status Status Status RANSIT Color Co	Direction Of Travel EASTBOUND With ORT ITE PROPERTY S) mber 154	D CLASS	Ations Issued CrashTire Mark Inction CIAL FUNC Trol FROL ature IT JTOMOBIL S VAGEN	TION	Total Trai 0 Speed Lir N/A St WI Year	AUTOMOE Operating A Iers mit Emergency NOT APPI Traffic Contr NO Road Grade LEVEL	s Endorse Total Haz 0 Total Lan 1 Motor Veh ICABLE ol Inopera	Mat Types les icle Use
UNIT 01	Unit IN T Vehi PAS Tota 1 Insu YES MOS Traff PAR Surfa Truc NO	Status Status Status RANSIT Color RED - RED Status	Direction Of Travel EASTBOUND With ORT ITE PROPERTY S) mber 154	D CLASS	Ations Issued CrashTire Mark Inction CIAL FUNC Trol FROL ature IT JTOMOBIL S VAGEN	TION	Total Trai 0 Speed Lir N/A St WI Year	AUTOMOE Operating A Iers mit Emergency NOT APPI Traffic Contr NO Road Grade LEVEL	s Endorse Total Haz 0 Total Lan 1 Motor Veh ICABLE ol Inopera	Mat Types ies icle Use tive/Missing

24-10934

WISCONSIN MOTOR VEHICLE CRASH REPORT

		Towed Due To Damage NOT TOWED		Vel	nicle Removed By			
		What Driver Was Doing OTHER		Vel	nicle Factors			
		Driver Prior Action Other		NC	T APPLICABLE			
		NAVIGATING PARKING LO	Т					
UNIT	VEHICLE	Driver Actions UNKNOWN						
		Owner Name CHRISTIE BECKER			Owner Address W6915 WELCH F			
01	01	(608) 547-8708			NEW LISBON, W			
		Sequence Of Events						
	01	MOTOR VEH IN TRANSPOR	RT					
	02	Event						
	03	Event						
	04	Event						
⊢	I	Policy Holder						
UNIT		Insurance Company			ndividual	P		
		PROGRESSIVE-CASUALTY-INS-CO			CHRISTIE BECKE	ĸ		
		Individual Driver			Citations Issued	Sex		
	_	CHRISTIE BECKER		0 FEMALE				
⊢	INDIVIDUAL	(608) 547-8708		Date of Birth Race WHITE				
UNIT		Address W6915 WELCH PRAIRIE RD		Driver License Number				
	IN	NEW LISBON, WI 53950 , U		:	STATE: WISCONSIN COUNTRY: UNITED STATES			
	Saf	On Duty C Tety Equipment	rash	ę	Safety Equipment			
		Row 01 - FRONT ROW	Seat Position 07 - LEFT		SHOULDER & LAF	PBELT		
		Helmet Use		Helmet Compliance				
		Eye Protection		Tint Compliance				
0	001	Injury Severity NO APPARENT INJURY		Airbag				
•	0		jection Path		NON DEPLOYED		Trapped/Extricated	
			PLIC	ABLE		NOT TRAPPED		
		Medical Transport		I	EMS Agency Identifie	r	EMS Run #	
		NOT TRANSPORTED		,			Time of Death	
		Hospital	D _0		Date of Death		Time of Death	
		Distracted By NOT APP	By Source PLICABLE (NOT DISTR	RACT	ED)			
		Distracted By Action NOT DISTRACTED						

24-10934

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Non Motorist	Striking Unit #	Location					
		Prior Action							
		Action							
	Ļ								
┝	N								
UNIT	Ę								
_	INDIVIDUAL								
	≤								
		Action Other						To/From School	
			Suspected Alcohol I	Jse	Suspected Drug Use				
		Drug & Alcohol	NO		NO				
		Alcohol Test Given		Alcohol Test Type	9		Alcohol Test Results		
		TEST NOT GIVEN Drug Test Given		Drug Test Type		Drug Test Resul	ts		
		TEST NOT GIVEN				Brug Foot Rood			
2	001	Drug Type							
U	0								
		Individual Condition							
		APPEARED NORM	IAL						
<u> </u>		t Summary Status		V	ehicle Operating As Classi	fication	Unit Type		
	-	IN TRANSIT			CLASS	noution	AUTOMOBILE		
02		icle Type					Operating As Endorsements		
	_	SENGER CAR	Train/Bus # Re	ecorded T	otal # Citations Issued	Total Tra	ilers Total Ha	azMat Types	
	1			0		0	0		
		Insurance? Direction Of Travel		_	Pre CrashTire	Speed Li		nes	
UNIT		YES SOUTHBOUND Most Harmful Event: Collision With			Mark	N/A	Emergency Motor Vehicle Use		
5		MOTOR VEH IN TRANSPORT			O SPECIAL FUNCTIO	N	NOT APPLICABL		
	Traffic Way				raffic Control		Traffic Control Inoperative/Missing		
	PARKING LOT OR PRIVATE PROPERTY Surface Type				IO CONTROL		NO Road Grade		
			DUS)				LEVEL		
	Truc								
	NO								
		Vehicle		Tr	Plate Type	St	Country of Issuance		
		License Plate Number 561UEA				wi	Country of Issuance UNITED STATES		
02	2	Vehicle Identification Number			Make	Year	Model		
0	02				HYUNDAI	2011	SONATA GLS		
		Color BLU - BLUE			Body Style 4D - 4DR		Bus Use		
	щ	Initial Contact Point			Vehicle Damage		<u> </u>	7 8 0 10 11	
UNIT		02 - RIGHT SIDE F	RONT					7 8 9 10 11 6 3 12	
5	VEHICLE	Extent Of Damage FUNCTIONAL DAM	MAGE		02 - RIGHT SIDE FROI	N I		5 4 3 2 1	
	>	Towed Due To Damag		· · · · · · · · · · · · · · · · · · ·	Vehicle Removed By				
		NOT TOWED							

24-10934

WISCONSIN MOTOR VEHICLE CRASH REPORT

		What Driver Was Doing		Vehicl	e Factors				
		GOING STRAIGHT							
		Driver Prior Action Other							
		Driver Actions							
	ш	NO CONTRIBUTING ACTIO							
E	CLI								
UNIT	VEHICLE								
_	K								
		Owner Name EILEEN ROMASANTA			wner Address 004 PROVIDENCE	ST			
02	02	(224) 433-1023			UN PRAIRIE, WI 5				
		Sequence Of Events							
	01	Event MOTOR VEH IN TRANSPOR	RT						
	02	Event							
	03	Event							
	04	Event							
		Policy Holder							
UNIT		Insurance Company		Indi	ividual				
		ALLSTATE-INS-CO		EIL	EEN ROMASANT	A			
	l	Individual							
		Driver EILEEN ROMASANTA (224) 433-1023			Citations Issued Sex 0 FEMALE Date of Birth Race				
	٩L								
Ŀ	INDIVIDUAL	()		Date	e of Birth		OR NATIVE HAWAIIAN OR OTHER PACIFIC ISLAN		
UNIT	N	Address 3004 PROVIDENCE ST		Driver License Number STATE: WISCONSIN COUNTRY: UNITED STATES					
	I	SUN PRAIRIE, WI 53590, U	JS						
	0-1	On Duty C	rash	Safe	ety Equipment				
	Sai	fety Equipment	SHOULDER & LAP BELT						
		Row 01 - FRONT ROW	Seat Position 07 - LEFT	SH	OULDER & LAP E	BELT			
		Helmet Use	U7 - LEFT	Helmet Compliance					
		Eye Protection			Tint Compliance				
03	002	Injury Severity			Airbag				
	õ	Injury NO APP		NO	N DEPLOYED				
		-	jection Path IOT EJECTED/NOT API				Trapped/Extricated NOT TRAPPED		
		Medical Transport		EM	S Agency Identifier		EMS Run #		
		NOT TRANSPORTED							
		Hospital		Date of Death Time of Death					
		Distracted By NOT APP	By Source PLICABLE (NOT DISTR	ACTE)				
		Distracted By Action NOT DISTRACTED							
		Non Motorist	hit # Location						
•									

24-10934

WISCONSIN MOTOR VEHICLE CRASH REPORT

		Prior Action						
		Action						
	Ļ							
⊢	INDIVIDUAL							
UNIT								
2	NDI							
	=							
		Action Other						To/From School
			Suspected Alcohol Us	se	Suspected Drug Use			
	L	Drug & Alcohol			NO			
		Alcohol Test Given		Alcohol Test Type			Alcohol Test Results	
		TEST NOT GIVEN Drug Test Given		Drug Test Type		Drug Test Results	2	
		TEST NOT GIVEN		2.09.000.900		Drug rest results	,	
02	002	Drug Type						
0	õ							
		Individual Condition						
			IAL					
		-						