WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Document Number Override		Primary Crash Document #		Agency Crash Number 24-12794		Investigating Officer/Deputy DEPUTY A. KULAS			
2 F	Crash Date 11/17/2024	Crash Time 05:55 PM Time Notified 05:56 PM		Date Arrived 11/17/2024 Total Units 01		Time Arrived 06:13 PM			
6 I LOC I JN51	Date Notified 11/17/2024					Total Injured Total Kille		Total Killed	ed be
<u>၂၈</u>	On Emergency Hit	and Run	Lane Closu		Work Zone	Trailer	or T	Towed	Reporting Threshold
<u>6</u> 1	Government Property		hool Zone	Schoo NO	l Bus Related	Tags			_
	Reportable	Crash Type DT4000 (STA	NDARD CRASH	l)		Amend	ded		Secondary Crash
	Description Diagram						Red	construction	By
	Diagram		4	7	not to scale		1100	Construction	Бу
)	not to scale		-		
							Pno	otos By	
	/ F= 1	\							
								ditional Infor INE	mation
	/ ()								
	/ 🖳 /								
	\[\	_							
	U_R								
	n								
	<u>-</u> 5	Bi	rchwood rd						
	I, a sworn law enforceme								
	UNIT 1 WAS SB ON BIRCHWOOD F NO DAMAGE OBSERVED.	RD. UNIT 1 FAILEI	O TO NEGOTIATE A	A LEFT H	IAND CURVE. UNIT 1 EN	TERED THE DITC	H AN	D GOT HUN	G UP ON A FALLEN TREE.

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 11/17/2024

Crash Time 05:55 PM

Constitution Cons	Loc	ation —									
OF TROUTRD IN SAUK COUNTY X Conceilante X C	ON BIRCHWOOD RD					Latitude			Longitude		
IN THE TOWN OF DELTON IN SAUK COUNTY A Contrainate 27181.75 Structure Type NO STRUCTURE Crash Scene First Hamful Event Location ON ROADWAY Read Surface Condition(s) O- NO COLLISION W/VEHICLE IN TRANSPORT Read Surface Condition(s) ON ON OCCULSION W/VEHICLE IN TRANSPORT Read Surface Condition(s) CLEAR Animal Type Frovincement Factor(s) NONE Weither Condition(s) CLEAR Animal Type Read Surface Condition(s) Clear Classification - Location NO SPECIAL JURISDICTION NO CONTROL Within Interchange Area Aunction Location NO ACCESS Control Within Interchange Area Aunction Location NO ACCESS Control NO ACCESS TRUCK Vehicle Insurance? Vehicle Insurance? Vehicle Insurance Access Control NO ACCESS Control NO ACCESS CONTROL NO SPECIAL FUNCTION NO ACCESS CONTROL						43.612705186			-89.82	28391313	
IN SAUK COUNTY 27/191.75 8492/46						X Coordinate			Y Coordinate		
No STRUCTURE							75		48327	746	
First Harmful Event Location ON ROADWAY Marmor of Collision 00 - NO COLLISION WIVEHICLE IN TRANSPORT Road Surface Condition(s) DRY Environment Factor(s) NONE Weather Condition(s) CLEAR Animal Type Relation To Trafficway TRAFFICWAY - ON ROAD Crash Classification - Location PUBLIC PROPERTY TRIBIAL TAME NO SPECIAL JURISDICTION NONE Within Interchange Area NO ONTROL Within Interchange Area NO UNILTY TRUCK/PICKUP TRUCK Total Cocs Traffic Country Tribial Land Traffic Country Tribial Event: Collision With TRANSIT D CLASS Security Tribial Traffic Country PESSOUTHBOUND Pre CrashTire Speed Limit Total HarMat Types O											
First Harmful Event Location ON ROADWAY Marmor of Collision 00 - NO COLLISION WIVEHICLE IN TRANSPORT Road Surface Condition(s) DRY Environment Factor(s) NONE Weather Condition(s) CLEAR Animal Type Relation To Trafficway TRAFFICWAY - ON ROAD Crash Classification - Location PUBLIC PROPERTY TRIBIAL TAME NO SPECIAL JURISDICTION NONE Within Interchange Area NO ONTROL Within Interchange Area NO UNILTY TRUCK/PICKUP TRUCK Total Cocs Traffic Country Tribial Land Traffic Country Tribial Event: Collision With TRANSIT D CLASS Security Tribial Traffic Country PESSOUTHBOUND Pre CrashTire Speed Limit Total HarMat Types O	Cra	sh Scene									
Second Process Seco						First Harn	nful Event I	Location			
O - NO COLLISION W/VEHICLE IN TRANSPORT DARK/UNILIT	TRE	E									
Roadway Factor(s) DRY Environment Factor(s) NONE Weather Condition(s) CLEAR Animal Type Relation To Trafficway TRAFFICWAY - ON ROAD Crash Classification - Location PUBLIC PROPERTY Tribal Land Access Control NO SPECIAL JURISDICTION NOS ACCESS CONTROL Within Interchange Area NO NONJUNCTION Interestation Type NOT AN INTERSECTION Unit Status IN TRANSIT D CLASS TRUCK Operating As Endorsements UTILITY TRUCK/PICKUP TRUCK Total Occs TaniPBus # Recorded Total # Citations Issued Total # Citations Issued Total Trailors Total HazMat Types UTILITY TRUCK/PICKUP TRUCK Total Occs Trailor Occs	Man	ner of Collision				Light Con	dition				
DRY Environment Factor(s) NONE Weather Condition(s) CLEAR Animal Type Relation To Trafficway TRAFFICWAY - ON ROAD Crash Classification - Location PUBLIC PROPERTY NO SPECIAL JURISDICTION Tribial Land Access Control NO SPECIAL JURISDICTION NO NOTARIAL Within Interchange Area Junction Location NON, NON, JUNCTION NON, NON, AN INTERSECTION Unit Status IN TRANSIT Vehicle Operating As Classification Unit Type Unit Status IN TRANSIT Vehicle Operating As Classification Unit Type Unit Status IN TRANSIT Vehicle Operating As Classification Unit Type Unit Status IN TRANSIT Vehicle Operating As Classification Unit Type Unit Status IN TRANSIT Vehicle Operating As Classification Unit Type Unit Status IN TRANSIT Vehicle Operating As Classification Unit Type Unit Status IN TRANSIT Vehicle Operating As Classification Unit Type Unit Trailies IN Traili	00 -	NO COLLISION W/VE	EHICLE IN TRANSPORT			DARK/U	NLIT				
Environment Factor(s) NONE Weather Condition(s) CLEAR Animal Type Relation To Trafficway TRAFFICWAY - ON ROAD Crash Classification - Location Crash Classification - Location PUBLIC PROPERTY Tribial Land NO SPECIAL JURISDICTION Access Centrol NO CONTROL Within Interchange Area NO NO_JUNCTION NOT AN INTERSECTION Unit Summary Unit Statius IN TRANSIT D CLASS TRUCK Operating As Classification O Unit Type Unit Statius I Unit Type Operating As Classification O Operating As Endorsements Unit Type Unit Status Unit Type Uni	Road	Surface Condition(s)				Roadway	Factor(s)				
NONE Weather Condition(s)	DRY	,									
NONE Weather Condition(s)	Fnvii	onment Factor(s)				1					
Weather Condition(s) CLEAR						NONE					
CLEAR Animal Type Relation To Trafficway TRAFFICWAY - ON ROAD Crash Classification - Location PUBLIC PROPERTY Tribal Land Access Centrel NO SPECIAL JURISDICTION Tribal Land NO CONTROL Within Interchange Area NO NON-JUNCTION Intersection Type NOT AN INTERSECTION Unit Status IN TRANSIT Unit Status Vehicle Operating As Classification Intersection Type UTILITY TRUCK/PICKUP TRUCK Total Occs Train/Bus # Recorded 1						NONE					
Animal Type Crash Classification - Location PUBLIC PROPERTY Tribal Land Access Control NON SPECIAL JURISDICTION NO SPECIAL JURISDICTION NO CONTROL Within Interchange Area NON NON-JUNCTION Intersection Type NOT AN INTERSECTION Unit Type UTILITY TRUCK/PICKUP TRUCK Total Cocs Trainibus # Recorded 1 total # Citations Issued 1	Wea	ther Condition(s)									
TRAFFICWAY - ON ROAD	CLE	AR									
Crash Classification - Jurisdiction PUBLIC PROPERTY Tribal Land Access Control NO SPECIAL JURISDICTION Special Study Within Interchange Area NO NON-JUNCTION Intersection Type NOT AN INTERSECTION Unit Status IN TRANSIT D CLASS TRUCK Vehicle Type UTILITY TRUCK/PICKUP TRUCK Total Ocs 1 Train/Bus # Recorded 1 O 0 0 0 Insurance? Pre Crash Tire No SPECIAL FUNCTION Direction Of Travel Special Function No SPECIAL Function NO TAPPLICABLE Traffic Way Traffic Control NO Traffic Control NO Traffic Control Intersection Type NO Traffic Control NO Traffic Control Intersection Type NO Traffic Control NO Traffic Control Intersection NO SPECIAL Function NO SPECIAL Function NO Traffic Control Intersection NO Traffic Control Intersection Type NO CONTROL NO Surface Type BLACKTOP (BITUMINOUS) CURYE LEFT LEVEL Truck Bus or Haz/Mat Vehicle Identification Number Intersection Type No Control No Control LEVEL Truck Bus or Haz/Mat Vehicle Identification Number Intersection Type No Control No Surface Type St Country of Issuance URYE LEFT LEVEL Truck Bus or Haz/Mat Vehicle Identification Number Intersection Type No Control No Surface Type St Country of Issuance URYE LEFT LEVEL Truck Bus or Haz/Mat Vehicle Identification Number Intersection Type No Control No Surface Type St Country of Issuance URYE LEFT LEVEL Truck Bus or Haz/Mat No Vehicle Identification Number Intersection Type Nodel Traffic Control No Surface Type St Country of Issuance URYE LEFT LEVEL Truck Bus or Haz/Mat No Vehicle Identification Number Vehicle Identification Number Intersection Type Nodel Truck Bus or Haz/Mat No Vehicle Identification Number Vehicle Identification Number Intersection Type No PK - PICKUP No DAMAGE	Anim	al Type				Relation 1	o Trafficw	ay			
PUBLIC PROPERTY Tribal Land Access Control NO CONTROL Within Interchange Area NO NO-JUNCTION NON-JUNCTION Intersection Type NOT AN INTERSECTION Unit Summary Unit Summary Unit Status IN TRANSIT D CLASS TRUCK Vehicle Type UnitLitry TRUCK/PICKUP TRUCK Total Occs Train/Bus # Recorded Total # Citations Issued Total Trailers Total Lanes Yes SOUTHBOUND Mark J Speed Limit Total Lanes YES SOUTHBOUND Mark Assembly No SPECIAL FUNCTION Unit Type Total Trailers Total HazMat Types Total HazMat Types Traffic Control Trace No SPECIAL FUNCTION No Trail Trailers Total Unit Type Total Trailers Total HazMat Types Total Control Traffic Control Inoperative/Missing No SPECIAL FUNCTION No TAPPLICABLE Traffic Control Inoperative/Missing Traffic Control Inoperative/Missing No CONTROL NO SUrface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat No Vehicle United Identification Number Type St Country of Issuance Type St Country of I						TRAFFIC	CWAY - C	N ROAD			
Tribal Land Access Control NO CONTROL Within Interchange Area Junction Location NO CONTROL Unit Summary Unit Status In TRANSIT Vehicle Operating As Classification Unit Type TRUCK Vehicle Type Operating As Classification Unit Type TRUCK Total Occs Train/Bus # Recorded Total # Citations Issued Total Trailers Total Lanes YES SOUTHBOUND TRIFF TOTAL Haz/Mat Types 1 Direction of Travel YES SOUTHBOUND NO SPECIAL FUNCTION NOT APPLICABLE Traffic Way Traffic Control Traffic Control Traffic Control Traffic Control Track Bus or Haz/Mat NO Vehicle License Plate Number Vefice Identification Number Double Corror SIL - SILVER (ALUMINUM) PK - PICKUP Triffic Control Initial Contact Point Make Vehicle Identification Number Vehicle Identification Number Update Traffic Control Source Style Sil Country of Issuance Vehicle Extent Of Damage Traffic Control Initial Contact Point Traffic Control Source Sil Country of Issuance Traffic Control Source Traffic Control Sil Country of Issuance Traffic Control Sil Silve Bus Use Traffic Control Sil Silve Bus Use Traffic Control Traffic Control Inoperative Model Traffic Control Inoperative Missing Truck Bus or Haz/Mat No Vehicle Unit Type Traffic Control Traffic Control Inoperative Missing Truck Bus or Haz/Mat No Vehicle Identification Number Traffic Control Traffic Co	Cras	h Classification - Location	ı			Crash Cla	ssification	- Jurisdiction			
Within Interchange Area						NO SPE	CIAL JUI	RISDICTION			
Within Interchange Area NO NON-JUNCTION Intersection Type NOT AN INTERSECTION Unit Summary Vehicle Operating As Classification	Triba	ll Land			Access Control					Special Study	
NO							ITROL				
Unit Summary Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP TRUCK Total Occs Train/Bus # Recorded Total # Citations Issued Operating As Endorsements Unit Type Total Trailers Total HazMat Types O Insurance? Direction Of Travel YES SOUTHBOUND Mark Special Function NO SPECIAL FUNCTION TREE Traffic Way Traffic Control Traffic Control TWO-WAY, NOT DIVIDED NO CONTROL Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO Vehicle License Plate Number Vehicle Gentification Number 107HW48K65S158889 DODG Color SiL - SILVER (ALUMINUM) PK - PICKUP Initial Contact Point Make Year Model Type Truck Unit Type Truck Uni		in Interchange Area					OT1011				
Unit Status IN TRANSIT D CLASS TRUCK Vehicle Type UTILITY TRUCK/PICKUP TRUCK Total Occs Train/Bus # Recorded O O O O O O O O O O O O O O O O O O			NON-JUNCTION		NOT AN	INTERSE	CHON				
IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP TRUCK Total Occs 1 Total **Train/Bus*** Recorded** 1 Total **Citations Issued** 0 0 0 0 Insurance? Direction Of Travel YES SOUTHBOUND Mark 45 2 Most Harmful Event: Collision With TREE NO SPECIAL FUNCTION NOT APPLICABLE Traffic Way Traffic Control NO CONTROL NO Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO Vehicle License Plate Number Vefa284 Vehicle Identification Number 107HW48K65S158889 DODG Color SIL - SILVER (ALUMINUM) PK - PICKUP Initial Contact Point 14 - UNDERCARRIAGE Extent Of Damage Description A contact Point Vehicle Damage 10 - NO DAMAGE Total Trailers Operating As Endorsements Total HazMat Types Operating As Endorsements Total HazMat Types Total HazMat Types No and Crash Tire NoT APPLICABLE Traffic Control Inoperative/Missing NO NO Surface Type Road Curvature Road Grade LEVEL LEVEL Truck Bus or HazMat No Vehicle License Plate Number Venice Unitial Control Inoperative/Missing No Vehicle Identification Number Venice DDDG 2005 Bus Use Traffic Control Inoperative/Missing No Vehicle Damage 00 - NO DAMAGE											
Vehicle Type UTILITY TRUCK/PICKUP TRUCK Total Occs Train/Bus # Recorded Total # Citations Issued 0 0 0 0 Insurance? Direction Of Travel Special Function Mark Special Function NO SPECIAL FUNCTION NO SPECIAL FUNCTION Traffic Control Inoperative/Missing TWO-WAY, NOT DIVIDED NO CONTROL Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO Vehicle License Plate Number VF6284 LTK Vehicle Identification Number 10 10 11 12 12 14 14 15 17 18 10 10 10 10 10 10 10 10 10 10 10 10 10				-	-	Classification	1				
UTILITY TRUCK/PICKUP TRUCK Total Occs Train/Bus # Recorded 0 0 1 Total # Citations Issued 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0				D CLASS							
Total Occs Train/Bus # Recorded Total # Citations Issued Total Trailers Total HazMat Types			TRUCK					Operating A	S LIIUUIS	cilicilis	
1				Total # Cita	tions Issued	1	Total Tra	ilers	I Total Ha	azMat Types	
YES SOUTHBOUND Wark 45 2		- 0000					**				
YES	Insu	ance?	Direction Of Travel			Speed Limit		Total Lanes			
TREE Traffic Way Traffic Control Traffic Control NO CONTROL Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO Vehicle License Plate Number VF6284 LTK Vehicle Identification Number 1D7HW48K65S158889 DODG SIL - SILVER (ALUMINUM) PK - PICKUP Initial Contact Point 14 - UNDERCARRIAGE Extent Of Damage NO Traffic Control Traffic Control NO Road Curvature Road Grade LEVEL Road Grade LEVEL Road Grade LEVEL Velevel Road Grade LEVEL Road Grade LEVEL Road Grade LEVEL Velevel VE6284 LTK WI UNITED STATES Make Year Model JODG SIL - SILVER (ALUMINUM) PK - PICKUP Initial Contact Point 14 - UNDERCARRIAGE Extent Of Damage 00 - NO DAMAGE	YES	;	SOUTHBOUND		Fie Grasiffie			2			
Traffic Way Traffic Control NO CONTROL Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO Vehicle License Plate Number VF6284 Vehicle Identification Number 1D7HW48K65S158889 DODG Color SIL - SILVER (ALUMINUM) Initial Contact Point 14 - UNDERCARRIAGE Extent Of Damage Traffic Control NO Traffic Control NO NO NO Road Curvature Road Grade LEVEL St Country of Issuance VI UNITED STATES WI UNITED STATES Bus Use Traffic Control NO NO NO NO St Country of Issuance VI UNITED STATES Will UNITED STATES Wodel Traffic Control NO	Most	Harmful Event: Collision	With		·			0 ,			
TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO Vehicle License Plate Number VF6284 Vehicle Identification Number 1D7HW48K65S158889 DODG Color SIL - SILVER (ALUMINUM) PK - PICKUP Initial Contact Point 14 - UNDERCARRIAGE Extent Of Damage NO CONTROL NO Road Curvature Road Grade LEVEL Road Grade LEVEL Curvy of Issuance UNITED STATES Model Vehicle Identification Number SIL - SILVER (ALUMINUM) PK - PICKUP Vehicle Damage 00 - NO DAMAGE						CTION					
Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO Vehicle License Plate Number VF6284 Vehicle Identification Number 1D7HW48K65S158889 Color SIL - SILVER (ALUMINUM) PK - PICKUP Initial Contact Point 14 - UNDERCARRIAGE Extent Of Damage Road Curvature CURVE LEFT Road Grade LEVEL St		•							rol Inoper	rative/Missing	
BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO Vehicle License Plate Number VF6284 Vehicle Identification Number 1D7HW48K65S158889 Color SIL - SILVER (ALUMINUM) PK - PICKUP Vehicle Damage Output Description Country of Issuance WI UNITED STATES Will UNITED STATES Make Year Model 1D7HW48K65S158889 DODG SIL - SILVER (ALUMINUM) PK - PICKUP Vehicle Damage Output Toutput Tout											
Truck Bus or HazMat NO Vehicle License Plate Number VF6284 Vehicle Identification Number 1D7HW48K65S158889 Color SIL - SILVER (ALUMINUM) PK - PICKUP Initial Contact Point 14 - UNDERCARRIAGE Extent Of Damage Vehicle Plate Type St Country of Issuance WI UNITED STATES Model 100 - NO DAMAGE		• •	e)						=		
Vehicle			3)	CORVEL	EFI	LEVEL					
Vehicle License Plate Number VF6284 Vehicle Identification Number 1D7HW48K65S158889 Color SIL - SILVER (ALUMINUM) PK - PICKUP Initial Contact Point 14 - UNDERCARRIAGE Extent Of Damage Plate Type St Country of Issuance WI UNITED STATES Model 2005 Bus Use FX - PICKUP Output Vehicle Damage Output Vehicle Damage Output Vehicle Damage Output Vehicle Damage Output Vehicle Damage Output Vehicle Damage Output Vehicle Damage Output Vehicle Damage		N Dus of Fluziviat									
License Plate Number VF6284 Vehicle Identification Number 1D7HW48K65S158889 DODG Color SIL - SILVER (ALUMINUM) Initial Contact Point 14 - UNDERCARRIAGE Extent Of Damage Plate Type St. Country of Issuance WI UNITED STATES Model Year Model PK - PICKUP Vehicle Damage 00 - NO DAMAGE		Vohiclo									
VF6284				Plate Type			St	I Country of Is	suance		
Vehicle Identification Number					31						
1D7HW48K65S158889 DODG 2005	Vehicle Identification Number 1D7HW48K65S158889										
SIL - SILVER (ALUMINUM) PK - PICKUP Initial Contact Point 14 - UNDERCARRIAGE Extent Of Damage Ou - NO DAMAGE											
Initial Contact Point 14 - UNDERCARRIAGE Extent Of Damage Vehicle Damage 7 8 9 10 11 6 00 - NO DAMAGE				Body Style				Bus Use			
14 - UNDERCARRIAGE Extent Of Damage 10 - NO DAMAGE		SIL - SILVER (ALUM	INUM)	PK - PIC	KUP						
14 - UNDERCARRIAGE Extent Of Damage 00 - NO DAMAGE	□ Initial Contact Point			Vehicle Da	amage	age				7 8 9 10 11	
Extent Of Damage 00 - NO DAMAGE	☐ 14 - UNDERCARRIAGE				6						
NO DAMAGE	I		00 - NO	00 - NO DAMAGE					5 4 3 2 1		

5

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 11/17/2024

Crash Time 05:55 PM

				Vehicle Removed By					
				OPERATOR Volviele Feeters					
		What Driver Was Doing		Vehicle Factors					
		NEGOTIATING CURVE Driver Prior Action Other		NOT APPLICABLE					
		Driver i noi Action Other							
		Driver Actions							
_	щ	102							
LNO	$\overline{\mathbf{c}}$								
5	VEHICLE								
	>								
		Owner Name		Owner Address					
	_	LANDYNN MILLER		N2692 CASSIDY RD					
	01	(608) 547-7187	MAUSTON, WI 53948 , US						
		Sequence Of Events Event							
	01	TREE							
	02	Event							
	~	Event							
	03	-							
	04	Event							
_	i	Policy Holder							
LNO		Insurance Company AMERICAN-FAMILY-INS-CO	INDIVIDUAL LANDYNN MILLER						
			LANDTHN WILLER						
		Individual DRIVER		Citations Issued	Sex				
		LANDYNN MILLER	0	MALE					
	¥	(608) 547-7187	Date of Birth						
╘	INDIVIDUAL			WHITE					
	2	Address N2692 CASSIDY RD		Driver License Number	Driver License Number				
	Z	MAUSTON, WI 53948, US		STATE: WISCONSIN COUNTRY: UNITED STATES					
	0-1	On Duty Crash		Safety Equipment					
	Sai	fety Equipment							
		Row	Seat Position 07 - LEFT	SHOULDER & LAP	BELT				
		01 - FRONT ROW Helmet Use	107 - LEFT	Helmet Compliance					
		Thomas dec		Tiomet compliance					
		Eye Protection	Tint Compliance						
	_	Injury Sev	eritv	Airbag					
2	90	Injury NO APPARENT INJURY Ejected Ejection Path		NON DEPLOYED					
				-		Trapped/Extricated			
		NOT EJECTED NOT EJECTED/NOT APPI				NOT TRAPPED			
		Medical Transport NOT TRANSPORTED	EMS Agency Identifier EMS Run #		EMS Run #				
		Hospital		Date of Death		Time of Death			
		Dist.	Dy Course						
		Distracted By NOT API	By Source PLICABLE (NOT DISTRA	ACTED)					
		Distracted By Action NOT DISTRACTED							

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 11/17/2024

Crash Time 05:55 PM

		Non Motorist	Striking Unit #	Location				
		Prior Action						
LIND	INDIVIDUAL	Action						
		Action Other						To/From School
	L	Orug & Alcohol	Suspected Alcohol U NO	Jse	Suspected Drug Use NO			
		Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type			Alcohol Test Results	
		Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug Test Results		
2	001	Drug Type		•				
		Individual Condition						
		APPEARED NORM	//AL					