24-13997

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Document Number Override	Primary Crash Doo	cument #	Agency 24-139	Crash Number 97		ating Officer/Deputy TY W. VERTEIN				
Crash Date 12/23/2024	Crash Time 02:10 PM		Date Ar		Time Arrive	d				
Date Notified 12/23/2024	Time Notified 02:15 PM		Total Ur 01	nits	Total Injured	d To	otal Killed 0			
On Emergency Hit	and Run	Lane Closu		Work Zone		r or Tow	ved	Reporting Threshold		
Government Property	Active Scho	ool Zone	School I	Bus Related	Tags					
Reportable	Crash Type DT4000 (STANI	DARD CRASH)		Amend	ded		Secondary Crash		
Description Diagram Reconstruction By										
Non reportable slide off						Additio NONE	onal Inforn	nation		
I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.										
I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report. ON THE DESCRIBED DATE, TIME, AND LOCATION, UNIT 1 WAS TRAVELING WESTBOUND. AS THE OPERATOR WAS ATTEMPTING TO NEGOTIATE A CURVE, HE LOST CONTROL OF UNIT 1 DUE TO SPEED AND SLIPPERY ROAD CONDITIONS. UNIT 1 ENTERED THE NORTHERNMOST DITCH LINE WHERE IT CAME TO REST. NO REPORTED INJURIES.										

24-13997

5

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 12/23/2024

Crash Time 02:10 PM

Loc	ation								
	USH12 WB				Latitude			Longitu	ıde
0.63 MI N						43.639941098		-89.799748661	
OF USH12 WB						X Coordinate		Y Coor	dinate
IN THE TOWN OF DELTON									92.5
IN SAUK COUNTY						Туре			
						UCTURE			
Cra	sh Scene			J					
_	Harmful Event			1	First Harm	nful Event I	contion		
					ROADSI		Location		
DITCH Manner of Collision									
		HICLE IN TRANSPORT			Light Con				
	d Surface Condition(s)	THOLE IN TRANSPORT			Roadway				
	DW, SLUSH					. 4313.(3)			
Envii	ronment Factor(s)								
WE	ATHER CONDITIONS				NONE				
Wea	ther Condition(s)								
SNC	• •								
Anim	nal Type				Relation T	o Trafficw	av		
	71						N ROAD		
Cras	h Classification - Location				Crash Cla	ssification	- Jurisdiction		
PUE	BLIC PROPERTY				NO SPE	CIAL JUI	RISDICTION		
Triba	al Land				Access Control Special Study				Special Study
					NO CONTROL				
With	in Interchange Area	Junction Location		Intersection					
NO		NON-JUNCTION		NOT AN I	INTERSE	CTION			
Unit	t Summary 👅								
	t Summary Status		Vehicle Ope	erating As Cla	assification	l	Unit Type		
Unit IN T	Status RANSIT		Vehicle Ope	_	assification	l	AUTOMO		
Unit IN T Vehi	Status 'RANSIT cle Type			_	assification	1			ements
Unit IN T Vehi	Status RANSIT cle Type SSENGER CAR	L Troin/Rus # Pecerded	D CLASS		assification		AUTOMO Operating A	s Endorse	
Unit IN T Vehi PAS Tota	Status 'RANSIT cle Type	Train/Bus # Recorded	D CLASS	_	assification	Total Tra	AUTOMO Operating A	s Endorse Total Ha	ements zMat Types
Unit IN T Vehic PAS Total 1	Status RANSIT cle Type SSENGER CAR		D CLASS Total # Cita 0	tions Issued	assification	Total Tra	AUTOMO Operating A	s Endorse Total Ha	zMat Types
Unit IN T Vehic PAS Tota 1	Status RANSIT cle Type SSENGER CAR I Occs rance?	Direction Of Travel	Total # Cita 0 Pre	tions Issued	assification	Total Tra 0 Speed Li	AUTOMO Operating A	Total Ha Total Lai	zMat Types
Unit IN T Vehi PAS Tota 1 Insui YES	Status RANSIT cle Type SSENGER CAR I Occs rance?	Direction Of Travel WESTBOUND	Total # Cita 0	tions Issued CrashTire Mark	assification	Total Tra	AUTOMO Operating A	Total Ha O Total Lai	zMat Types nes
Unit IN T Vehi PAS Tota 1 Insui YES	Status RANSIT cle Type SSENGER CAR I Occs rance? B I Harmful Event: Collision V	Direction Of Travel WESTBOUND	Total # Cita 0 Pre Special Fur	tions Issued CrashTire Mark		Total Tra 0 Speed Li	AUTOMO Operating A	Total Ha 0 Total Lan 2 Motor Vel	zMat Types nes nicle Use
Unit IN T Vehi PAS Tota 1 Insui YES Most	Status RANSIT cle Type SSENGER CAR I Occs rance? B I Harmful Event: Collision V	Direction Of Travel WESTBOUND	Total # Cita 0 Pre Special Fur	CrashTire Mark nction		Total Tra 0 Speed Li	AUTOMO Operating A illers mit Emergency NOT APP	Total Ha 0 Total Lan 2 Motor Vel	zMat Types nes nicle Use
Unit IN T Vehi PAS Tota 1 Insui YES Most DITC	Status RANSIT cle Type SSENGER CAR I Occs rance? St Harmful Event: Collision V	Direction Of Travel WESTBOUND	Total # Cita 0 Pre Special Fur NO SPEC	CrashTire Mark nction		Total Tra 0 Speed Li	AUTOMO Operating A illers mit Emergency NOT APP	Total Ha 0 Total Lan 2 Motor Vel	zMat Types nes nicle Use
Unit IN T Vehic PAS Tota 1 Insur YES Most DITC Traff TWC	Status RANSIT cle Type SSENGER CAR I Occs rance? Harmful Event: Collision V CH ic Way D-WAY, NOT DIVIDED ace Type	Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva	CrashTire Mark Inction CIAL FUNCT		Total Tra 0 Speed Li	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade	Total Ha 0 Total Lai 2 Motor Vel LICABLE	zMat Types nes nicle Use
Unit IN T Vehic PAS Tota 1 Insui YES Most DIT(Traff TW(Surfa	Status RANSIT Cle Type SSENGER CAR I Occs Harmful Event: Collision V CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS	Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont	CrashTire Mark Inction CIAL FUNCT		Total Tra 0 Speed Li	AUTOMO Operating A iilers mit Emergency NOT APP Traffic Cont	Total Ha 0 Total Lai 2 Motor Vel LICABLE	zMat Types nes nicle Use
Unit IN T Vehi PAS Tota 1 Insui YES Most DIT(Traff TW(Surfa BLA	Status RANSIT cle Type SSENGER CAR I Occs rance? Harmful Event: Collision V CH ic Way D-WAY, NOT DIVIDED ace Type	Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva	CrashTire Mark Inction CIAL FUNCT		Total Tra 0 Speed Li	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade	Total Ha 0 Total Lai 2 Motor Vel LICABLE	zMat Types nes nicle Use
Unit IN T Vehi PAS Tota 1 Insur YES Most DITC Traff TWC Surfa BLA Truc NO	Status RANSIT Cle Type SSENGER CAR I Occs rance? I Harmful Event: Collision V CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat	Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva	CrashTire Mark Inction CIAL FUNCT		Total Tra 0 Speed Li	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade	Total Ha 0 Total Lai 2 Motor Vel LICABLE	zMat Types nes nicle Use
Unit IN T Vehi PAS Tota 1 Insur YES Most DITC Traff TWC Surfa BLA Truc NO	Status RANSIT Cle Type SSENGER CAR I Occs rance? St Harmful Event: Collision W CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat	Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva CURVE L	CrashTire Mark notion IAL FUNCT trol FROL ature EFT		Total Tra 0 Speed Li 55	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL	Total Ha 0 Total Lai 2 Motor Vel LICABLE rol Inopera	zMat Types nes nicle Use
Unit IN T Vehi PAS Tota 1 Insur YES Most DITC Traff TWC Surfa BLA Truc NO	Status RANSIT cle Type SSENGER CAR I Occs rance? St Harmful Event: Collision V CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number	Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva CURVE L	CrashTire Mark notion IAL FUNCT trol FROL ature EFT		Total Tra 0 Speed Li 55	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL	Total Ha 0 Total Lai 2 Motor Vel LICABLE rol Inopera	zMat Types nes nicle Use
Unit IN T Vehi PAS Tota 1 Insur YES Most DITC Traff TWC Surfa BLA Truc NO	Status RANSIT cle Type SSENGER CAR I Occs rance? St Harmful Event: Collision V CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number AYD2010	Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva CURVE L Plate Type AUT	CrashTire Mark notion IAL FUNCT trol FROL ature EFT		Total Tra 0 Speed Li 55	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED S	Total Ha 0 Total Lai 2 Motor Vel LICABLE rol Inopera	zMat Types nes nicle Use
Unit IN T Vehi PAS Tota 1 Insui YES Most DITC Traff TWC Surfa BLA Truc	Status RANSIT cle Type SSENGER CAR I Occs rance? St Harmful Event: Collision V CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number AYD2010 Vehicle Identification Num	Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva CURVE L Plate Type AUT Make	CrashTire Mark notion IAL FUNCT trol FROL ature EFT		Total Tra 0 Speed Li 55 St WI Year	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED ST	Total Ha 0 Total Lai 2 Motor Vel LICABLE rol Inopera	zMat Types nes nicle Use
Unit IN T Vehi PAS Tota 1 Insur YES Most DITC Traff TWC Surfa BLA Truc NO	Status RANSIT Cle Type SSENGER CAR I Occs rance? I Harmful Event: Collision V CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number AYD2010 Vehicle Identification Num 1G1ZS58F07F153923	Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva CURVE L Plate Type AUT Make CHEV	CrashTire Mark Inction CIAL FUNCT Trol TROL ature EFT		Total Tra 0 Speed Li 55	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED ST Model MALIBU	Total Ha 0 Total Lai 2 Motor Vel LICABLE rol Inopera	zMat Types nes nicle Use
Unit IN T Vehi PAS Tota 1 Insui YES Most DITC Traff TWC Surfa BLA Truc	Status RANSIT Cle Type SSENGER CAR I Occs rance? I Harmful Event: Collision V CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number AYD2010 Vehicle Identification Num 1G1ZS58F07F153923 Color	Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva CURVE L Plate Type AUT Make CHEV Body Style	CrashTire Mark Inction CIAL FUNCT Trol FROL atture EFT		Total Tra 0 Speed Li 55 St WI Year	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED ST	Total Ha 0 Total Lai 2 Motor Vel LICABLE rol Inopera	zMat Types nes nicle Use
Unit IN T Vehic PAS Total 1 Insur YES Most DITC Traff TWC Surfa BLA Truc NO	Status RANSIT Cle Type SSENGER CAR I Occs rance? I Harmful Event: Collision V CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number AYD2010 Vehicle Identification Num 1G1ZS58F07F153923 Color SIL - SILVER (ALUMI	Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva CURVE L Plate Type AUT Make CHEV Body Style SD - SEE	CrashTire Mark Inction CIAL FUNCT Trol TROL ature EFT		Total Tra 0 Speed Li 55 St WI Year	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED ST Model MALIBU	Total Ha 0 Total Lai 2 Motor Vel LICABLE rol Inopera	zMat Types nes nicle Use
Unit IN T Vehic PAS Total 1 Insur YES Most DITC Traff TWC Surfa BLA Truc NO	Status RANSIT Cle Type SSENGER CAR I Occs rance? B t Harmful Event: Collision V CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number AYD2010 Vehicle Identification Num 1G1ZS58F07F153923 Color SIL - SILVER (ALUMI Initial Contact Point	Direction Of Travel WESTBOUND With Solution NUM)	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva CURVE L Plate Type AUT Make CHEV Body Style	CrashTire Mark Inction CIAL FUNCT Trol TROL ature EFT		Total Tra 0 Speed Li 55 St WI Year	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED ST Model MALIBU	Total Ha 0 Total Lai 2 Motor Vel LICABLE rol Inopera	zMat Types nes nicle Use
Unit IN T Vehi PAS Tota 1 Insui YES Most DITC Traff TWC Surfa BLA Truc	Status RANSIT Cle Type SSENGER CAR I Occs rance? I Harmful Event: Collision V CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number AYD2010 Vehicle Identification Num 1G1ZS58F07F153923 Color SIL - SILVER (ALUMI	Direction Of Travel WESTBOUND With Solution NUM)	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva CURVE L Plate Type AUT Make CHEV Body Style SD - SEE Vehicle Da	CrashTire Mark Inction CIAL FUNCT Trol TROL ature EFT		Total Tra 0 Speed Li 55 St WI Year	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED ST Model MALIBU	Total Ha 0 Total Lai 2 Motor Vel LICABLE rol Inopera	zMat Types nes nicle Use E ative/Missing

24-13997

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Towed Due To Damage		Ve	nicle Removed By					
		NOT TOWED		OF	PERATOR					
		What Driver Was Doing		Vehicle Factors						
		NEGOTIATING CURVE	EGOTIATING CURVE							
		Driver Prior Action Other		NOT APPLICABLE						
		Driver Actions								
	Щ	SPEED TOO FAST/COND	, RAN OFF ROADWAY							
╘	VEHICLE									
LNO	王									
	VE									
		Owner Name JESSICA HAUGE			Owner Address 511A GALE CT					
	01	JESSICA HAUGE			WISCONSIN DELL	.S, WI 53965 , U	S			
						,				
		Sequence Of Events								
		Event								
	01	RUN OFF ROADWAY RIG	GHT							
	02	Event DITCH								
	03	Event								
		Event								
	04	Event								
⊨	ı	Policy Holder								
LIND		Insurance Company			INDIVIDUAL					
_		PROGRESSIVE-CLASSIC-INS-CO			JESSICA HAUGE					
		ndividual								
		DRIVER WESLEY HILL			Citations Issued Sex					
	٩L	(608) 547-2417		Date of Birth		MALE				
_	INDIVIDUAL	(666) 647 2411			Date of Birth	Race WHITE				
	Σ	Address 118 E LEMONWEIR ST NEW LISBON, WI 53950 , US			Driver License Number					
_	N				STATE: WISCONSIN COUNTRY: UNITED STATES					
	=				STATE. WISCONSIN COUNTRY. UNITED STATES					
		On Dut	. Oh		26.5					
	Sat	On Duty fety Equipment	y Crasn	;	Safety Equipment					
		Row	Seat Position	SHOULDER & LAP BELT						
		01 - FRONT ROW	07 - LEFT							
		Helmet Use	L		Helmet Compliance					
		Eye Protection			Tint Compliance					
_	Ξ	Injury Severity			Airbag					
2	00	Injury NO AP	Injury NO APPARENT INJURY			NON DEPLOYED				
		Ejection Path					Trapped/Extricated			
		NOT EJECTED NOT EJECTED/NOT APP					NOT TRAPPED			
		Medical Transport NOT TRANSPORTED			EMS Agency Identifier		EMS Run #			
		Hospital		+	Date of Death		Time of Death			
		Distracted By NOT A	ed By Source PPLICABLE (NOT DISTR	RACT	ED)					
		Distracted By Action	,		-					
		NOT DISTRACTED								

Crash Date 12/23/2024
Crash Time 02:10 PM

24-13997

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 12/23/2024

Crash Time 02:10 PM

		Non Motorist Striking Unit #	Location				
		Prior Action					
		Action					
	AL						
LIND	INDIVIDUAL						
5	DIV						
	Z						
		A 11 - O11					1 = 0
		Action Other					To/From School
	L	Drug & Alcohol NO	Use	Suspected Drug Use NO			
		Alcohol Test Given	Alcohol Test Type)		Alcohol Test Results	
		TEST NOT GIVEN	Drug Toot Time		To + . D =		
		Drug Test Given TEST NOT GIVEN	Drug Test Type		Drug Test Results	•	
2	001	Drug Type					
	0						
		Individual Condition					
		APPEARED NORMAL					