# **6TL0DKRB2L** 25-01419

## WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Document Number Override	e Primary Crash		Agency Crash Number 25-01419  Date Arrived 02/14/2025		DEPUTY R. BARNES			
Crash Date 02/14/2025	Crash Time 05:53 PM				Time Arrived 06:06 PM			
Date Notified 02/14/2025	Time Notified 05:53 PM	T 0	otal Units		Total Injured	Total Kille	d	
On Emergency	Hit and Run	Lane Closure		Zone	Trailer or	l	Reporting Threshold	
Government Property	Active Se	shool Zana	chool Bus Related	I	Tags			
✓ Reportable	Crash Type DT4000 (STA	ANDARD CRASH)			Amended		Secondary Crash	
escription =				l.			1	
Diagram	Diagram by: F On 02/14/202 Not to Scale					construction	Б	
					Ad	ditional Info	rmation	
	Gavin Rd		Gavin F					
🗸 I, a sworn law enfo								

Wisconsin Motor Vehicle Crash Form DT4000

This report does not include any CJIS data.

1 of 4

Crash Date 02/14/2025
Crash Time 05:53 PM

# **6TL0DKRB2L** 25-01419

### WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Ī	629	GAVIN RD FT E			Latitude <b>43.61955</b>	5608		Longitude -89.987118602		
	IN T	CTHK THE TOWN OF WINFIEL SAUK COUNTY	LD		X Coordin 258980.0			Y Coordinate 4833955.5		
	IIV S	SAUK COUNTY			Structure Type					
1	Cra	sh Scene								
1		Harmful Event			First Harm	nful Event I	ocation			
	DIT				ROADSI		-coation			
ł	Man	ner of Collision		Light Condition						
	00 -	NO COLLISION W/VEI	HICLE IN TRANSPORT		DARK/UNLIT					
ł	Roa	d Surface Condition(s)			Roadway Factor(s)					
	SNO	` '				,				
	Envi	ronment Factor(s)	_							
	WE	ATHER CONDITIONS			NONE					
Ì		ther Condition(s)			1					
	SNO									
	Anim	nal Type			Relation To Trafficwa TRAFFICWAY - N			•		
Î		sh Classification - Location BLIC PROPERTY			Crash Classification - Jurisdiction NO SPECIAL JURISDICTION					
ł		al Land			Access Co			Special Study		
					NO CONTROL			., ,		
•		3.	Junction Location		Intersection Type			<u>.</u>		
l	NO		NON-JUNCTION	NOT AN	INTERSE	CTION				
		t Summary ===								
				Vahicle Operating As C	laccification	1	Unit Type			
		Status TRANSIT		Vehicle Operating As C D CLASS	Classification	1	Unit Type AUTOMOE	BILE		
_	IN T				Classification	1	AUTOMOE	BILE s Endorsements		
01	IN T	RANSIT	E		Classification		AUTOMOE			
01	Vehi	TRANSIT cle Type	E Train/Bus # Recorded			Total Tra	AUTOMOE Operating As			
04	Vehi	RANSIT cle Type ORT) UTILITY VEHICLI		D CLASS			AUTOMOE Operating As	s Endorsements  Total HazMat Types  0		
01	Vehi (SP Tota 1	RANSIT cle Type ORT) UTILITY VEHICLI	Train/Bus # Recorded  Direction Of Travel	D CLASS  Total # Citations Issued	d	Total Tra  0 Speed Li	AUTOMOE Operating As	Total HazMat Types  O  Total Lanes		
	Vehi (SP) Tota 1 Insu	RANSIT cle Type ORT) UTILITY VEHICLI I Occs rance?	Train/Bus # Recorded  Direction Of Travel  WESTBOUND	Total # Citations Issued  1  Pre CrashTire Mark	d	Total Tra	AUTOMOE Operating As illers	Total HazMat Types  O  Total Lanes 2		
UNIT 01	Vehi (SP) Tota 1 Insu	RANSIT cle Type ORT) UTILITY VEHICLI I Occs rance? t Harmful Event: Collision W	Train/Bus # Recorded  Direction Of Travel  WESTBOUND	Total # Citations Issued  Pre CrashTire	d e	Total Tra  0 Speed Li	AUTOMOE Operating As illers	s Endorsements  Total HazMat Types  Total Lanes  Motor Vehicle Use		
	IN T Vehi (SP) Tota 1 Insui NO Most DIT(	RANSIT cle Type ORT) UTILITY VEHICLI I Occs rance? t Harmful Event: Collision W CH	Train/Bus # Recorded  Direction Of Travel  WESTBOUND	Total # Citations Issued  1  Pre CrashTire Mark  Special Function	d e	Total Tra  0 Speed Li	AUTOMOE Operating As illers mit Emergency I NOT APPL	s Endorsements  Total HazMat Types  Total Lanes  Motor Vehicle Use		
	Vehi (SP) Tota 1 Insu NO Mosi DIT(	RANSIT cle Type ORT) UTILITY VEHICLI I Occs rance?  t Harmful Event: Collision W CH fic Way D-WAY, NOT DIVIDED	Train/Bus # Recorded  Direction Of Travel  WESTBOUND	Total # Citations Issued  Total # Citations Issued  Pre CrashTire Mark  Special Function NO SPECIAL FUNC  Traffic Control NO CONTROL	d e	Total Tra  0 Speed Li	AUTOMOE Operating As illers mit Emergency I NOT APPL Traffic Contr	Total HazMat Types  0  Total Lanes  2  Motor Vehicle Use  ICABLE  ol Inoperative/Missing		
	Vehi (SP) Tota 1 Insui NO Most DITC Traff TWC	RANSIT cle Type ORT) UTILITY VEHICLI I Occs rance? t Harmful Event: Collision W CH iic Way D-WAY, NOT DIVIDED ace Type	Train/Bus # Recorded  Direction Of Travel  WESTBOUND  Vith	Total # Citations Issued  Total # Citations Issued  Pre CrashTire Mark  Special Function NO SPECIAL FUNC  Traffic Control NO CONTROL  Road Curvature	d e	Total Tra  0 Speed Li	AUTOMOE Operating As  illers  mit  Emergency I NOT APPL  Traffic Contr NO Road Grade	Total HazMat Types  0  Total Lanes  2  Motor Vehicle Use  ICABLE  ol Inoperative/Missing		
	IN T Vehic (SP) Tota 1 Insur NO Most DITC Traff TWC Surfat BLA	RANSIT cle Type ORT) UTILITY VEHICLI I Occs rance? t Harmful Event: Collision W CH iic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS	Train/Bus # Recorded  Direction Of Travel  WESTBOUND  Vith	Total # Citations Issued  Total # Citations Issued  Pre CrashTire Mark  Special Function NO SPECIAL FUNC  Traffic Control NO CONTROL	d e	Total Tra  0 Speed Li	AUTOMOE Operating As illers mit Emergency I NOT APPL Traffic Contr	Total HazMat Types  0  Total Lanes  2  Motor Vehicle Use  ICABLE  ol Inoperative/Missing		
	IN T Vehic (SP) Tota 1 Insur NO Most DITC Traff TWC Surfat BLA	RANSIT cle Type ORT) UTILITY VEHICLI I Occs rance? t Harmful Event: Collision W CH iic Way D-WAY, NOT DIVIDED ace Type	Train/Bus # Recorded  Direction Of Travel  WESTBOUND  Vith	Total # Citations Issued  Total # Citations Issued  Pre CrashTire Mark  Special Function NO SPECIAL FUNC  Traffic Control NO CONTROL  Road Curvature	d e	Total Tra  0 Speed Li	AUTOMOE Operating As  illers  mit  Emergency I NOT APPL  Traffic Contr NO Road Grade	Total HazMat Types  0  Total Lanes  2  Motor Vehicle Use  ICABLE  ol Inoperative/Missing		
	IN T Vehi (SP Tota 1 Insu NO Most DIT Traff TWO Surfa BLA Truc NO	RANSIT cle Type ORT) UTILITY VEHICLI I Occs rance?  t Harmful Event: Collision W CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat	Train/Bus # Recorded  Direction Of Travel  WESTBOUND  Vith	Total # Citations Issued  Total # Citations Issued  Pre CrashTire Mark  Special Function NO SPECIAL FUNC  Traffic Control NO CONTROL  Road Curvature	d e	Total Tra 0 Speed Li 55	AUTOMOE Operating As  illers  mit  Emergency I NOT APPL  Traffic Contr NO Road Grade UPHILL	Total HazMat Types  0  Total Lanes  2  Motor Vehicle Use LICABLE  ol Inoperative/Missing		
	IN T Vehi (SP Tota 1 Insu NO Most DIT Traff TWO Surfa BLA Truc NO	RANSIT cle Type ORT) UTILITY VEHICLI I Occs rance?  It Harmful Event: Collision W CH ici Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat  Vehicle License Plate Number	Train/Bus # Recorded  Direction Of Travel  WESTBOUND  Vith	Total # Citations Issued  Total # Citations Issued  Pre CrashTire Mark  Special Function NO SPECIAL FUNC  Traffic Control NO CONTROL  Road Curvature CURVE RIGHT	d e	Total Tra 0 Speed Li 55	AUTOMOE Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade UPHILL Country of Iss	Total HazMat Types  0  Total Lanes  2  Motor Vehicle Use LICABLE ol Inoperative/Missing		
	IN T Vehi (SP Tota 1 Insu NO Most DIT Traff TWO Surfa BLA Truc NO	RANSIT cle Type ORT) UTILITY VEHICLI I Occs rance?  It Harmful Event: Collision W CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat  Vehicle License Plate Number AZP2094	Train/Bus # Recorded  Direction Of Travel  WESTBOUND  Vith	Total # Citations Issued  Total # Citations Issued  Pre CrashTire Mark  Special Function NO SPECIAL FUNC  Traffic Control NO CONTROL  Road Curvature CURVE RIGHT  Plate Type AUT	d e	Total Tra 0 Speed Li 55	AUTOMOE Operating As illers mit  Emergency I NOT APPL Traffic Contr NO Road Grade UPHILL  Country of Iss UNITED ST	Total HazMat Types  0  Total Lanes  2  Motor Vehicle Use LICABLE ol Inoperative/Missing		
	IN T Vehi (SP) Tota 1 Insul NO Most DIT( Traff TW( Surfa BLA Truc	CRANSIT  Cle Type  ORT) UTILITY VEHICLI  I Occs  rance?  It Harmful Event: Collision W  CH  Tic Way  D-WAY, NOT DIVIDED  Tace Type  ACKTOP (BITUMINOUS  Ik Bus or HazMat  Vehicle  License Plate Number  AZP2094  Vehicle Identification Num	Train/Bus # Recorded  Direction Of Travel  WESTBOUND  Vith	Total # Citations Issued  Total # Citations Issued  Pre CrashTire Mark  Special Function NO SPECIAL FUNC  Traffic Control NO CONTROL  Road Curvature CURVE RIGHT  Plate Type AUT Make	d e	Total Tra 0 Speed Li 55	AUTOMOE Operating As  illers  mit  Emergency I NOT APPL  Traffic Contr NO Road Grade UPHILL  Country of Iss UNITED ST Model	Total HazMat Types  0  Total Lanes  2  Motor Vehicle Use LICABLE ol Inoperative/Missing		
	IN T Vehi (SP Tota 1 Insu NO Most DIT Traff TWO Surfa BLA Truc NO	CRANSIT  cle Type  ORT) UTILITY VEHICLI  I Occs  rance?  It Harmful Event: Collision W  CH  ric Way  D-WAY, NOT DIVIDED  ace Type  ACKTOP (BITUMINOUS  k Bus or HazMat  Vehicle  License Plate Number  AZP2094  Vehicle Identification Num  2GNFLEEKXC634645	Train/Bus # Recorded  Direction Of Travel  WESTBOUND  Vith	Total # Citations Issued  Pre CrashTire Mark  Special Function NO SPECIAL FUNC  Traffic Control NO CONTROL  Road Curvature CURVE RIGHT  Plate Type AUT Make CHEV	d e	Total Tra 0 Speed Li 55	AUTOMOE Operating As  illers  mit  Emergency I NOT APPL  Traffic Contr NO Road Grade UPHILL  Country of Iss UNITED ST Model EQX	Total HazMat Types  0  Total Lanes  2  Motor Vehicle Use LICABLE ol Inoperative/Missing		
	IN T Vehi (SP) Tota 1 Insul NO Most DIT( Traff TW( Surfa BLA Truc	ransit cle Type ORT) UTILITY VEHICLI I Occs rance?  It Harmful Event: Collision W CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS Ik Bus or HazMat  Vehicle License Plate Number AZP2094  Vehicle Identification Num 2GNFLEEKXC634645  Color	Train/Bus # Recorded  Direction Of Travel  WESTBOUND  Vith	Total # Citations Issued  Pre CrashTire Mark  Special Function NO SPECIAL FUNC  Traffic Control NO CONTROL  Road Curvature CURVE RIGHT  Plate Type AUT  Make CHEV  Body Style	ECTION	Total Tra 0 Speed Li 55	AUTOMOE Operating As  illers  mit  Emergency I NOT APPL  Traffic Contr NO Road Grade UPHILL  Country of Iss UNITED ST Model	Total HazMat Types  0  Total Lanes  2  Motor Vehicle Use LICABLE ol Inoperative/Missing		
	IN T Vehi (SP) Tota 1 Insul NO Most DIT( Traff TW( Surfa BLA Truc	ransit cle Type ORT) UTILITY VEHICLI I Occs rance?  It Harmful Event: Collision W CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS Ik Bus or HazMat  Vehicle License Plate Number AZP2094  Vehicle Identification Num 2GNFLEEKXC634645  Color WHI - WHITE	Train/Bus # Recorded  Direction Of Travel  WESTBOUND  Vith	Total # Citations Issued  Pre CrashTire Mark  Special Function NO SPECIAL FUNC  Traffic Control NO CONTROL  Road Curvature CURVE RIGHT  Plate Type AUT  Make CHEV  Body Style UT - SPORT UTILI	ECTION	Total Tra 0 Speed Li 55	AUTOMOE Operating As  illers  mit  Emergency I NOT APPL  Traffic Contr NO Road Grade UPHILL  Country of Iss UNITED ST Model EQX	Total HazMat Types  0  Total Lanes  2  Motor Vehicle Use  ICABLE  ol Inoperative/Missing		
ONII	IN T Vehi (SP (SP Tota 1 Insul NO Most DIT Traff TW( Surfa BLA Truc NO )	ransit cle Type ORT) UTILITY VEHICLI I Occs rance?  It Harmful Event: Collision W CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS Ik Bus or HazMat  Vehicle License Plate Number AZP2094  Vehicle Identification Num 2GNFLEEKXC634645  Color	Train/Bus # Recorded  Direction Of Travel WESTBOUND  With	Total # Citations Issued  Total # Citations Issued  Pre CrashTire Mark  Special Function NO SPECIAL FUNC  Traffic Control NO CONTROL  Road Curvature CURVE RIGHT  Plate Type AUT Make CHEV Body Style UT - SPORT UTILI Vehicle Damage	ECTION  TY VEHIC	Total Tra 0 Speed Li 55	AUTOMOE Operating As  illers  mit  Emergency I NOT APPL  Traffic Contr NO Road Grade UPHILL  Country of Iss UNITED ST Model EQX Bus Use	Total HazMat Types  0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing		
ONII	IN T Vehi (SP (SP Tota 1 Insul NO Most DIT Traff TW( Surfa BLA Truc NO )	ransit cle Type ORT) UTILITY VEHICLI I Occs rance?  It Harmful Event: Collision W CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS Ik Bus or HazMat  Vehicle License Plate Number AZP2094  Vehicle Identification Num 2GNFLEEKXC634645  Color WHI - WHITE Initial Contact Point	Train/Bus # Recorded  Direction Of Travel WESTBOUND  With	Total # Citations Issued  Pre CrashTire Mark  Special Function NO SPECIAL FUNC  Traffic Control NO CONTROL  Road Curvature CURVE RIGHT  Plate Type AUT Make CHEV Body Style UT - SPORT UTILI Vehicle Damage 01 - RIGHT FRON FRONT, 10 - LEFT	TY VEHICE	Total Tra 0 Speed Li 55  St WI Year 2012  LE	AUTOMOE Operating As  illers  mit  Emergency I NOT APPL  Traffic Contr NO Road Grade UPHILL  Country of Iss UNITED ST Model EQX Bus Use	Total HazMat Types  0  Total Lanes 2  Motor Vehicle Use LICABLE ol Inoperative/Missing		
	IN T Vehi (SP Tota 1 Insul NO Most DIT Truff TWG Surfa BLA Truc	ransit cle Type ORT) UTILITY VEHICLI I Occs rance?  It Harmful Event: Collision W CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS Ik Bus or HazMat  Vehicle License Plate Number AZP2094  Vehicle Identification Num 2GNFLEEKXC634645  Color WHI - WHITE Initial Contact Point 00 - NON-COLLISION	Train/Bus # Recorded  Direction Of Travel WESTBOUND  Vith  S)	Total # Citations Issued  Pre CrashTire Mark  Special Function NO SPECIAL FUNC  Traffic Control NO CONTROL  Road Curvature CURVE RIGHT  Plate Type AUT  Make CHEV  Body Style UT - SPORT UTILI  Vehicle Damage 01 - RIGHT FRON	TY VEHICE	Total Tra 0 Speed Li 55  St WI Year 2012  LE	AUTOMOE Operating As  illers  mit  Emergency I NOT APPL  Traffic Contr NO Road Grade UPHILL  Country of Iss UNITED ST Model EQX Bus Use	Total HazMat Types  0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing		

Wisconsin Motor Vehicle Crash Form DT4000

This report does not include any CJIS data.

2 of 4

Crash Date 02/14/2025
Crash Time 05:53 PM

#### 6TL0DKRB2L 25-01419

### WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

				Vehicle Removed By PLATTS WRECKER					
	What Driver Was Doing				Vehicle Factors				
		NEGOTIATING CURVE			NOT ARRUGARUE				
		Driver Prior Action Other			NOT APPLICABLE				
		Driver Actions		L					
	쁘	SPEED TOO FAST/COND							
FIN	₽								
┍	VEHICLE								
		Owner Name OMAR LOPEZ-MARTIN	EZ		Owner Address 340 E MAIN ST # /	Α.			
2	2	(608) 415-9517			REEDSBURG, WI	53959 , US			
	;	Sequence Of Events Event							
	2	DITCH							
	05	Event							
	03	Event							
	40	Event							
	'	Individual							
	INDIVIDUAL	OMAR LOPEZ-MARTINEZ (608) 415-9517			Citations Issued Sex  1 MALE				
					Date of Birth	Date of Birth Race HISPANIC			
FIN	₽	Address			Driver License Number				
5	Ì	340 E MAIN ST # A			Diver License Number				
	=	REEDSBURG, WI 53959 , US							
		On Duty	Crash		Safety Equipment				
	Saf	Safety Equipment							
		Row	Seat Position		SHOULDER & LAP BELT				
		01 - FRONT ROW Helmet Use	V 07 - LEFT		Helmet Compliance				
		Eye Protection			Tint Compliance				
10	00	Injury Seventy			Airbag				
•	8	Injury NO AP	PARENT	INJURY	NON DEPLOYED		Transad/Cutrinated		
		NOT EJECTED	Ejection P	atn ECTED/NOT APPI	LICABLE		Trapped/Extricated NOT TRAPPED		
		Medical Transport			EMS Agency Identifier		EMS Run #		
	NOT TRANSPORTED				Date of Dooth		T(B#		
		Hospital		Date of Death Time of Death					
		Distracted By NOT A	ed By Sour PPLICAB	DE (NOT DISTRA	CTED)				
		NOT DISTRACTED							
		Non Motorist Striking	Unit #	Location					

Wisconsin Motor Vehicle Crash Form DT4000

This report does not include any CJIS data.  $3 \quad \text{of} \quad 4$  Crash Date 02/14/2025
Crash Time 05:53 PM

## **6TL0DKRB2L** 25-01419

### WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Prior Action						
İ		Action						
	Ι							
FIND	₫							
5	INDIVIDUAL							
	Z							
		Action Other						To/From School
		Drug & Alcohol	Suspected Alco	hol Use	Suspected Drug Use NO			
	_	Alcohol Test Given		Alcohol Test Type	_		Alcohol Test Results	
		TEST NOT GIVEN		Alcohol Test Type			Alcohol Test Nesults	
		Drug Test Given		Drug Test Type		Drug Test Results		
		TEŠT NOT GIVEN						
2	90	Drug Type						
		Individual Condition						
		APPEARED NORM	<b>IAL</b>					
		# 1 · 4 · · · ·						
		Violations UTC Number	Issue To?	Ctatuta Number	Description			
	5	BI589708	001	Statute Number <b>343.05(3)(a)</b>	Description OPERATE W/O VAL	ID LICENSE		