## WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	Document Number Override	Primary Crash Document #		3,		Investigating Officer/Deputy DEPUTY T. MOSLEY			
í	Crash Date <b>02/21/2025</b>	Crash Time 06:00 PM		Date A		Time Arrived 06:15 PM			
֝֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֡֓֓֓֓֓֡֓֓֡֓֓֡֓֓֓֓֓֡֡֓֡֓	02/21/2025  Date Notified 02/21/2025	Time Notified 06:00 PM	Time Notified		nits	Total Injured Total Killed 00 00		ed	
<u> </u>	On Emergency Hit	and Run	Lane Clos	ure Work Zone		Trailer or Towed		Reporting Threshold	
5	Government Property	Active So	chool Zone	School <b>NO</b>	Bus Related	Tags			
	<b>✓</b> Reportable	Crash Type PRIVATE PR	OPERTY/PARK	ING LO	Г	Amended		Secondary Crash	
Ē	Description								
	S3268 CTY TK BE 2/21/2025 @6:00F**NOT TO SCALE DEPUTY T.MOSLI	PM	WI 53913	white all Cross of a Strock of the Control of the C	asing the state of		otos By IOSLEY9 dittional Info		
	I, a sworn law enforceme Unit 1 WAS TRAVELING WEST BO DESIGNATED TRAVEL LANE. UNIT	OUND ON A DESI	GNATED TRAVEL L	ANE IN T	HE PARKING LOT. UNIT 2 V	VAS LEAVING THE	GAS STATI	ON TO GET ON THE SAME	

Wisconsin Motor Vehicle Crash Form DT4000

This report does not include any CJIS data.

1 of 6

#### **WISCONSIN MOTOR VEHICLE CRASH REPORT**

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

LU	cation ====							
_	RKING LOT			Latitude			Longitude	
C.	THBD EB LOT S3268			43.52761	17148		-89.777262665	
(0	THER S3268)			X Coordin	ate		Y Coordinate	
					275571.78125		4823156	
	THE TOWN OF DELTO	ON .					1.020.00	
IN	SAUK COUNTY			Structure of OTHER	туре			
<u> </u>				OTHER				
Cra	ash Scene 💳							
Fire	st Harmful Event			First Harm	nful Event I	ocation		
МС	TOR VEH IN TRANSP	ORT	IN PARK	ING LAN	IE OR ZONE			
Ma	nner of Collision		Light Cond	dition				
01	- ANGLE			DARK/L				
Ro	ad Surface Condition(s)			Roadway	_			
			Roadway	1 actor(3)				
DR	Y							
Env	vironment Factor(s)							
	)NE			NONE				
INC	/NE			NONL				
We	ather Condition(s)							
CI	EAR							
Ani	mal Type				o Trafficwa	•		
				NON TR	AFFICW	AY - PARKIN	G LOT	
Cra	sh Classification - Location	1		Crash Clas	ssification	- Jurisdiction		
PR	IVATE PROPERTY			PRIVATI	E PROPE	RTY		
Trib	oal Land			Access Co	ontrol		Special Study	
				NO CON	ITROL			
Wit	hin Interchange Area	Junction Location	Intersect	ion Type			<u>.</u>	
NC	-	NON-JUNCTION	NOT AN	N INTERSE	CTION			
<u> </u>			<u> </u>					
UN	it Summary 💻							
			1771110 0 0	01 '6' 6'				
Uni	t Status		Vehicle Operating As	Classification	ı	Unit Type		
Uni <b>IN</b>	t Status TRANSIT		Vehicle Operating As O	Classification	1	TRUCK		
IN Vel	t Status TRANSIT nicle Type			Classification	l	TRUCK	s Endorsements	
IN Vel	t Status TRANSIT nicle Type ILITY TRUCK/PICKUP		D CLASS			TRUCK Operating A		
IN Vel	t Status TRANSIT nicle Type	TRUCK Train/Bus # Recorded	D CLASS  Total # Citations Issue		Total Tra	TRUCK Operating A	Total HazMat Types	
IN Vel	t Status TRANSIT nicle Type ILITY TRUCK/PICKUP		D CLASS			TRUCK Operating A	Total HazMat Types	
Vel Uni Vel UT Tot	t Status TRANSIT nicle Type ILITY TRUCK/PICKUP		D CLASS  Total # Citations Issue	d	Total Tra	TRUCK Operating A	Total HazMat Types	
Vel Uni Vel UT Tot	t Status TRANSIT nicle Type ILITY TRUCK/PICKUP al Occs urance?	Train/Bus # Recorded	D CLASS  Total # Citations Issue 0	d	Total Tra	TRUCK Operating A	Total HazMat Types	
IN Vel UT Tot 1 Ins	t Status TRANSIT nicle Type ILITY TRUCK/PICKUP al Occs urance?	Train/Bus # Recorded  Direction Of Travel  WESTBOUND	Total # Citations Issue 0  Pre CrashTir Mark Special Function	e e	Total Tra  0  Speed Li	TRUCK Operating A illers mit Emergency	Total HazMat Types  0  Total Lanes  Motor Vehicle Use	
Uni IN Vel UT Tot 1 Ins YE	t Status TRANSIT nicle Type ILITY TRUCK/PICKUP al Occs urance? S	Train/Bus # Recorded  Direction Of Travel  WESTBOUND  With	Total # Citations Issue 0  Pre CrashTir Mark	e e	Total Tra  0  Speed Li	TRUCK Operating A	Total HazMat Types  0  Total Lanes  Motor Vehicle Use	
Uni IN Vel UT Tot 1 Ins YE	t Status TRANSIT nicle Type ILITY TRUCK/PICKUP al Occs urance? S st Harmful Event: Collision	Train/Bus # Recorded  Direction Of Travel  WESTBOUND  With	Total # Citations Issue 0  Pre CrashTir Mark Special Function	e e	Total Tra  0  Speed Li	TRUCK Operating A illers mit  Emergency NOT APP	Total HazMat Types  0  Total Lanes  Motor Vehicle Use	
Uni IN Vel UT Tot 1 Ins YE Mo MC	t Status TRANSIT nicle Type ILITY TRUCK/PICKUP al Occs urance? S st Harmful Event: Collision DTOR VEH IN TRANSP	Train/Bus # Recorded  Direction Of Travel  WESTBOUND  With  ORT	D CLASS  Total # Citations Issue 0  Pre CrashTir Mark Special Function NO SPECIAL FUN	e e	Total Tra  0  Speed Li	TRUCK Operating A illers mit  Emergency NOT APP	Total HazMat Types  0  Total Lanes  Motor Vehicle Use  LICABLE	
Uni IN Vel UT Tot 1 Ins YE Mo MC Tra	t Status TRANSIT nicle Type ILITY TRUCK/PICKUP al Occs urance? S st Harmful Event: Collision DTOR VEH IN TRANSP ffic Way RKING LOT OR PRIVA	Train/Bus # Recorded  Direction Of Travel  WESTBOUND  With  ORT	Total # Citations Issue 0  Pre CrashTir Mark Special Function NO SPECIAL FUN Traffic Control	e e	Total Tra  0  Speed Li	TRUCK Operating A  illers  mit  Emergency NOT APP Traffic Cont	Total HazMat Types  0  Total Lanes  Motor Vehicle Use LICABLE  rol Inoperative/Missing	
Uni IN Vel UT Tot 1 Ins YE Mo MC Tra PA	t Status TRANSIT nicle Type ILITY TRUCK/PICKUP al Occs urance? S st Harmful Event: Collision DTOR VEH IN TRANSP ffic Way RKING LOT OR PRIVA	Train/Bus # Recorded  Direction Of Travel  WESTBOUND  With OORT	Total # Citations Issue 0  Pre CrashTir Mark  Special Function NO SPECIAL FUN  Traffic Control NO CONTROL  Road Curvature	e e	Total Tra  0  Speed Li	TRUCK Operating A  illers  mit  Emergency NOT APP Traffic Cont NO	Total HazMat Types  0  Total Lanes  Motor Vehicle Use LICABLE  rol Inoperative/Missing	
Uni IN Vel UT Tot 1 Ins YE Mo Tra PA Sui BL	t Status TRANSIT nicle Type ILITY TRUCK/PICKUP al Occs urance? S st Harmful Event: Collision DTOR VEH IN TRANSP ffic Way RKING LOT OR PRIVA face Type ACKTOP (BITUMINOU	Train/Bus # Recorded  Direction Of Travel  WESTBOUND  With OORT	Total # Citations Issue 0  Pre CrashTir Mark  Special Function NO SPECIAL FUN  Traffic Control NO CONTROL	e e	Total Tra  0  Speed Li	TRUCK Operating A  illers  mit  Emergency NOT APP  Traffic Cont NO  Road Grade	Total HazMat Types  0  Total Lanes  Motor Vehicle Use LICABLE  rol Inoperative/Missing	
Uni IN Vel UT Total 1 Ins YE Mo MC Trans BL Tru	t Status TRANSIT nicle Type ILITY TRUCK/PICKUP al Occs urance? S st Harmful Event: Collision DTOR VEH IN TRANSP ffic Way RKING LOT OR PRIVA fface Type ACKTOP (BITUMINOU ck Bus or HazMat	Train/Bus # Recorded  Direction Of Travel  WESTBOUND  With OORT	Total # Citations Issue 0  Pre CrashTir Mark  Special Function NO SPECIAL FUN  Traffic Control NO CONTROL  Road Curvature	e e	Total Tra  0  Speed Li	TRUCK Operating A  illers  mit  Emergency NOT APP  Traffic Cont NO  Road Grade	Total HazMat Types  0  Total Lanes  Motor Vehicle Use LICABLE  rol Inoperative/Missing	
Uni IN Vel UT Tot 1 Ins YE Mo Tra PA Sui BL	t Status TRANSIT nicle Type ILITY TRUCK/PICKUP al Occs urance? S st Harmful Event: Collision DTOR VEH IN TRANSP ffic Way RKING LOT OR PRIVA face Type ACKTOP (BITUMINOU ck Bus or HazMat	Train/Bus # Recorded  Direction Of Travel  WESTBOUND  With OORT	Total # Citations Issue 0  Pre CrashTir Mark  Special Function NO SPECIAL FUN  Traffic Control NO CONTROL  Road Curvature	e e	Total Tra  0  Speed Li	TRUCK Operating A  illers  mit  Emergency NOT APP  Traffic Cont NO  Road Grade	Total HazMat Types  0  Total Lanes  Motor Vehicle Use LICABLE  rol Inoperative/Missing	
Uni IN Vel UT Total 1 Ins YE Mo MC Trans BL Tru	t Status TRANSIT nicle Type ILITY TRUCK/PICKUP al Occs urance? S st Harmful Event: Collision DTOR VEH IN TRANSP ffic Way RKING LOT OR PRIVA face Type ACKTOP (BITUMINOU ck Bus or HazMat ) Vehicle	Train/Bus # Recorded  Direction Of Travel  WESTBOUND  With OORT	D CLASS  Total # Citations Issue 0  Pre CrashTir Mark Special Function NO SPECIAL FUN Traffic Control NO CONTROL Road Curvature STRAIGHT	e e	Total Tra 0 Speed Li 10	TRUCK Operating A illers  mit  Emergency NOT APP Traffic Cont NO Road Grade LEVEL	Total HazMat Types  0  Total Lanes  Motor Vehicle Use LICABLE  rol Inoperative/Missing	
Uni IN Vel UT Total 1 Ins YE Mo MC Tra PA Sul BL Tru	t Status TRANSIT nicle Type ILITY TRUCK/PICKUP al Occs urance? S st Harmful Event: Collision DTOR VEH IN TRANSP ffic Way RKING LOT OR PRIVA face Type ACKTOP (BITUMINOU ck Bus or HazMat ) Vehicle License Plate Number	Train/Bus # Recorded  Direction Of Travel  WESTBOUND  With OORT	D CLASS  Total # Citations Issue 0  Pre CrashTir Mark Special Function NO SPECIAL FUN Traffic Control NO CONTROL Road Curvature STRAIGHT	e e	Total Tra 0 Speed Li 10	TRUCK Operating A  illers  mit  Emergency NOT APP Traffic Cont NO Road Grade LEVEL  Country of Is	Total HazMat Types  0  Total Lanes  Motor Vehicle Use LICABLE  rol Inoperative/Missing	
United States of the states of	t Status TRANSIT nicle Type ILITY TRUCK/PICKUP al Occs urance? S st Harmful Event: Collision DTOR VEH IN TRANSP ffic Way RKING LOT OR PRIVA face Type ACKTOP (BITUMINOU ck Bus or HazMat ) Vehicle	Train/Bus # Recorded  Direction Of Travel  WESTBOUND  With OORT	Total # Citations Issue 0  Pre CrashTir Mark  Special Function NO SPECIAL FUN  Traffic Control NO CONTROL  Road Curvature STRAIGHT  Plate Type LTK	e e	Total Tra 0 Speed Li 10	TRUCK Operating A illers  mit  Emergency NOT APP Traffic Cont NO Road Grade LEVEL	Total HazMat Types  0  Total Lanes  Motor Vehicle Use LICABLE  rol Inoperative/Missing	
Uni IN Vel UT Tot 1 Ins YE Mo MC Tra BL Tru NC	t Status TRANSIT nicle Type ILITY TRUCK/PICKUP al Occs urance? S st Harmful Event: Collision DTOR VEH IN TRANSP ffic Way RKING LOT OR PRIVA fface Type ACKTOP (BITUMINOU ck Bus or HazMat ) Vehicle  License Plate Number RP6676 Vehicle Identification Nu	Train/Bus # Recorded  Direction Of Travel  WESTBOUND  With OORT  ATE PROPERTY  JS)	Total # Citations Issue 0  Pre CrashTir Mark  Special Function NO SPECIAL FUN  Traffic Control NO CONTROL  Road Curvature STRAIGHT  Plate Type LTK Make	e e	Total Tra 0 Speed Li 10	TRUCK Operating A  illers  mit  Emergency NOT APP Traffic Cont NO Road Grade LEVEL  Country of Is UNITED ST	Total HazMat Types  0  Total Lanes  Motor Vehicle Use LICABLE  rol Inoperative/Missing	
Uni IN Vel UT Tot 1 Ins YE Mo MC Tra PA Suit BL Tru NC	t Status TRANSIT nicle Type ILITY TRUCK/PICKUP al Occs urance? S st Harmful Event: Collision DTOR VEH IN TRANSP ffic Way RKING LOT OR PRIVA face Type ACKTOP (BITUMINOU ck Bus or HazMat ) Vehicle License Plate Number RP6676	Train/Bus # Recorded  Direction Of Travel  WESTBOUND  With OORT  ATE PROPERTY  JS)	Total # Citations Issue 0  Pre CrashTir Mark  Special Function NO SPECIAL FUN  Traffic Control NO CONTROL  Road Curvature STRAIGHT  Plate Type LTK	e e	Total Tra 0 Speed Li 10	TRUCK Operating A illers mit  Emergency NOT APP Traffic Cont NO Road Grade LEVEL  Country of Is UNITED S	Total HazMat Types  0  Total Lanes  Motor Vehicle Use LICABLE  rol Inoperative/Missing	
Uni IN Vel UT Tot 1 Ins YE Mo MC Tran BL Tru NC	t Status TRANSIT nicle Type ILITY TRUCK/PICKUP al Occs urance? S st Harmful Event: Collision DTOR VEH IN TRANSP ffic Way RKING LOT OR PRIVA fface Type ACKTOP (BITUMINOU ck Bus or HazMat ) Vehicle  License Plate Number RP6676 Vehicle Identification Nu	Train/Bus # Recorded  Direction Of Travel  WESTBOUND  With OORT  ATE PROPERTY  JS)	Total # Citations Issue 0  Pre CrashTir Mark  Special Function NO SPECIAL FUN  Traffic Control NO CONTROL  Road Curvature STRAIGHT  Plate Type LTK Make	e e	Total Tra 0 Speed Li 10	TRUCK Operating A  illers  mit  Emergency NOT APP Traffic Cont NO Road Grade LEVEL  Country of Is UNITED ST	Total HazMat Types  0  Total Lanes  Motor Vehicle Use LICABLE  rol Inoperative/Missing	
Uni IN Vel UT Tot 1 Ins YE Mo MC Tra BL Tru NC	t Status TRANSIT nicle Type ILITY TRUCK/PICKUP al Occs urance? S st Harmful Event: Collision DTOR VEH IN TRANSP ffic Way RKING LOT OR PRIVA face Type ACKTOP (BITUMINOU ck Bus or HazMat ) Vehicle License Plate Number RP6676 Vehicle Identification Nu 3GTU9DEL9LG2565	Train/Bus # Recorded  Direction Of Travel  WESTBOUND  With OORT  ATE PROPERTY  JS)	Total # Citations Issue 0  Pre CrashTir Mark  Special Function NO SPECIAL FUN  Traffic Control NO CONTROL  Road Curvature STRAIGHT  Plate Type LTK Make GMC	e e	Total Tra 0 Speed Li 10	TRUCK Operating A  illers  mit  Emergency NOT APP Traffic Cont NO Road Grade LEVEL  Country of Is UNITED ST Model SIERRA	Total HazMat Types  0  Total Lanes  Motor Vehicle Use LICABLE  rol Inoperative/Missing	
Uni IN Vel UT Tot 1 Ins YE Mo MC Tran BL Tru NC	t Status TRANSIT nicle Type ILITY TRUCK/PICKUP al Occs urance? S st Harmful Event: Collision DTOR VEH IN TRANSP ffic Way RKING LOT OR PRIVA face Type ACKTOP (BITUMINOU ck Bus or HazMat ) Vehicle License Plate Number RP6676 Vehicle Identification Nu 3GTU9DEL9LG2565 Color	Train/Bus # Recorded  Direction Of Travel  WESTBOUND  With OORT  ATE PROPERTY  JS)	Total # Citations Issue 0  Pre CrashTir Mark  Special Function NO SPECIAL FUN  Traffic Control NO CONTROL  Road Curvature STRAIGHT  Plate Type LTK Make GMC Body Style	e e	Total Tra 0 Speed Li 10	TRUCK Operating A  illers  mit  Emergency NOT APP Traffic Cont NO Road Grade LEVEL  Country of Is UNITED ST Model SIERRA	Total HazMat Types  0  Total Lanes  Motor Vehicle Use LICABLE  rol Inoperative/Missing  suance  FATES	
Uni IN Vel UT Tot 1 Ins YE Mo MC Tran BL Tru NC	t Status TRANSIT nicle Type ILITY TRUCK/PICKUP al Occs urance? S st Harmful Event: Collision DTOR VEH IN TRANSP ffic Way RKING LOT OR PRIVA fface Type ACKTOP (BITUMINOU ck Bus or HazMat ) Vehicle License Plate Number RP6676 Vehicle Identification Nu 3GTU9DEL9LG2565 Color BLK - BLACK	Train/Bus # Recorded  Direction Of Travel WESTBOUND  With ORT  ATE PROPERTY  US)	Total # Citations Issue 0  Pre CrashTir Mark  Special Function NO SPECIAL FUN  Traffic Control NO CONTROL  Road Curvature STRAIGHT  Plate Type LTK Make GMC  Body Style PK - PICKUP	e e	Total Tra 0 Speed Li 10	TRUCK Operating A  illers  mit  Emergency NOT APP Traffic Cont NO Road Grade LEVEL  Country of Is UNITED ST Model SIERRA	Total HazMat Types  0  Total Lanes  Motor Vehicle Use LICABLE  rol Inoperative/Missing  suance FATES	
Uni IN Vel UT Tot 1 Ins YE Mo MC Tran BL Tru NC	t Status TRANSIT nicle Type ILITY TRUCK/PICKUP al Occs urance? S st Harmful Event: Collision DTOR VEH IN TRANSP ffic Way RKING LOT OR PRIVA face Type ACKTOP (BITUMINOU ck Bus or HazMat ) Vehicle License Plate Number RP6676 Vehicle Identification Nu 3GTU9DEL9LG2565 Color BLK - BLACK Initial Contact Point	Train/Bus # Recorded  Direction Of Travel WESTBOUND  With ORT  ATE PROPERTY  US)	Total # Citations Issue 0  Pre CrashTir Mark  Special Function NO SPECIAL FUN  Traffic Control NO CONTROL  Road Curvature STRAIGHT  Plate Type LTK Make GMC  Body Style PK - PICKUP	e CTION	Total Tra 0 Speed Li 10	TRUCK Operating A  illers  mit  Emergency NOT APP Traffic Cont NO Road Grade LEVEL  Country of Is UNITED ST Model SIERRA	Total HazMat Types  0  Total Lanes  Motor Vehicle Use LICABLE  rol Inoperative/Missing  suance  FATES	112
Uni IN Vei UT Tot 1 Ins YE Mo MC Trara BL Tru NC	t Status TRANSIT nicle Type ILITY TRUCK/PICKUP al Occs urance? S st Harmful Event: Collision DTOR VEH IN TRANSP ffic Way RKING LOT OR PRIVA face Type ACKTOP (BITUMINOU ck Bus or HazMat ) Vehicle License Plate Number RP6676 Vehicle Identification Nu 3GTU9DEL9LG2565 Color BLK - BLACK Initial Contact Point 04 - RIGHT SIDE RE Extent Of Damage	Train/Bus # Recorded  Direction Of Travel WESTBOUND  With ORT  ATE PROPERTY  US)	Total # Citations Issue 0  Pre CrashTir Mark  Special Function NO SPECIAL FUN  Traffic Control NO CONTROL  Road Curvature STRAIGHT  Plate Type LTK Make GMC Body Style PK - PICKUP  Vehicle Damage	e CTION	Total Tra 0 Speed Li 10	TRUCK Operating A  illers  mit  Emergency NOT APP Traffic Cont NO Road Grade LEVEL  Country of Is UNITED ST Model SIERRA	Total HazMat Types  0  Total Lanes  Motor Vehicle Use LICABLE  rol Inoperative/Missing  suance FATES	12
Uni IN Vel UT Tot 1 Ins YE Mo MC Tran BL Tru NC	t Status TRANSIT nicle Type ILITY TRUCK/PICKUP al Occs urance? S st Harmful Event: Collision DTOR VEH IN TRANSP ffic Way RKING LOT OR PRIVA face Type ACKTOP (BITUMINOU ck Bus or HazMat ) Vehicle License Plate Number RP6676 Vehicle Identification Nu 3GTU9DEL9LG2565 Color BLK - BLACK Initial Contact Point 04 - RIGHT SIDE RE	Train/Bus # Recorded  Direction Of Travel WESTBOUND  With ORT  ATE PROPERTY  US)	Total # Citations Issue 0  Pre CrashTir Mark  Special Function NO SPECIAL FUN  Traffic Control NO CONTROL  Road Curvature STRAIGHT  Plate Type LTK Make GMC Body Style PK - PICKUP  Vehicle Damage	e CTION	Total Tra 0 Speed Li 10	TRUCK Operating A  illers  mit  Emergency NOT APP Traffic Cont NO Road Grade LEVEL  Country of Is UNITED ST Model SIERRA	Total HazMat Types  0  Total Lanes  Motor Vehicle Use LICABLE  rol Inoperative/Missing  suance FATES	112

Wisconsin Motor Vehicle Crash Form DT4000

is report does not include any CJIS data. 2 of 6

Crash Time 06:00 PM

Page 2 of 6

## WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		T 15 T 5						
		Towed Due To Damage		Vehicle Removed By				
		NOT TOWED		OWNER				
		What Driver Was Doing		Vehicle Factors				
		GOING STRAIGHT		NOT APPLICABLE				
		Driver Prior Action Other		NOT APPLICABLE				
		Discontations						
		Driver Actions NO CONTRIBUTING ACT	ION					
ᆫ	"	NO CONTRIBUTING ACT	ION					
E E	≌							
5	VEHICLE							
	>							
		Owner Name		Owner Address				
		Owner Name RONALD SKROCH		3684 W 11TH JC	т			
2	2	(608) 418-0408			LLS, WI 53965 ,U	IS		
-								
		Common Of France						
	,	Sequence Of Events Event						
	2	MOTOR VEH IN TRANSP	ORT					
	05	Event						
	•							
	03	Event						
		Event						
	9	Event						
١.		Policy Holder						
FNS		Insurance Company		INDIVIDUAL				
5		STATE-FARM-MUTUAL-	AUTOMOBILE-INS-CO	RONALD SKROCK	н			
		Individual  DRIVER		Oiteffers Januari	Low			
		RONALD SKROCH		Citations Issued Sex  MALE				
	₹	(608) 418-0408		Date of Birth				
_	INDIVIDUAL			WHITE				
Ę	ੁ	Address		Driver License Number	er			
>	፬	3684 W 11TH JCT						
	=	WISCONSIN DELLS, WI	53965 , US					
l	S-1	On Duty	y Crash	Safety Equipment				
	Sai	fety Equipment						
		Row Seat Position		SHOULDER & LAP BELT				
		01 - FRONT ROW	07 - LEFT	Helmet Compliance				
		Helmet Use						
		Eye Protection		Tint Compliance				
				Tint Compliance				
_	Ξ	Injury S	everity	Airbag				
0	90	Injury NO AF	PPARENT INJURY	NON DEPLOYED				
l		Ejected	Ejection Path	•		Trapped/Extricated		
		NOT EJECTED	NOT EJECTED/NOT AP	PLICABLE		NOT TRAPPED		
		Medical Transport		EMS Agency Identifie	r	EMS Run #		
		NOT TRANSPORTED		Date of Date		Time of Dooth		
		Hospital		Date of Death		Time of Death		
		Distract	ed By Source			1		
		Distracted By NOT A	APPLICABLE (NOT DISTR	ACTED)				
		Distracted By Action						
		NOT DISTRACTED						

Wisconsin Motor Vehicle Crash Form DT4000

This report does not include any CJIS data.  $\begin{tabular}{ll} 3 & of & 6 \end{tabular}$ 

Crash Date 02/21/2025
Crash Time 06:00 PM

## WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Non Motorist	riking Unit #	Location					
		Prior Action							
		Action							
	4								
LIND	INDIVIDUAL								
5									
	Z								
		Action Other						To/From School	
								16,116 66.166.	
	1	Drug & Alcohol N	uspected Alcohol ( O	Use	Suspected Drug Use NO				
		Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type			Alcohol Test I	Results	
		Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug Test Resul	ts	_	
_	_	Drug Type							
2	90								
		Individual Condition							
		APPEARED NORMA	L						
I	Uni	t Summary <b>=</b>							
		Status			ehicle Operating As Class	ification	Unit Type		
		RANSIT		D	CLASS		AUTOMOBILE		
05		icle Type ORT) UTILITY VEHICI	e Type RT) UTILITY VEHICLE				Operating As Endorsements		
	Tota 1	l Occs	Train/Bus # Re		Total # Citations Issued Total Trai  0 0			Total HazMat Types  0	
		rance?	Direction Of Ti	ravel	Pre CrashTire	Speed Li		Total Lanes	
LIND	YES	S SOUTHBOUND t Harmful Event: Collision With		-	Mark 05 Special Function			Motor Vehicle Use	
7	МО	TOR VEH IN TRANSP		N	NO SPECIAL FUNCTION			ICABLE	
	Traffic Way PARKING LOT OR PRIVATE PROPERTY				raffic Control IO CONTROL		Traffic Control Inoperative/Missing  NO		
		ace Type ACKTOP (BITUMINOU	S)		Road Curvature STRAIGHT				
	Truc	k Bus or HazMat	<u> </u>		TIVALOITI		LEVEL	_	
	NO,	Vehicle							
		License Plate Number		F	Plate Type	St	Country of Issuance		
		946XUH			AUT	WI	UNITED STATES		
05	05	Vehicle Identification Null 1C4NJDBB6ED8803			Make JEEP	Year <b>2014</b>	Model COMPASS SP		
		Color		E	Body Style		Bus Use	<u></u>	
	111	WHI - WHITE Initial Contact Point			LL - CARRYALL Vehicle Damage				
L	ij	11 - LEFT FRONT CO	ORNER		verlicle Damage			7 8 9 10 11	
LIND	VEHICLE	Extent Of Damage MINOR DAMAGE			11 - LEFT FRONT CO	RNER	6		
	>	Towed Due To Damage			Vehicle Removed By				
1		NOT TOWED			OWNER				

Wisconsin Motor Vehicle Crash Form DT4000

This report does not include any CJIS data.

4 of 6

Crash Date 02/21/2025
Crash Time 06:00 PM

# WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

								` ,	
		What Driver Was Doing		V	ehicle Factors				
		LEAVING A PARKED POSITION			OT APPLICABLE				
		Driver Prior Action Other	iver Prior Action Other						
		Driver Actions		•					
	щ	FAILED TO YIELD RIGH	T-OF-WAY						
╘	ರ								
IND	主								
-	VEHICLE								
		Owner Name			Owner Address				
~	ROBERT EBNER				N7560 COUNTY R				
02	05	(847) 271-5678			MINDORO, WI 546	44 , US			
	;	Sequence Of Events	<b>5</b>						
		Event							
	2	MOTOR VEH IN TRANSI	PORT						
	05	Event							
	0								
	03	Event							
	0								
	4	Event							
	0								
<b>-</b>	- 1	Policy Holder							
LIND		Insurance Company			INDIVIDUAL				
>		AMERICAN-FAMILY-INS-CO			ROBERT EBNER				
		Individual							
		DRIVER			Citations Issued Sex				
	_	ROBERT EBN	ER		0 MALE				
	4	(847) 271-5678			Date of Birth Race				
⊨	NDIVIDUAL					WHITE			
IN N	≥	Address	•		Driver License Number				
-	Ħ	N7560 COUNTY ROAD ( MINDORO, WI 54644, U							
	_	MINDORO, WI 54644 , US							
		On Duty Crash							
	Sat	fety Equipment	ity Crasn		Safety Equipment				
					SHOULDER & LAP BELT				
		Row 01 - FRONT ROW	Seat Posi 07 - LEF		SHOULDER & LAP	DELI			
		Helmet Use	07 - EEI	1	Helmet Compliance				
		Heimet Use			Tionnet Compilance				
		Eye Protection			Tint Compliance				
		,							
~	2	Injury :	Severity		Airbag				
05	005	Injury NO A	PPARENT IN	JURY	NON DEPLOYED				
		Ejected	Ejection Path				Trapped/Extricated		
		NOT EJECTED	NOT EJEC	TED/NOT APPL	ICABLE		NOT TRAPPED		
		Medical Transport			EMS Agency Identifier		EMS Run #		
		NOT TRANSPORTED							
		Hospital	<u></u>		Date of Death		Time of Death		
		15::	ated Director						
	Distracted By Source UNKNOWN								
	Distracted By Action								
		OTHER ACTION (LOOK	ING AWAY FE	ROM TASK ETC	<b>(</b> )				
		Strikin		Location	-				
		Non Motorist							

Wisconsin Motor Vehicle Crash Form DT4000

This report does not include any CJIS data.  $5 \quad \text{of} \quad 6$ 

Crash Date 02/21/2025
Crash Time 06:00 PM

## WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Prior Action					
İ		Action					
	Ļ						
_	N						
LNO	VID						
_	INDIVIDUAL						
	=						
		Action Other					To/From School
		Aloudi Guidi					Ton Ton Concor
	L	Drug & Alcohol NO	Jse	Suspected Drug Use NO			
		Alcohol Test Given TEST NOT GIVEN	Alcohol Test Type			Alcohol Test Results	
		Drug Test Given TEST NOT GIVEN	Drug Test Type		Drug Test Results	5	
05	002	Drug Type			1		
	0						
		Individual Condition		_			
		APPEARED NORMAL					