25-02131

WISCONSIN MOTOR VEHICLE CRASH REPORT

Crash Date Crash Time Date Arrived Time Arrived 03/07/2025 12:39 PM 03/07/2025 01:02 PM Date Notified Time Notified Total Units Total Injured 00 03/07/2025 12:39 PM 01 Total Units Total Injured 00 03/07/2025 12:39 PM 01 Total Units Total Injured 00 00 00 00 0 0 0 0 0 0 0 00 0 0 0 0 0 0 0 0 0 00 0	
Ng Date Notified Time Notified Total Units Total Units Total Injured Total Killed 03/07/2025 12:39 PM 01 00 00	
O3/07/2025 12:39 PM O1 O0 O0 On Emergency Hit and Run Lane Closure Work Zone Trailer or Towed []	
On Emergency Hit and Run Lane Closure Work Zone Trailer or Towed	
	Reporting Threshold
Government Property Active School Zone NO School Bus Related Tags	
Image: Crash Type PRIVATE PROPERTY/PARKING LOT Amended	Secondary Crash
Description	
Diagram Reconstruction By not to scale Photos By DEPUTY J. HUI	
Additional Informat PHOTOS	ation
HY 33/ W. Main St	
light pole w/ stop sion attached HY 58/ Center St.	
, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.	
OPERATOR OF UNIT 1 WAS W/B ON HY 33/ W. MAIN ST. IN LA VALLE. OPERATOR MISSED HIS TURN ONTO 33/58 N/B AND WANTED TO TUR	
THE PARKING LOT NEAR HY 33/ HY 58 S/B AND ATTEMPTED TO TURN AROUND IN IT. WHILE BACKING, TRAILER OF UNIT 1 STRUCK A LIG SIGN ATTACHED. THIS CRACKED OR BROKE NEARLY THE ENTIRE BASE, CAUSING THE POLE TO BE DAMAGED AND WOBBLY TO THE TO BYSTANDERS ASSISTED THE OPERATOR IN SAFELY BACKING ONTO THE ROADWAY.	GHT POLE W/ A STOP

25-02131

WISCONSIN MOTOR VEHICLE CRASH REPORT

l	_oc	ation									
ſ		KING LOT		Latitude			Longitu	de			
					43.5826		.582618422		-90.13	3612282	
		HE VILLAGE OF LA V AUK COUNTY				ate 5		Y Coord 48302			
						Structure NO STR					
(Cra	sh Scene									
1		Harmful Event				First Harm	nful Event Lo	ocation			
	ОТН	IER FIXED OBJECT						OR ZONE			
ľ	Man	ner of Collision				Light Con	dition				
	00 -	NO COLLISION W/VE	HICLE IN TRANSPORT			DAYLIG					
Ī	Road	d Surface Condition(s)				Roadway	Factor(s)				
	DR۱	(
	Envi	ronment Factor(s)									
	NOM	NE				NONE					
ŀ	Wea	ther Condition(s)				_					
	CLE										
							- - "				
	ANIM	nal Type					o Trafficwa	/ Y - PARKIN	GLOT		
ł	Cras	h Classification - Location					ssification -				
		BLIC PROPERTY						ISDICTION			
ľ	Triba	al Land				Access Control				Special Study	
			Junction Location			NO CONTROL					
		in Interchange Area		Intersection Type NOT AN INTERSECTION							
	NO		NON-JUNCTION		NUTAN	INTERSE	CTION				
		t Summary		N/abiala On	anatian A.a. C	N : f : + :					
				A CLASS	erating As C	lassification	1	Unit Type TRUCK			
ŀ		cle Type	Operating As Endorse			ments					
•		ICK TRACTOR (SEMI	ATTACHED)				operating				
ŀ		Occs	Train/Bus # Recorded	Total # Cita	ations Issued	ł	Total Trail	ers	Total Ha	zMat Types	
	1			0			1		0		
		rance?	Direction Of Travel	Pre CrashTi				nit	Total Lar	Total Lanes	
	YES			Special Fur	Mark			Emergency Motor Vel			
		: Harmful Event: Collision [\] IER FIXED OBJECT	vvitri								
ŀ		ic Way		Traffic Cont	trol			Traffic Cont	rol Inopera	tive/Missing	
	PAR	KING LOT OR PRIVA	TE PROPERTY	NO CONT				NO			
ľ	Surface Type			Road Curva	ature			Road Grade			
		CKTOP (BITUMINOU	S)	STRAIGH	IT			LEVEL			
		k Bus or HazMat									
4			BINATION > 10,000LBS G	WR/GCWR	_	_	_	_			
		Vehicle License Plate Number		Dioto Turo			St	Country of Is	suance		
		3033030		Plate Type APO	3		IN	UNITED S			
		Vehicle Identification Nur	mber	Make			Year	Model			
	01	3AKJHHDR2MSMS1	FRHT				SEMI				
		Color	Body Style	Body Style Bus Use							
		WHI - WHITE	DS - TRACTOR-TRUCK DIESEL								
	ГШ	Initial Contact Point		Vehicle Da	amage					7 8 9 10 11	
	/EHICL	00 - NON-COLLISION	N		DAMAGE					6	
	山	Extent Of Damage NO DAMAGE	00 - NO	DANAGE					5 4 3 2 1		
. J	-										

25-02131

WISCONSIN MOTOR VEHICLE CRASH REPORT

		Towed Due To Damage				Vehicle Removed By						
		NOT TOWED				ERATOR						
		What Driver Was Doing BACKING			Veł	nicle Facto	rs					
		Driver Prior Action Other			NC		CABLE					
		Driver Actions										
	Щ	UNSAFE BACKING										
UNIT	<u></u>											
5	VEHICLE											
	>											
		Owner Name				Owner Ad						
01						1201 CENTRAL AVE UNIT 5N LAKE STATION, IN 46405 , US						
								40403 , 0	.5			
			_									
		Sequence Of Event Event	S									
	0	OTHER FIXED OBJECT	Γ									
	02	Event										
	e	Event										
	03	Front										
	04	Event										
⊢	I	Policy Holder										
UNIT		Insurance Company				ORGANIZATION/COMPANY						
		INSURNORTH CORP		MOLDEX INC								
	•	Trailer/Towed							1			
2			ate Type RL	Make MCKT			State IL			ry of Issuance ED STATES		
	R/	Unit Type				1201			Addre			
UNIT	LE L	SEMI TRAILER MOLDEX INC Vehicle Identification Number 5MAPA5320RH072538								1201 CENTRAL AVE UNIT 5N LAKE STATION, IN 46405 , US		
2	TRAILER/											
		Individual										
		DRIVER			(Citations Is	sued	Sex				
	٩L	GEORGII MIAKINKIN (929) 426-8310				0		MALE				
		(323) 420-03 10				Date of Birth		Race WHITE				
UNIT	NDIVIDN	Address				Driver License Number						
	ā	1985 W 9TH ST BROOKLYN, NY 11223 ,US				STATE: NEW YORK COUNTRY: UNITED STATES						
	=											
		On D	On Duty Crash				Cofet - Environment					
Safety Equipment					Safety Equipment							
		Row	Seat Position			SHOULDER & LAP BELT						
		01 - FRONT ROW 07 - LEFT										
	Helmet Use					Helmet Compliance						
		Eye Protection			1	Fint Compli	iance					
01	001	1	Severity		Airbag							
	õ				1	NON DEPLOYED						
		Ejected NOT EJECTED	-	on Path EJECTED/NOT AP						Trapped/Extricated NOT TRAPPED		
			101									

25-02131

WISCONSIN MOTOR VEHICLE CRASH REPORT

		Medical Transport			EMS A	gency Identifier			EMS Run #			
		NOT TRANSPORTED	Date of Death									
		Hospital	Date o	of Death lime of Death			Time of Death					
		Distracted By Distracted	l By Source WN	2	1							
		Distracted By Action UNKNOWN										
	-	Non Motorist	nit #	Location								
		Prior Action										
UNIT	INDIVIDUAL	Action										
		Action Other								To/From School		
		Quarante			0	ate d Davie Lla a						
	L	Drug & Alcohol NO	lse	NO NO	cted Drug Use							
		Alcohol Test Given Alcohol Test Ty TEST NOT GIVEN					Alcohol Test Results					
		Drug Test Given Drug Test Type TEST NOT GIVEN			Drug Test Results							
2	001	Drug Type										
		Individual Condition APPEARED NORMAL										
		Carrier										
		Use Vehicle O	wner San	ne as Carrier		Source DRIVER						
2	-	Name			Address							
0	01	MOLDEX INC USDOT# 2324273				1201 CENTRAL AVE UNIT 5N LAKE STATION, IN 46405 , US						
0	S	GVWR	Cargo Body Type			o Body Type						
UNIT	BUS	MORE THAN 26,000 LB	I-TRAIL									
5	×	US DOT # 2324273	Carrier Ty	pe TATE CARRIER			Permitted Load NOT APPLICABL			E		
	TRUCK	WI Permit		ted Vehicle On Escort Vehicle Beguired			scort Vehicle Present					
	Г	Measured Height	Measu	red Length	milleu	Measured Width			Measured Weight			
		perty Owner			Address							
PROP OWNER 01		/ERNMENT L AGE OF LA VALLE 8) 985-8383			101 W	MAIN ST LLE, WI 53941 ,US						
	Fixe	ed Objects Struck										

25-02131

WISCONSIN MOTOR VEHICLE CRASH REPORT

Striking Unit	Struck Object	Structure Number	Damage Tag Number
5 01	LUM LIGHT SUPPORT		NA