6TL0FV1GFS 25-02672

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	Document Number Override	5 S S						g Officer/Deputy W. VERTEIN			
ŝ	Crash Date 03/21/2025	Crash Time 07:10 AM		Date Ar 03/21/2		Time Arrived	Time Arrived				
G	Date Notified	Time Notified		Total Units Tota			al Injured Total Killed				
5	03/21/2025	07:18 AM		01	I	00	00	Dev entin a			
H ا	On Emergency	t and Run	Lane Closu		Work Zone		or Towed	Reporting Threshold			
6TL0FV1GF	Government Property	Active Sc	hool Zone	School NO	Bus Related	Tags					
-	Reportable	Crash Type DT4000 (STA	NDARD CRASH	I)		Ameno	ded	Secondary Crash			
	Description										
	Diagram						Reconstruction	on By			
	Not to sca	le									
				-	ф-						
					<u> </u>		Photos By				
	Main Street				Cable line						
					Cable line		Additional Information				
							-				
					1						
					- \$ -						
	✓ I, a sworn law enforcement	ent officer, agre	e that I have no	ot addec	d any CJIS data in t	nis report.					
	ON THE DESCRIBED DATE, TIME, LINE BREAKING THE LINE AND AL	AND LOCATION, SO BREAKING TH	UNIT 1 WAS TRAVE HE POWER POLE I	ELING EA	STBOUND. WHILE EAS TACHED TO. NO REPO	TBOUND, THE OV ORTED INJURIES.	/ERSIZED LOAI	D HIT AN OVERHEAD CABLE			

Wisconsin Motor Vehicle Crash Form DT4000 This report does not include any CJIS data. 1 of 4
 Crash Date
 03/21/2025

 Crash Time
 07:10 AM

6TL0FV1GFS

25-02672

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

L	Loc	ation										
Ī		STH78 NB	Latitude			Longitue	Longitude					
		FTE		43.37305	6514		-89.634337278					
				X Coordin	ate		Y Coordinate					
		THE VILLAGE OF MER	KRIMAC			286578.71875			4805614			
	in c					Structure Type						
l						NO STR	JCTURE					
		sh Scene										
I		Harmful Event			ful Event Lo							
		HER FIXED OBJECT			DER RIGH	Т						
		ner of Collision	HICLE IN TRANSPORT	Light Cond DAYLIG								
ł		d Surface Condition(s)		Roadway								
	DR											
ł	Envi	ronment Factor(s)										
	NO	NE		NONE								
ł	Wea	ther Condition(s)				1						
	CLE	EAR										
ţ	Anim	nal Type					o Trafficwa					
ļ	Cras	sh Classification - Location				WAY - O	N ROAD					
		BLIC PROPERTY					ISDICTION					
Ī	Triba	al Land			Access Co	Special Study						
ł	With	in Interchange Area	Junction Location		Intersection Type							
	-						AN INTERSECTION					
1					NUTAN	INTERSE	CTION					
l	Uni	t Summary			NUTAN	INTERSE	CTION					
		t Summary		Vehicle Ope				Unit Type				
	Unit IN T	Status RANSIT		Vehicle Ope				TRUCK				
-	Unit IN T Vehi	Status RANSIT icle Type							s Endorse	ments		
-	Unit IN T Vehi TRU	Status RANSIT icle Type JCK TRACTOR (SEMI	ATTACHED)	A CLASS	erating As C	lassification		TRUCK Operating A				
	Unit IN T Vehi TRU	Status RANSIT icle Type		A CLASS	erating As C	lassification	Total Trail	TRUCK Operating A	Total Haz	ments Mat Types		
-	Unit IN T Vehi TRL Tota 1	Status RANSIT icle Type JCK TRACTOR (SEMI	ATTACHED)	A CLASS Total # Citat 0	erating As C	lassification		TRUCK Operating A lers		Mat Types		
5	Unit IN T Vehi TRL Tota 1	Status TRANSIT icle Type JCK TRACTOR (SEMI I Occs rance?	ATTACHED) Train/Bus # Recorded	A CLASS	erating As C	lassification	Total Trail 2	TRUCK Operating A lers	Total Haz 0	Mat Types		
5	Unit IN T Vehi TRU Tota 1 Insu Most	Status TRANSIT icle Type JCK TRACTOR (SEMI I Occs rance? S t Harmful Event: Collision 1	ATTACHED) Train/Bus # Recorded Direction Of Travel EASTBOUND	A CLASS	erating As C tions Issued CrashTire Mark ction	lassification	Total Trail 2 Speed Lin	TRUCK Operating A lers nit Emergency	Total Haz 0 Total Lan 2 Motor Veh	Mat Types es icle Use		
;	Unit IN T Vehi TRU Tota 1 Insu YES Most OTH	Status TRANSIT icle Type JCK TRACTOR (SEMI I Occs rance? S t Harmful Event: Collision 1 HER FIXED OBJECT	ATTACHED) Train/Bus # Recorded Direction Of Travel EASTBOUND	A CLASS	tions Issued CrashTire Mark ction IAL FUNC	lassification	Total Trail 2 Speed Lin	TRUCK Operating A ers nit Emergency NOT APPI	Total Haz 0 Total Lan 2 Motor Veh LICABLE	Mat Types es icle Use		
	Unit IN T Vehi Tota 1 Insu YES Most OTH	Status TRANSIT icle Type JCK TRACTOR (SEMI I Occs rance? S t Harmful Event: Collision 1	ATTACHED) Train/Bus # Recorded Direction Of Travel EASTBOUND With	A CLASS	tions Issued CrashTire Mark ction IAL FUNC	lassification	Total Trail 2 Speed Lin	TRUCK Operating A lers nit Emergency	Total Haz 0 Total Lan 2 Motor Veh LICABLE	Mat Types es icle Use		
	Unit IN T Vehi Tota 1 Insu YES OTH Traff TWO Surfa	Status TRANSIT icle Type JCK TRACTOR (SEMI I Occs rance? S t Harmful Event: Collision 1 HER FIXED OBJECT fic Way D-WAY, NOT DIVIDED ace Type	ATTACHED) Train/Bus # Recorded Direction Of Travel EASTBOUND With	A CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL tture	lassification	Total Trail 2 Speed Lin	TRUCK Operating A ers nit Emergency NOT APPI Traffic Contr NO Road Grade	Total Haz 0 Total Lan 2 Motor Veh LICABLE	Mat Types es icle Use		
	Unit IN T Vehi Tota 1 Insu YES OTH Traff TWO Surfa	Status TRANSIT icle Type JCK TRACTOR (SEMI I Occs rance? S t Harmful Event: Collision 1 HER FIXED OBJECT fic Way D-WAY, NOT DIVIDED	ATTACHED) Train/Bus # Recorded Direction Of Travel EASTBOUND With	A CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL tture	lassification	Total Trail 2 Speed Lin	TRUCK Operating A ers nit Emergency NOT APPI Traffic Contr NO	Total Haz 0 Total Lan 2 Motor Veh LICABLE	Mat Types es icle Use		
-	Unit IN T Vehi TRU Tota 1 Insu YES OTH Traff TWO Surfa BLA Truc	Status TRANSIT icle Type JCK TRACTOR (SEMI I Occs rance? S t Harmful Event: Collision 1 HER FIXED OBJECT fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU ik Bus or HazMat	ATTACHED) Train/Bus # Recorded Direction Of Travel EASTBOUND With	A CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL tture	lassification	Total Trail 2 Speed Lin	TRUCK Operating A ers nit Emergency NOT APPI Traffic Contr NO Road Grade	Total Haz 0 Total Lan 2 Motor Veh LICABLE	Mat Types es icle Use		
	Unit IN T Vehi Tota 1 Insuu YES Moss OTH Traff TWO Surfa BLA Truc TRU	Status TRANSIT icle Type JCK TRACTOR (SEMI I Occs I Cocs Trance? S t Harmful Event: Collision 1 HER FIXED OBJECT fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU ik Bus or HazMat JCK OR TRUCK COMI Vehicle	ATTACHED) Train/Bus # Recorded Direction Of Travel EASTBOUND With S)	A CLASS	tions Issued CrashTire Mark IAL FUNC rol ROL iture T	lassification	Total Trail 2 Speed Lin 35	TRUCK Operating A ers nit Emergency NOT APPI Traffic Conti NO Road Grade DOWNHIL	Total Haz 0 Total Lan 2 Motor Veh ICABLE Tol Inopera	Mat Types es icle Use		
-	Unit IN T Vehi Tota 1 Insuu YES Moss OTH Traff TWO Surfa BLA Truc TRU	Status TRANSIT icle Type JCK TRACTOR (SEMI I Occs rance? S t Harmful Event: Collision 1 HER FIXED OBJECT fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU ik Bus or HazMat JCK OR TRUCK COMI Vehicle License Plate Number	ATTACHED) Train/Bus # Recorded Direction Of Travel EASTBOUND With S)	A CLASS	tions Issued CrashTire Mark IAL FUNC rol ROL iture T	lassification	Total Trail 2 Speed Lin 35	TRUCK Operating A Operating A Inters It Emergency NOT APPI Traffic Contr NO Road Grade DOWNHIL Country of Is	Total Haz 0 Total Lan 2 Motor Veh ICABLE Tol Inopera L Suance	Mat Types es icle Use		
	Unit IN T Vehi Tota 1 Insuu YES Moss OTH Traff TWO Surfa BLA Truc TRU	Status TRANSIT icle Type JCK TRACTOR (SEMI I Occs I Cocs Trance? S t Harmful Event: Collision 1 HER FIXED OBJECT fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU ik Bus or HazMat JCK OR TRUCK COMI Vehicle License Plate Number 77489Z	ATTACHED) Train/Bus # Recorded Direction Of Travel EASTBOUND With S BINATION > 10,000LBS G	A CLASS	tions Issued CrashTire Mark IAL FUNC rol ROL iture T	lassification	Total Trail 2 Speed Lin 35	TRUCK Operating A ers nit Emergency NOT APPI Traffic Cont NO Road Grade DOWNHIL	Total Haz 0 Total Lan 2 Motor Veh ICABLE Tol Inopera L Suance	Mat Types es icle Use		
	Unit IN T Vehi Tota 1 Insuu YES Moss OTH Traff TWO Surfa BLA Truc TRU	Status TRANSIT icle Type JCK TRACTOR (SEMI I Occs rance? S t Harmful Event: Collision 1 HER FIXED OBJECT fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU ik Bus or HazMat JCK OR TRUCK COMI Vehicle License Plate Number	ATTACHED) Train/Bus # Recorded Direction Of Travel EASTBOUND With S BINATION > 10,000LBS G	A CLASS	tions Issued CrashTire Mark IAL FUNC rol ROL iture T	lassification	Total Trail 2 Speed Lin 35	TRUCK Operating A Operating A Inters It Emergency NOT APPI Traffic Contr NO Road Grade DOWNHIL Country of Is	Total Haz 0 Total Lan 2 Motor Veh ICABLE Tol Inopera L Suance	Mat Types es icle Use		
	Unit IN T Vehi TRL Tota 1 Insuu YES OTH Traff TWO Surfa BLA Truc TRL	Status TRANSIT icle Type JCK TRACTOR (SEMI I Occs I Cocs I Harmful Event: Collision 1 HER FIXED OBJECT icle Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU ik Bus or HazMat JCK OR TRUCK COMI Vehicle License Plate Number 774892 Vehicle Identification Nur	ATTACHED) Train/Bus # Recorded Direction Of Travel EASTBOUND With S BINATION > 10,000LBS G	A CLASS	tions Issued CrashTire Mark IAL FUNC rol ROL tture T	lassification	Total Trail 2 Speed Lin 35 St WI Year	TRUCK Operating A Operating A Inters It Emergency NOT APPI Traffic Contr NO Road Grade DOWNHIL Country of Is UNITED S1 Model	Total Haz 0 Total Lan 2 Motor Veh ICABLE Tol Inopera L Suance	Mat Types es icle Use		
	Unit IN T Vehi TRL Tota 1 Insuu YES OTH Traff TWO Surfa BLA Truc TRL	Status TRANSIT icle Type JCK TRACTOR (SEMI I Occs I Cocs Trance? S t Harmful Event: Collision 1 HER FIXED OBJECT fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU ik Bus or HazMat JCK OR TRUCK COMI Vehicle License Plate Number 774892 Vehicle Identification Nur 1XPXP4EX4RD67673 Color GRY - GRAY	ATTACHED) Train/Bus # Recorded Direction Of Travel EASTBOUND With S BINATION > 10,000LBS G	A CLASS	tions Issued CrashTire Mark IAL FUNC rol ROL tture T	lassification	Total Trail 2 Speed Lin 35 St WI Year	TRUCK Operating A Operating A ers nit Emergency NOT APPI Traffic Contr NO Road Grade DOWNHIL Country of Is UNITED S1 Model 389	Total Haz 0 Total Lan 2 Motor Veh ICABLE Tol Inopera L Suance	Mat Types es icle Use		
	Unit IN T Vehi TRU Tota 1 Insuu YES Most OTH Traff TWO Surfa BLA Truc TRU	Status TRANSIT icle Type JCK TRACTOR (SEMI I Occs Trance? S t Harmful Event: Collision 1 HER FIXED OBJECT fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU ik Bus or HazMat JCK OR TRUCK COMI Vehicle License Plate Number 77489Z Vehicle Identification Nur 1XPXP4EX4RD67673 Color GRY - GRAY Initial Contact Point	ATTACHED) Train/Bus # Recorded Direction Of Travel EASTBOUND With S BINATION > 10,000LBS G mber 37	A CLASS	tions Issued CrashTire Mark IAL FUNC rol ROL tture T	lassification	Total Trail 2 Speed Lin 35 St WI Year	TRUCK Operating A Operating A ers nit Emergency NOT APPI Traffic Contr NO Road Grade DOWNHIL Country of Is UNITED S1 Model 389	Total Haz 0 Total Lan 2 Motor Veh ICABLE Tol Inopera L Suance	Mat Types es icle Use tive/Missing		
	Unit IN T Vehi TRU Tota 1 Insuu YES Most OTH Traff TWO Surfa BLA Truc TRU	Status TRANSIT icle Type JCK TRACTOR (SEMI I Occs rance? S t Harmful Event: Collision 1 HER FIXED OBJECT fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU ik Bus or HazMat JCK OR TRUCK COMI Vehicle License Plate Number 77489Z Vehicle Identification Nur 1XPXP4EX4RD67673 Color GRY - GRAY Initial Contact Point 00 - NON-COLLISION	ATTACHED) Train/Bus # Recorded Direction Of Travel EASTBOUND With S BINATION > 10,000LBS G mber 37	A CLASS Total # Citat 0 Pre Special Fun NO SPEC Traffic Contt NO CONT Road Curva STRAIGH VWR/GCWR Plate Type APO Make PTRB Body Style TC - TRA Vehicle Da	tions Issued CrashTire Mark IAL FUNC rol ROL iture T	lassification	Total Trail 2 Speed Lin 35 St WI Year	TRUCK Operating A Operating A ers nit Emergency NOT APPI Traffic Contr NO Road Grade DOWNHIL Country of Is UNITED S1 Model 389	Total Haz 0 Total Lan 2 Motor Veh ICABLE Tol Inopera L Suance	Mat Types es icle Use		
	Unit IN T Vehi TRU Tota 1 Insuu YES OTH Traff TWO Surfa BLA Truc TRU	Status TRANSIT icle Type JCK TRACTOR (SEMI I Occs Trance? S t Harmful Event: Collision 1 HER FIXED OBJECT fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU ik Bus or HazMat JCK OR TRUCK COMI Vehicle License Plate Number 77489Z Vehicle Identification Nur 1XPXP4EX4RD67673 Color GRY - GRAY Initial Contact Point	ATTACHED) Train/Bus # Recorded Direction Of Travel EASTBOUND With S BINATION > 10,000LBS G mber 37	A CLASS Total # Citat 0 Pre Special Fun NO SPEC Traffic Contt NO CONT Road Curva STRAIGH VWR/GCWR Plate Type APO Make PTRB Body Style TC - TRA Vehicle Da	tions Issued CrashTire Mark IAL FUNC rol ROL tture T	lassification	Total Trail 2 Speed Lin 35 St WI Year	TRUCK Operating A Operating A ers nit Emergency NOT APPI Traffic Contr NO Road Grade DOWNHIL Country of Is UNITED S1 Model 389	Total Haz 0 Total Lan 2 Motor Veh ICABLE Tol Inopera L Suance	Mat Types es icle Use tive/Missing		

Wisconsin Motor Vehicle Crash Form DT4000 This report does not include any CJIS data. 2 of 4 Crash Date 03/21/2025 Crash Time 07:10 AM

6TL0FV1GFS 25-02672

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

. 1		÷			Vehicle Removed By									
- 1							OPERATOR							
- 1		GOING STRAIGHT					Vehicle Factors							
- 1							NOT APPLICABLE							
- 1														
- 1		Driver Actions NO CONTRIBUTING												
ы.	Щ	NUCONTRIBUTING	ACTION											
INN	VEHICLE													
2	ē													
- 1	-													
- 1		Owner Name	DATION			Owner A								
2	5	FINEHURST CORPORATION (608) 459-5454					INEHURST ETON, WI 5							
- 1		Sequence Of Eve	nts			1								
- 1	6	Event OTHER FIXED OBJE	ст											
- 1	8		.01											
- 1	02	Event												
- 1	03	Event												
- 1	•													
- 1	04	Event												
ьI	l I	Policy Holder												
INN		Insurance Company				ORGANIZATION/COMPANY								
- 1		RURAL-MUTUAL-IN	S-CO-(AT	TN:-C	LAIMS-DEPT)	PINEHURST CORPORATION								
- 1		Trailer/Towed												
2		Trailer Plate # 833572	Plate Type STL	e	Make TRLK	State WI			Country of Issuance UNITED STATES					
- 1	2				ANIZATION/COMPA	MPANY			Address					
INN	TRAILER	SEMI TRAILER			EHURST CORPOR 3) 459-5454	RATION			2170 PINEHURST DR MIDDLETON, WI 53562 , US					
5	RA	Vehicle Identification Number 1TKJ061446M014843												
- 1	-	Trailer Plate #	Plate Type	e	Make	State			Country of Issuance					
2		833573	STL		TRLK	WI			UNITED STATES					
ᆔ	2								Address 2170 PINEHURST DR					
IN I	TRAILER/	SEMI TRAILER PINEHURST CORPO Vehicle Identification Number (608) 459-5454							MIDDLETON, WI 53562 , US					
- 1	TR/	1TKS005146M01484												
- 1	I	Individual												
- 1		DRIVER JASON DRALLMEIER (414) 651-4646				0 Date of Birth		Sex						
- 1	A							MALE Race						
L	INDIVIDUAL							WHITE						
IN IN	≥	Address 2011 PATRICIA LN WAUKESHA, WI 53188 , US				Driver License Number								
-	R													
- 1	-													
- 1	_	On Duty Crash				Safety Equipment								
	Saf	fety Equipment												
		Row Seat Position 01 - FRONT ROW 07 - LEFT Heimet Use					ER & LAP I	BELT						
							Helmet Compliance							

Wisconsin Motor Vehicle Crash Form DT4000 This report does not include any CJIS data. 3 of 4 Crash Date 03/21/2025 Crash Time 07:10 AM

6TL0FV1GFS 25-02672

WISCONSIN MOTOR VEHICLE CRASH REPORT

	Eye Protection			Tint (Tint Compliance								
2	001	Injury N			Airba								
	5 8 Injury NO APPARENT INJURY Ejected Ejection Path NOT EJECTED NOT EJECTED/NOT APP					Trapped/Extricate					ed		
						LE	r	NOT TRAPPED					
		Medical Transport			EMS	EMS Agency Identifier			EMS Run #				
		NOT TRANSPORTED	D										
	Hospital					ate of Death Time of Death							
	Distracted By Source NOT APPLICABLE (NOT DISTRACTED)												
		Distracted By Action NOT DISTRACTED Striking Unit #											
		Non Motorist	riking Uni	t # Locati	on								
		Prior Action											
		Action											
	_												
	IAI												
UNIT	INDIVIDUAL												
5	N												
	R												
	-												
		Action Other To/From School							To/From School				
	L	Drug & Alcohol NO				Suspected Drug Use							
		Alcohol Test Given Alcol			Icohol Test Type			A	Alcohol Test Re	esults			
		TEST NOT GIVEN											
		Drug Test Given TEST NOT GIVEN			Test Type		Drug Test Re		esults				
_	1	Drug Type											
2	001												
		Institutue I Constitue											
		Individual Condition											
		APPEARED NORMA	L										
	(Carrier											
		Use Vehicle Owner Same as Carrier				Source VEHICLE-SIDE							
6	~	Name				Address							
0	01	PINEHURST CORPORATION USDOT# 2640550				2170 PINEHURST DR			116				
						MIDDLETON, WI 53562 , US							
	46												
F	BUS	GVWR Vehicle Configuration MORE THAN 26,000 LB TRUCK TRACTOR				LER		LOWB					
UNIT		US DOT # 2640550		Carrier Type NTRASTATE (CARRIER	IER			Permitted Load OSOW				
	TRUCK	▼ OS/OW Load	Permit N	umber	Permitted Vehicle On Es			Escort Vehicle Required By Permit			scort Vehicle Present		
		Measured Height		Measured Len		Measured Width			Measured Weight				
		16 FT 0 IN			0	12 FT 6 IN							

Wisconsin Motor Vehicle Crash Form DT4000 This report does not include any CJIS data. 4 of 4 Crash Date 03/21/2025 Crash Time 07:10 AM