WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

C	د
٥	L
Ц	7
H	_
	V
9	
C	2
Ē	
6	0

Document Number Override				Agency Crash Number 20-00692		Investigating Officer/Deputy DEPUTY J. KIRKENG		
Crash Date		Crash Time		Date Arrived		Time Arrived		
01/18/2020		02:00 AM		01/18/2020		03:16 AM		
Date Notified		Time Notified		Total Units		Total Injured	Total Killed	
01/18/2020		03:11 AM		01		00	00	
On Emergency Hi		it and Run Lane Closu		ure Work Zone		Trailer or Towed Reporting Threshold		
Government Active School Zone			School Bus Related NO		Tags			
Crash Type DT4000 (STANDARD CRASH			I)		Amended		Secondary Crash	

Description



I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

UNIT 1 WAS TRAVELING N/B ON STH 23. UNIT 1 LOST CONTROL CAUSING IT TO EXIT THE ROADWAY ON THE EAST SIDE OF THE ROAD, GOING INTO THE DITCH BEFORE STRIKING TREES.

Location

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 01/18/2020

Crash Time 02:00 AM

	499 OF	STH23 EB FT N CTHS NB			-	Latitude 43.502510797 X Coordinate		Longitude -90.016223473	
		THE TOWN OF REEDSE SAUK COUNTY	BURG		<u>_</u>	256159.5		Y Coordinate 4821040.5	
				Structure Type NO STRUCTURE					
(Cra	sh Scene							
	First	Harmful Event				First Harmful Even	t Location		
	TRE			ROADSIDE					
		ner of Collision				Light Condition			
		NO COLLISION W/VEH	HICLE IN TRANSPORT			DARK/UNLIT			
		d Surface Condition(s)				Roadway Factor(s)			
	SNO	OW, ICE							
	Envi	ironment Factor(s)							
	WE	ATHER CONDITIONS				NONE			
	Wea	ather Condition(s)							
	SNO	wo							
	Anin	nal Type				Relation To Traffic	way		
						TRAFFICWAY -	ON ROAD		
		sh Classification - Location				Crash Classificatio			
		BLIC PROPERTY al Land				NO SPECIAL JU	JRISDICTION		
	THDa	ai Land				Access Control NO CONTROL		Special Study	
	With	in Interchange Area	Junction Location		Intersection Type				
	NO		NON-JUNCTION		NOT AN	INTERSECTION			
	Uni	t Summary							
		Status		Vehicle Ope	erating As Cla	assification	Unit Type		
	Unit IN T	Status FRANSIT		Vehicle Ope D CLASS	erating As Cla	assification	TRUCK		
11	Unit IN T Vehi	Status FRANSIT icle Type	TRUCK	· ·	erating As Cla	assification	TRUCK	As Endorsements	
10	Unit IN T Vehi UTI	Status FRANSIT icle Type LITY TRUCK/PICKUP T		D CLASS			TRUCK Operating		
0.1	Unit IN T Vehi UTI	Status FRANSIT icle Type	TRUCK Train/Bus # Recorded	D CLASS Total # Citat		Total T	TRUCK Operating	Total HazMat Types	
10	Unit IN T Vehi UTI Tota 1	Status TRANSIT icle Type LITY TRUCK/PICKUP T	Train/Bus # Recorded	Total # Citat 2	tions Issued	Total T	TRUCK Operating		
0.1	Unit IN T Vehi UTII Tota 1 Insu	Status FRANSIT icle Type LITY TRUCK/PICKUP T		Total # Citat 2 Pre 0		Total T	TRUCK Operating	Total HazMat Types 0	
10 UNI	Unit IN T Vehi UTII Tota 1 Insu	Status TRANSIT icle Type LITY TRUCK/PICKUP T al Occs rance?	Train/Bus # Recorded Direction Of Travel NORTHBOUND	Total # Citat 2 Pre (Special Fundament)	tions Issued CrashTire Mark ction	Total T 0 Speed 55	TRUCK Operating	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use	
UNII 01	Unit IN T Vehi UTII Tota 1 Insui UNI Most	Status FRANSIT icle Type LITY TRUCK/PICKUP T al Occs rance? KNOWN It Harmful Event: Collision W EE	Train/Bus # Recorded Direction Of Travel NORTHBOUND	Total # Citat 2 Pre (Special Fundament)	tions Issued CrashTire Mark	Total T 0 Speed 55	TRUCK Operating A railers Limit Emergency NOT APF	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use	
UNIT 01	Unit IN T Vehi UTII Tota 1 Insu UNI Most TRE	Status FRANSIT icle Type LITY TRUCK/PICKUP T al Occs rance? KNOWN It Harmful Event: Collision W EE fic Way	Train/Bus # Recorded Direction Of Travel NORTHBOUND	Total # Citat 2 Pre (Special Fundament No SPEC) Traffic Contri	CrashTire Mark ction IAL FUNC	Total T 0 Speed 55	TRUCK Operating A railers Limit Emergency NOT APF Traffic Con	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use	
UNIT	Unit IN T Vehi UTII Tota 1 Insu UNI Mosi TRE	Status TRANSIT icle Type LITY TRUCK/PICKUP T al Occs rance? KNOWN It Harmful Event: Collision W EE fic Way O-WAY, NOT DIVIDED	Train/Bus # Recorded Direction Of Travel NORTHBOUND	Total # Citat 2 Pre 0 Special Fun NO SPECI Traffic Contr	CrashTire Mark ction IAL FUNC	Total T 0 Speed 55	TRUCK Operating of the second	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use PLICABLE trol Inoperative/Missing	
	Unit IN T Vehi UTII Tota 1 Insu UNI Most TRE Traff TWO	Status TRANSIT icle Type LITY TRUCK/PICKUP T al Occs rance? KNOWN It Harmful Event: Collision W EE fic Way O-WAY, NOT DIVIDED ace Type	Train/Bus # Recorded Direction Of Travel NORTHBOUND	D CLASS Total # Citat 2 Pre 0 Special Fun NO SPECI Traffic Contr NO CONTI	CrashTire Mark ction IAL FUNC	Total T 0 Speed 55	TRUCK Operating of the second	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use PLICABLE trol Inoperative/Missing	
	Unit IN T Vehi UTII Tota 1 Insu UNI Most TRE	Status TRANSIT icle Type LITY TRUCK/PICKUP T al Occs rance? KNOWN It Harmful Event: Collision W EE fic Way O-WAY, NOT DIVIDED	Train/Bus # Recorded Direction Of Travel NORTHBOUND	Total # Citat 2 Pre 0 Special Fun NO SPECI Traffic Contr	CrashTire Mark ction IAL FUNC	Total T 0 Speed 55	TRUCK Operating of the second	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use PLICABLE trol Inoperative/Missing	
LO LINO	Unit IN T Vehi UTII Tota 1 Insu UNI Most TRE	Status TRANSIT icle Type LITY TRUCK/PICKUP T al Occs rance? KNOWN It Harmful Event: Collision W EE fic Way O-WAY, NOT DIVIDED ace Type NCRETE Ek Bus or HazMat	Train/Bus # Recorded Direction Of Travel NORTHBOUND	D CLASS Total # Citat 2 Pre 0 Special Fun NO SPECI Traffic Contr NO CONTI	CrashTire Mark ction IAL FUNC	Total T 0 Speed 55	TRUCK Operating of the second	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use PLICABLE trol Inoperative/Missing	
LO LINO	Unit IN T Vehi UTII Tota 1 Insu UNII Most TREE Traff TWO Surface COI Truce NO	Status TRANSIT icle Type LITY TRUCK/PICKUP T al Occs rance? KNOWN It Harmful Event: Collision W EE fic Way O-WAY, NOT DIVIDED ace Type NCRETE Ek Bus or HazMat	Train/Bus # Recorded Direction Of Travel NORTHBOUND	D CLASS Total # Citat 2 Pre 0 Special Fun NO SPECI Traffic Contr NO CONTI	CrashTire Mark ction IAL FUNC	Total T 0 Speed 55	TRUCK Operating A railers Limit Emergency NOT APF Traffic Con NO Road Grad DOWNHI	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use PLICABLE trol Inoperative/Missing e LL	
UNIT 01	Unit IN T Vehi UTII Tota 1 Insu UNII Most TREE Traff TWO Surface COI Truce NO	Status TRANSIT icle Type LITY TRUCK/PICKUP T all Occs rance? KNOWN It Harmful Event: Collision W EE fic Way O-WAY, NOT DIVIDED ace Type NCRETE ck Bus or HazMat Vehicle License Plate Number	Train/Bus # Recorded Direction Of Travel NORTHBOUND	D CLASS Total # Citat 2 Pre (Special Funino SPECI Traffic Contrino CONTI Road Curva CURVE RI	CrashTire Mark ction IAL FUNC rol ROL ture	Total T 0 Speed 55 TION	TRUCK Operating A railers Limit Emergency NOT APF Traffic Con NO Road Grad DOWNHI Country of I	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use PLICABLE trol Inoperative/Missing e LL	
UNI 01	Unit IN T Vehi UTII Tota 1 Insu UNII Most TREE Traff TWO Surface COI Truce NO	Status FRANSIT icle Type LITY TRUCK/PICKUP T al Occs rance? KNOWN It Harmful Event: Collision W EE fic Way O-WAY, NOT DIVIDED ace Type NCRETE Ek Bus or HazMat Vehicle License Plate Number EC61688	Train/Bus # Recorded Direction Of Travel NORTHBOUND //ith	Total # Citat 2 Pre (Special Fun NO SPECI Traffic Contr NO CONTI Road Curva CURVE RI Plate Type LTK - LIG	CrashTire Mark ction IAL FUNC rol ROL ture	Total T 0 Speed 55 TION St WI	TRUCK Operating A railers Limit Emergency NOT APF Traffic Con NO Road Grad DOWNHI Country of I: UNITED S	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use PLICABLE trol Inoperative/Missing e LL	
UNII 01	Unit IN T Vehi UTII Tota 1 Insu UNII Most TREE Traff TWO Surface COI Truce NO	Status TRANSIT icle Type LITY TRUCK/PICKUP T all Occs rance? KNOWN It Harmful Event: Collision W EE fic Way O-WAY, NOT DIVIDED ace Type NCRETE ck Bus or HazMat Vehicle License Plate Number	Train/Bus # Recorded Direction Of Travel NORTHBOUND Vith	D CLASS Total # Citat 2 Pre (Special Funino SPECI Traffic Contrino CONTI Road Curva CURVE RI	CrashTire Mark ction IAL FUNC rol ROL iture IGHT	Total T 0 Speed 55 TION	TRUCK Operating A railers Limit Emergency NOT APF Traffic Con NO Road Grad DOWNHI Country of I	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use PLICABLE trol Inoperative/Missing e LL ssuance TATES	
UNII 01	Unit IN T Vehi UTII Tota 1 Insu UNI Mos TRE Traff TWG Surface NO	Status TRANSIT icle Type LITY TRUCK/PICKUP T al Occs rance? KNOWN It Harmful Event: Collision W EE fic Way O-WAY, NOT DIVIDED ace Type NCRETE Ek Bus or HazMat Vehicle License Plate Number EC61688 Vehicle Identification Num	Train/Bus # Recorded Direction Of Travel NORTHBOUND Vith	D CLASS Total # Citat 2 Pre 0 Special Funch NO SPECI Traffic Contr NO CONTI Road Curva CURVE RI Plate Type LTK - LIG Make	CrashTire Mark ction IAL FUNC rol ROL sture IGHT	Total T 0 Speed 55 TION St WI Year	TRUCK Operating A railers Limit Emergency NOT APF Traffic Con NO Road Grad DOWNHI Country of I: UNITED S Model	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use PLICABLE trol Inoperative/Missing e LL ssuance TATES	
UNII 01	Unit IN T Vehi UTII Tota 1 Insu UNI Mos TRE Traff TWG Surface NO	Status TRANSIT icle Type LITY TRUCK/PICKUP T all Occs Trance? KNOWN It Harmful Event: Collision W EE fic Way O-WAY, NOT DIVIDED ace Type NCRETE Ek Bus or HazMat Vehicle License Plate Number EC61688 Vehicle Identification Num 1GCHK39UX5E251310 Color MAR - MAROON (BUF	Train/Bus # Recorded Direction Of Travel NORTHBOUND Vith	Total # Citat 2 Pre (Special Fundament NO SPECIAL Traffic Contract NO CONTIAL Road Curvar CURVE RI Plate Type LTK - LIG Make CHEVRO Body Style PK - PICK	CrashTire Mark ction IAL FUNC rol ROL sture IGHT CHT TRUC	Total T 0 Speed 55 TION St WI Year	TRUCK Operating A railers Limit Emergency NOT APF Traffic Con NO Road Grad DOWNHI Country of I: UNITED S Model SILVERAI	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use PLICABLE trol Inoperative/Missing e LL ssuance TATES	
01 UNI 01	Unit IN T Vehi UTII Tota 1 Insu UNI Mos: TRE Traff TWG COI Truc NO	Status TRANSIT icle Type LITY TRUCK/PICKUP T all Occs Trance? KNOWN It Harmful Event: Collision W EE fic Way O-WAY, NOT DIVIDED ace Type NCRETE Ek Bus or HazMat Vehicle License Plate Number EC61688 Vehicle Identification Num 1GCHK39UX5E25131 Color MAR - MAROON (BUF Initial Contact Point	Train/Bus # Recorded Direction Of Travel NORTHBOUND Vith	Total # Citat 2 Pre (Special Funch NO SPECI Traffic Contr NO CONTI Road Curva CURVE RI Plate Type LTK - LIG Make CHEVRO Body Style	CrashTire Mark ction IAL FUNC rol ROL sture IGHT CHT TRUC	Total T 0 Speed 55 TION St WI Year	TRUCK Operating A railers Limit Emergency NOT APF Traffic Con NO Road Grad DOWNHI Country of I: UNITED S Model SILVERAI	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use PLICABLE trol Inoperative/Missing e LL ssuance TATES	
01 UNI 01	Unit IN T Vehi UTII Tota 1 Insu UNI Mos: TRE Traff TWG COI Truc NO	Status TRANSIT icle Type LITY TRUCK/PICKUP T all Occs Trance? KNOWN It Harmful Event: Collision W EE fic Way O-WAY, NOT DIVIDED ace Type NCRETE bk Bus or HazMat Vehicle License Plate Number EC61688 Vehicle Identification Num 1GCHK39UX5E251316 Color MAR - MAROON (BUF Initial Contact Point 12 - FRONT	Train/Bus # Recorded Direction Of Travel NORTHBOUND Vith	Total # Citat 2 Pre (Special Funch NO SPECI Traffic Contr NO CONTI Road Curva CURVE RI Plate Type LTK - LIG Make CHEVRO Body Style PK - PICK Vehicle Date	CrashTire Mark ction IAL FUNC rol ROL sture IGHT CHT TRUC	Total T 0 Speed 55 TION St WI Year 2005	TRUCK Operating A railers Limit Emergency NOT APF Traffic Con NO Road Grad DOWNHI Country of I: UNITED S Model SILVERAI Bus Use	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use PLICABLE trol Inoperative/Missing e LL ssuance TATES	
UNII 01	Unit IN T Vehi UTII Tota 1 Insu UNI Mos: TRE TWO Surface COI	Status TRANSIT icle Type LITY TRUCK/PICKUP T all Occs Trance? KNOWN It Harmful Event: Collision W EE fic Way O-WAY, NOT DIVIDED ace Type NCRETE Ek Bus or HazMat Vehicle License Plate Number EC61688 Vehicle Identification Num 1GCHK39UX5E25131 Color MAR - MAROON (BUF Initial Contact Point	Train/Bus # Recorded Direction Of Travel NORTHBOUND Vith	D CLASS Total # Citat 2 Pre (Special Funk NO SPECI Traffic Contr NO CONTI Road Curva CURVE RI Plate Type LTK - LIG Make CHEVRO Body Style PK - PICK Vehicle Dat 01 - RIGH	CrashTire Mark ction IAL FUNC rol ROL sture IGHT CHT TRUC	Total T	TRUCK Operating A railers Limit Emergency NOT APF Traffic Con NO Road Grad DOWNHI Country of I: UNITED S Model SILVERAI Bus Use	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use PLICABLE trol Inoperative/Missing e LL ssuance TATES	

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Towed Due To Damage		Ve	hicle Removed By				
		TOWED BUT NOT DUE TO	DISABLING	DAMAG ST	EVES AUTO SERVICE				
		What Driver Was Doing		Ve	Vehicle Factors				
		GOING STRAIGHT							
		Driver Prior Action Other		NO	OT APPLICABLE				
		Driver Actions							
	Е	Driver Actions SPEED TOO FAST/COND.	FAILURE TO	O CONTROL. R	AN OFF ROADWAY, FAILED TO KEI	EP IN DESIGNATED LANE			
_	ĭ	,		 	,				
LNO	VEHICL								
ا ر	ΛE								
		Owner Name			Owner Address				
2	01	WERLA CONSTRUCTION (608) 415-3963	LLC		E5442 FRIENDSHIP DR LOGANVILLE, WI 53943 , US				
)	(444)			200/111122, 111 000 10 , 00				
		Sequence Of Events							
		Event							
	01	RUN OFF ROADWAY RIGH	HT .						
	02	Event DITCH							
	03	Event TREE							
	04	Event							
	0								
		ndividual							
		Driver KYLE C WERLA			Citations Issued	Sex			
	٦ <u>ـ</u>	(608) 415-3963		_	2	MALE			
_	INDIVIDUAL	(111)			Date of Birth	Race WHITE			
	<u> </u>	Address			Driver License Number				
	N	E5442 FRIENDSHIP DR LOGANVILLE, WI 53943,	us		STATE: WISCONSIN COUNTRY: UNITED STATES				
		,							
	ļ	On Duty (Crash		Safety Equipment				
	Sat	ety Equipment							
		Row Seat Position			SHOULDER & LAP BELT				
		01 - FRONT ROW	07 - LEFT						
		Helmet Use			Helmet Compliance				
		Eye Protection			Tint Compliance				
_	Ξ.	Injury Sev	verity		Airbag				
6	90		PARENT INJ	URY	NON DEPLOYED				
		•	Ejection Path	ED/NOT ADDI I	04015	Trapped/Extricated			
		NOT EJECTED Medical Transport	NOT EJECT	ED/NOT APPLIC	EMS Agency Identifier	NOT TRAPPED EMS Run #			
		NOT TRANSPORTED		'	EMS Agency Identifier	EIVIS KUII #			
		Hospital			Date of Death	Time of Death			
		Distracted By Distracted UNKNO	d By Source WN						
		Distracted By Action UNKNOWN							
		Non Motorical Striking U	Jnit # L	ocation					
		Non Motorist							

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Prior Action								
		Action								
_	UAL									
UNIT	INDIVIDUAL									
	Ĭ									
		Action Other							To/From School	
	ı	Drug & Alcoh	Suspected Ald YES	cohol Use		Suspected Drug Use YES			•	
		Alcohol Test Give	n L	Alcohol Test Ty	уре			Alcohol Test Results		
		TEST GIVEN		BLOOD	BLOOD			PENDING		
		Drug Test Given TEST GIVEN		Drug Test Type BLOOD	Drug Test Type BLOOD		Drug Test Results PENDING			
10	00	Drug Type		·						
•		Individual Condition	on							
		UNDER THE IN	FLUENCE OF N	MEDICATIONS/DRU	IGS	S/ ALCOHOL				
	,	Violations								
	5	UTC Number AD978388	Issue To? 001	Statute Number 346.63(1)(a)		Description OPERATING WHILE	UNDER THE IN	IFLUENCE		
	05	UTC Number AD978389	Issue To? 001	Statute Number 346.57(3)		Description DRIVING TOO FAST FOR CONDITIONS				
	Pro	perty Owne	r							
10	Gove	ernment JK COUNTY HW	V DEBT		1	Address 620 STH 136				
		3) 356-3855	IDEFI			PO BOX 26				
PROP OWNER	•				BARABOO, WI 53913 , US					
	Fixe	ed Objects St	ruck							
	5	Striking Unit 01	Struck Object DITCH					Structure Number	Damage Tag Number 0000	
	05	Striking Unit 01	Struck Object TREE					Structure Number	Damage Tag Number 0000	